



Kelly Young
Dirigo Software
PO Box 53
Readfield, ME 04355

ds@dirigosoftware.com
www.dirigosoftware.com

TSB Report for: 2000 BMW X5

Mfg Bulletin #: **005099** Repl Bulletin #: Bulletin Date: **19991201**
Component: **98000 UNKNOWN OR OTHER**

THIS BULLETIN CONTAINS NEW VEHICLES PREPARATION AND MAINTENANCE REQUIREMENTS FOR BMW ALL-NEW SPORT ACTIVITY VEHICLE (SAV) AVAILABLE IN DECEMBER. *TT

TSB Report for: 2000 BMW X5

Mfg Bulletin #: **360599** Repl Bulletin #: Bulletin Date: **19991201**
Component: **19000 TIRES**

INFORMATION REGARDING THE BMW AFTERSALES PARTS OF THE WINTER TIRES. *MJS

TSB Report for: 2000 BMW X5

Mfg Bulletin #: **005099** Repl Bulletin #: **005099** Bulletin Date: **20000201**
Component: **98000 UNKNOWN OR OTHER**

SUBJECT PERTAINING NEW VEHICLE PREPARATION AND MAINTENANCE REQUIREMENTS. *TT

TSB Report for: 2000 BMW X5

Mfg Bulletin #: **515100** Repl Bulletin #: Bulletin Date: **20000801**
Component: **133000 VISIBILITY:POWER WINDOW DEVICES AND CONTROLS**

THIS BULLETIN ADDRESSES CUSTOMER COMPLAINTS OF CREAKING, SQUEAKING, CLICKING NOISES FROM WINDOW REGULATOR ON VEHICLES PRODUCED PRIOR TO 5/2000. *TT

TSB Report for: 2000 BMW X5

Mfg Bulletin #: **325000** Repl Bulletin #: Bulletin Date: **20000601**
Component: **011000 STEERING:WHEEL AND HANDLE BAR**

SOME VEHICLES MAY HAVE BEEN INADVERTENTLY ASSEMBLED WITH A MANUALLY ADJUSTABLE STEERING COLUMN IN PLACE OF THE ELECTRICALLY ADJUSTABLE STEERING COLUMN THAT IS STANDARD IN ALL US MODELS. *TT

TSB Report for: 2000 BMW X5

Mfg Bulletin #: **840601** Repl Bulletin #: Bulletin Date: **20010701**
Component: **350000 EQUIPMENT**

SERVICE INFORMATION REGARDING VEHICLES WITH CPT 8000 PHONE; VEHICLE BATTERY DISCHARGED. *TT



Kelly Young
Dirigo Software
PO Box 53
Readfield, ME 04355

ds@dirigosoftware.com
www.dirigosoftware.com

TSB Report for: 2000 BMW X5

Mfg Bulletin #: **355001** Repl Bulletin #: Bulletin Date: **20011101**
Component: **031000 SERVICE BRAKES, HYDRAULIC:PEDALS AND LINKAGES**

SOME CUSTOMERS MAY COMPLAIN OF A RATTLE WHEN THEY RELEASE THE BRAKE PEDAL SO THAT IT POPS BACK TO THE REST POSITION. *TT

TSB Report for: 2000 BMW X5

Mfg Bulletin #: **240500** Repl Bulletin #: **240500** Bulletin Date: **20011201**
Component: **103000 POWER TRAIN:AUTOMATIC TRANSMISSION**

CUSTOMERS MAY COMPLAIN ABOUT ERRATIC/HARSH SHIFTING AND THE TRANSMISSION LIGHT IS ILLUMINATED AND NO START/NO CRANK CONDITION. *TT

TSB Report for: 2000 BMW X5

Mfg Bulletin #: **240200** Repl Bulletin #: **240200** Bulletin Date: **20011201**
Component: **103100 POWER TRAIN:AUTOMATIC TRANSMISSION:CONTROL MODULE (TCM, PCM)**

CUSTOMERS MAY COMPLAIN OF HARD OR NO SHIFT AND GEAR ERROR FAULT CODES 50, 52, 53, OR 55 IN THE TRANSMISSION CONTROL MODULE. *TT

TSB Report for: 2000 BMW X5

Mfg Bulletin #: **SI545002** Repl Bulletin #: Bulletin Date: **20020201**
Component: **134000 VISIBILITY:SUN ROOF ASSEMBLY**

CONSUMERS MAY COMPLAIN OF A WIND NOISE EVEN THOUGH THE SUNROOF PANEL IS PROPERLY ADJUSTED.. *JG.

TSB Report for: 2000 BMW X5

Mfg Bulletin #: **120903** Repl Bulletin #: Bulletin Date: **20031001**
Component: **061000 ENGINE AND ENGINE COOLING:ENGINE**

A POTENTIAL PROBLEM THAT COULD AFFECT THE DURABILITY OF AIR MASS METER OF CERTAIN BMWs EQUIPPED WITH THE 4.4L ENGINE. VEHICLES AFFECTED WILL HAVE AN ILLUMINATED CHECK ENGINE LIGHT AND AN AIR MASS METER SIGNAL PLAUSIBILITY FAULT FC 73 STORE



Kelly Young
Dirigo Software
PO Box 53
Readfield, ME 04355

ds@dirigosoftware.com
www.dirigosoftware.com

TSB Report for: 2000 BMW X5

Mfg Bulletin #: **000403** Repl Bulletin #: **000403** Bulletin Date: **20040201**
Component: **355100 EQUIPMENT:OTHER:LABELS**

VERMONT STATE MERCURY CONTENT LABEL LAW. 2000 6 SERIES, X3 AND Z4 MODELS ALSO INCLUDED. *TT

TSB Report for: 2000 BMW X5

Mfg Bulletin #: **510307** Repl Bulletin #: Bulletin Date: **20070201**
Component: **176100 LATCHES/LOCKS/LINKAGES:HOOD:LATCH**

INSTALL HOOD LATCH CORROSION RESISTANT CLIP. *KB

TSB Report for: 2000 BMW X5

Mfg Bulletin #: **SI B61 11 07** Repl Bulletin #: Bulletin Date: **20071101**
Component: **110000 ELECTRICAL SYSTEM**

MISSING CLIP ON POWER CABLE CAUSES VARIOUS ELECTRICAL COMPLAINTS. *NJ

TSB Report for: 2000 BMW X5

Mfg Bulletin #: **SI B 340307** Repl Bulletin #: **SI B34-03-07** Bulletin Date: **20080601**
Component: **114000 ELECTRICAL SYSTEM:WIRING**

DSC WARNING LAMP ILLUMINATED. E70 (X5) VEHICLES PRODUCED UP TO JANUARY 28, 2007. *PE
UPDATED 9/10/08. *PE

TSB Report for: 2000 BMW X5

Mfg Bulletin #: **SI B34 01 08** Repl Bulletin #: Bulletin Date: **20080401**
Component: **053000 PARKING BRAKE:INDICATOR LIGHT**

THE PARKING BRAKE WARNING IS ILLUMINATED AND FAULT CODE 6032 IS STORED. FOR MODEL E70 (X5). *PE

TSB Report for: 2000 BMW X5

Mfg Bulletin #: **SI B37-03-07** Repl Bulletin #: Bulletin Date: **20080101**
Component: **020000 SUSPENSION**

BMW: DYNAMIC DRIVE (ARS) FRONT SWAY BAR REPAIRS. E70 (X5) WITH SPORT PACKAGE OPTION CODE ZSP. *PE



Kelly Young
Dirigo Software
PO Box 53
Readfield, ME 04355

ds@dirigosoftware.com
www.dirigosoftware.com

TSB Report for: 2000 BMW X5

Mfg Bulletin #: **SI B63-04-08** Repl Bulletin #:
Component: **121000 EXTERIOR LIGHTING:HEADLIGHTS** Bulletin Date: **20080601**

BMW: HEADLAMP MOISTURE: FAULT DIAGNOSTICS. WATER OR CONDENSATION IN ONE OR BOTH HEADLAMPS. MODELS 5 SERIES, 6 SERIES, 7 SERIES, X5, X6, 1 SERIES, AND 3 SERIES. MODEL YEARS 2000-20008. *PE

TSB Report for: 2000 BMW X5

Mfg Bulletin #: **SI-B51-30-08** Repl Bulletin #:
Component: **160000 STRUCTURE** Bulletin Date: **20081101**

BMW: WATER LEAK IN THE FRONT RIGHT FOOTWELL AREA CAUSING THE CARPET TO BECOME WET. *PE

TSB Report for: 2000 BMW X5

Mfg Bulletin #: **SI-B51-30-08** Repl Bulletin #:
Component: **161000 STRUCTURE:FRAME AND MEMBERS** Bulletin Date: **20081101**

BMW: WATER LEAK IN THE FRONT RIGHT FOOTWELL AREA CAUSING THE CARPET TO BECOME WET. *PE

TSB Report for: 2000 BMW X5

Mfg Bulletin #: **SI-B51-30-08** Repl Bulletin #:
Component: **162000 STRUCTURE:BODY** Bulletin Date: **20081101**

BMW: WATER LEAK IN THE FRONT RIGHT FOOTWELL AREA CAUSING THE CARPET TO BECOME WET. *PE

TSB Report for: 2000 BMW X5

Mfg Bulletin #: **SI-B51-30-08** Repl Bulletin #:
Component: **162800 STRUCTURE:BODY:HOOD** Bulletin Date: **20081101**

BMW: WATER LEAK IN THE FRONT RIGHT FOOTWELL AREA CAUSING THE CARPET TO BECOME WET. *PE



Kelly Young
Dirigo Software
PO Box 53
Readfield, ME 04355

ds@dirigosoftware.com
www.dirigosoftware.com

TSB Report for: 2000 BMW X5

Mfg Bulletin #: **SI-B-11-01-0** Repl Bulletin #: Bulletin Date: **20090301**
Component: **061000 ENGINE AND ENGINE COOLING:ENGINE**

BMW: SMALL NUMBER OF VEHICLES EXPERIENCE PROBLEMS RANGING FROM LEAKING OIL FILLER CAPS, LEAKING OR BROKEN VALVE COVERS, TO COMPLETE ENGINE FAILURE IN EXTREMELY COLD CLIMATE CONDITIONS. MOISTURE ACCUMULATING IN ENGINE CRANKCASE VENTILATION V

TSB Report for: 2000 BMW X5

Mfg Bulletin #: **SI-B-11-01-0** Repl Bulletin #: Bulletin Date: **20090301**
Component: **061200 ENGINE AND ENGINE COOLING:ENGINE:DIESEL**

BMW: SMALL NUMBER OF VEHICLES EXPERIENCE PROBLEMS RANGING FROM LEAKING OIL FILLER CAPS, LEAKING OR BROKEN VALVE COVERS, TO COMPLETE ENGINE FAILURE IN EXTREMELY COLD CLIMATE CONDITIONS. MOISTURE ACCUMULATING IN ENGINE CRANKCASE VENTILATION V

TSB Report for: 2000 BMW X5

Mfg Bulletin #: **SI-B-11-01-0** Repl Bulletin #: Bulletin Date: **20090301**
Component: **063110 ENGINE AND ENGINE COOLING:EXHAUST SYSTEM:EMISSION CONTROL:CRANKCASE (PCV)**

BMW: SMALL NUMBER OF VEHICLES EXPERIENCE PROBLEMS RANGING FROM LEAKING OIL FILLER CAPS, LEAKING OR BROKEN VALVE COVERS, TO COMPLETE ENGINE FAILURE IN EXTREMELY COLD CLIMATE CONDITIONS. MOISTURE ACCUMULATING IN ENGINE CRANKCASE VENTILATION V

TSB Report for: 2000 BMW X5

Mfg Bulletin #: **SI-B130209** Repl Bulletin #: Bulletin Date: **20090301**
Component: **080000 FUEL SYSTEM, DIESEL**

BMW: DIESEL: DIAGNOSIS FOR LOW PRESSURE FUEL SUPPLY FAULTS. SERVICE ENGINE SOON LAMP IS ILLUMINATED (A FUEL PUMP MALFUNCTION MESSAGE IS DISPLAYED IN THE CC) AND A COMBINATION OF THE FOLLOWING FAULT CODES MAY BE STORED IN THE DDE CONTROL MOD

TSB Report for: 2000 BMW X5

Mfg Bulletin #: **SIB-65-75-06** Repl Bulletin #: **SIB-65-75-06** Bulletin Date: **20110801**
Component: **140000 AIR BAGS**

BMW SERVICE CAMPAIGN: SEE DOCUMENT SEARCH BUTTON FOR OWNER LETTER. THE AIRBAG WARNING LAMP (AWL) IS ILLUMINATED, TOGETHER WITH THE PASSENGER AIRBAG STATUS LAMP (POL). THE PROBLEM MAY BE INTERMITTENT. MICROCRACKS IN THE OC3 SEAT MAT. *PE

TSB Report for: 2000 BMW X5

Mfg Bulletin #: **SI-B31-01-08** Repl Bulletin #:
Bulletin Date: **20090901**
Component: **105200 POWER TRAIN:DRIVELINE:CONSTANT VELOCITY JOINT**

BMW: REPLACEMENT OF FRONT OUTER CV JOINT. COMPLAINTS OF CLICKING OR GRINDING NOISES COMING FROM THE FRONT AXLE AREA WHEN MAKING A TURN. THE FRONT OUTER CONSTANT VELOCITY JOINT BOOT IS SPLIT OPEN AND THE JOINT IS ALREADY DAMAGED.

TSB Report for: 2000 BMW X5

Mfg Bulletin #: **SIB-61-15-09** Repl Bulletin #:
Bulletin Date: **20100401**
Component: **110000 ELECTRICAL SYSTEM**

BMW VEHICLES: VARIOUS ELECTRICAL PROBLEMS ARE POSSIBLE ON THE VEHICLE: WARNING LAMPS ILLUMINATED IN THE INSTRUMENT CLUSTER; CHECK CONTROL MESSAGES; SYSTEMS INOPERATIVE; FUSE BLOWN; WIPERS IN DEFAULT MODE (PERMANENTLY ON); AND FAULT CODES F

TSB Report for: 2000 BMW X5

Mfg Bulletin #: **SIB-61-15-09** Repl Bulletin #:
Bulletin Date: **20100401**
Component: **117000 DIGITAL INSTRUMENT PANEL**

BMW VEHICLES: VARIOUS ELECTRICAL PROBLEMS ARE POSSIBLE ON THE VEHICLE: WARNING LAMPS ILLUMINATED IN THE INSTRUMENT CLUSTER; CHECK CONTROL MESSAGES; SYSTEMS INOPERATIVE; FUSE BLOWN; WIPERS IN DEFAULT MODE (PERMANENTLY ON); AND FAULT CODES F

TSB Report for: 2000 BMW X5

Mfg Bulletin #: **SIB-34-03-07** Repl Bulletin #:
Bulletin Date: **20091001**
Component: **110000 ELECTRICAL SYSTEM**

BMW VEHICLES: DSC WARNING LAMP ILLUMINATED. THE DSC (DYNAMIC STABILITY CONTROL) WARNING LAMP IS ILLUMINATED AND SOME OR ALL OF THE FOLLOWING FAULT CODES ARE STORED: 6E58; 6E04; 53BA; D36F; 55C3; 6ECA; AND THE WIPERS MAY ALSO BE OPERATING

TSB Report for: 2000 BMW X5

Mfg Bulletin #: **SIB-34-03-07** Repl Bulletin #:
Bulletin Date: **20091001**
Component: **114000 ELECTRICAL SYSTEM:WIRING**

BMW VEHICLES: DSC WARNING LAMP ILLUMINATED. THE DSC (DYNAMIC STABILITY CONTROL) WARNING LAMP IS ILLUMINATED AND SOME OR ALL OF THE FOLLOWING FAULT CODES ARE STORED: 6E58; 6E04; 53BA; D36F; 55C3; 6ECA; AND THE WIPERS MAY ALSO BE OPERATING



Kelly Young
Dirigo Software
PO Box 53
Readfield, ME 04355

ds@dirigosoftware.com
www.dirigosoftware.com

TSB Report for: 2000 BMW X5

Mfg Bulletin #: **SIB-34-03-07** Repl Bulletin #:
Bulletin Date: **20091001**
Component: **136000 VISIBILITY:WINDSHIELD WIPER/WASHER**

BMW VEHICLES: DSC WARNING LAMP ILLUMINATED. THE DSC (DYNAMIC STABILITY CONTROL) WARNING LAMP IS ILLUMINATED AND SOME OR ALL OF THE FOLLOWING FAULT CODES ARE STORED: 6E58; 6E04; 53BA; D36F; 55C3; 6ECA; AND THE WIPERS MAY ALSO BE OPERATING

TSB Report for: 2000 BMW X5

Mfg Bulletin #: **SIB-34-03-07** Repl Bulletin #:
Bulletin Date: **20091001**
Component: **025000 ELECTRONIC STABILITY CONTROL**

BMW VEHICLES: DSC WARNING LAMP ILLUMINATED. THE DSC (DYNAMIC STABILITY CONTROL) WARNING LAMP IS ILLUMINATED AND SOME OR ALL OF THE FOLLOWING FAULT CODES ARE STORED: 6E58; 6E04; 53BA; D36F; 55C3; 6ECA; AND THE WIPERS MAY ALSO BE OPERATING

TSB Report for: 2000 BMW X5

Mfg Bulletin #: **SIB-13-02-09** Repl Bulletin #:
Bulletin Date: **20091001**
Component: **061200 ENGINE AND ENGINE COOLING:ENGINE:DIESEL**

BMW VEHICLES: DIAGNOSIS FOR LOW PRESSURE FUEL SUPPLY FAULTS. THE SERVICE ENGINE SOON LAMP IS ILLUMINATED (A FUEL PUMP MALFUCTION MESSAGE IS DISPLAYED IN THE CC), AND A COMBINATION OF THE FOLLOWING FAULT CODES MAY BE STORED IN THE DDE CONT

TSB Report for: 2000 BMW X5

Mfg Bulletin #: **SIB-12-09-08** Repl Bulletin #:
Bulletin Date: **20080201**
Component: **062200 ENGINE AND ENGINE COOLING:COOLING SYSTEM:FAN**

BMW VEHICLE: DRIVEABILITY COMPLAINTS DUE TO COOLING FAN RELAY FAILURE. THE CUSTOMER MAY COMPLAIN OF INTERMITTENT DRIVEABILITY PROBLEMS, DESCRIBED AS-ENGINE IS LACKING POWER WHEN ACCELERATING UPHILL; TRANSMISSION WILL NOT UPSHIFT UNDER HEA

TSB Report for: 2000 BMW X5

Mfg Bulletin #: **SIB-12-09-08** Repl Bulletin #:
Bulletin Date: **20080201**
Component: **110000 ELECTRICAL SYSTEM**

BMW VEHICLE: DRIVEABILITY COMPLAINTS DUE TO COOLING FAN RELAY FAILURE. THE CUSTOMER MAY COMPLAIN OF INTERMITTENT DRIVEABILITY PROBLEMS, DESCRIBED AS-ENGINE IS LACKING POWER WHEN ACCELERATING UPHILL; TRANSMISSION WILL NOT UPSHIFT UNDER HEA



Kelly Young
Dirigo Software
PO Box 53
Readfield, ME 04355

ds@dirigosoftware.com
www.dirigosoftware.com

TSB Report for: 2000 BMW X5

Mfg Bulletin #: **SIB-12-23-07** Repl Bulletin #:
Bulletin Date: **20071101**
Component: **061000 ENGINE AND ENGINE COOLING:ENGINE**

BMW VEHICLE: FC 2EF4 CHARACTERISTIC MAP THERMOSTAT. COMPLAINTS THAT THE SERVICE ENGINE SOON LAMP IS ILLUMINATED. FAULT CODE 2EF4 CHARACTERISTIC MAP THERMOSTAT IS STORED IN DME FAULT MEMORY. DME SOFTWARE CALIBRATION RELATED TO HIGH HEATIN

TSB Report for: 2000 BMW X5

Mfg Bulletin #: **SIB-12-23-07** Repl Bulletin #:
Bulletin Date: **20071101**
Component: **353000 EQUIPMENT:ELECTRICAL**

BMW VEHICLE: FC 2EF4 CHARACTERISTIC MAP THERMOSTAT. COMPLAINTS THAT THE SERVICE ENGINE SOON LAMP IS ILLUMINATED. FAULT CODE 2EF4 CHARACTERISTIC MAP THERMOSTAT IS STORED IN DME FAULT MEMORY. DME SOFTWARE CALIBRATION RELATED TO HIGH HEATIN

TSB Report for: 2000 BMW X5

Mfg Bulletin #: **SIB-12-23-07** Repl Bulletin #:
Bulletin Date: **20071101**
Component: **118000 ELECTRICAL SYSTEM: SOFTWARE**

BMW VEHICLE: FC 2EF4 CHARACTERISTIC MAP THERMOSTAT. COMPLAINTS THAT THE SERVICE ENGINE SOON LAMP IS ILLUMINATED. FAULT CODE 2EF4 CHARACTERISTIC MAP THERMOSTAT IS STORED IN DME FAULT MEMORY. DME SOFTWARE CALIBRATION RELATED TO HIGH HEATIN

TSB Report for: 2000 BMW X5

Mfg Bulletin #: **SIB-61-11-07** Repl Bulletin #:
Bulletin Date: **20071101**
Component: **110000 ELECTRICAL SYSTEM**

BMW VEHICLE: MISSING CLIP ON POWER CABLE CAUSES VARIOUS ELECTRICAL COMPLAINTS. VEHICLE WILL NOT START. INSTRUMENT CLUSTER OR DISPLAYS ARE FLICKERING. REMOTE CONTROL WILL NOT UNLOCK VEHICLE. VARIOUS CONTROL MODULES CANNOT BE ACCESSED USIN

TSB Report for: 2000 BMW X5

Mfg Bulletin #: **SIB-61-13-07** Repl Bulletin #:
Bulletin Date: **20071101**
Component: **110000 ELECTRICAL SYSTEM**

BMW VEHICLE: ELECTRONIC MALFUNCTION CC MESSAGE CAUSED BY SHORTED WIRING. THE ELECTRONIC MALFUNCTION CHECK CONTROL MESSAGE MAY BE DISPLAYED; THE SOUNDS SYSTEM EMITS A STATIC NOISE FROM THE SPEAKERS; THE RFK (REAR VIEW CAMERA) DOES NOT PAN;



Kelly Young
Dirigo Software
PO Box 53
Readfield, ME 04355

ds@dirigosoftware.com
www.dirigosoftware.com

TSB Report for: 2000 BMW X5

Mfg Bulletin #: **SIB-61-13-07** Repl Bulletin #:
Bulletin Date: **20071101**
Component: **114000 ELECTRICAL SYSTEM:WIRING**

BMW VEHICLE: ELECTRONIC MALFUNCTION CC MESSAGE CAUSED BY SHORTED WIRING. THE ELECTRONIC MALFUNCTION CHECK CONTROL MESSAGE MAY BE DISPLAYED; THE SOUNDS SYSTEM EMITS A STATIC NOISE FROM THE SPEAKERS; THE RFK (REAR VIEW CAMERA) DOES NOT PAN;

TSB Report for: 2000 BMW X5

Mfg Bulletin #: **SIB-61-13-07** Repl Bulletin #:
Bulletin Date: **20071101**
Component: **353000 EQUIPMENT:ELECTRICAL**

BMW VEHICLE: ELECTRONIC MALFUNCTION CC MESSAGE CAUSED BY SHORTED WIRING. THE ELECTRONIC MALFUNCTION CHECK CONTROL MESSAGE MAY BE DISPLAYED; THE SOUNDS SYSTEM EMITS A STATIC NOISE FROM THE SPEAKERS; THE RFK (REAR VIEW CAMERA) DOES NOT PAN;

TSB Report for: 2000 BMW X5

Mfg Bulletin #: **SIB-61-13-07** Repl Bulletin #:
Bulletin Date: **20071101**
Component: **118000 ELECTRICAL SYSTEM: SOFTWARE**

BMW VEHICLE: ELECTRONIC MALFUNCTION CC MESSAGE CAUSED BY SHORTED WIRING. THE ELECTRONIC MALFUNCTION CHECK CONTROL MESSAGE MAY BE DISPLAYED; THE SOUNDS SYSTEM EMITS A STATIC NOISE FROM THE SPEAKERS; THE RFK (REAR VIEW CAMERA) DOES NOT PAN;

TSB Report for: 2000 BMW X5

Mfg Bulletin #: **SIB-36-05-07** Repl Bulletin #:
Bulletin Date: **20071201**
Component: **199000 TIRES:PRESSURE MONITORING AND REGULATING SYSTEMS**

BMW: TIRE WARNING LIGHT ILLUMINATED DUE TO LOW AMBIENT TEMPERATURE. MODEL E90, E91 (3 SERIES); E92, E92 (3 SERIES); E60 (5 SERIES); E60 (M5); E63, E64 (6 SERIES); E63, E64 (M6); E65, E66 (7 SERIES); E70 (X5); E83 (X3); AND E85, E86 (Z4).

TSB Report for: 2000 BMW X5

Mfg Bulletin #: **SIB-16-02-09** Repl Bulletin #:
Bulletin Date: **20091201**
Component: **072100 FUEL SYSTEM, GASOLINE:DELIVERY:FUEL PUMP**

BMW VEHICLES: FUEL LEVEL SENSOR REPAIRS. WHERE IT IS NECESSARY TO REPLACE THE RIGHT OR THE LEFT SIDE FUEL LEVEL SENSOR DUE TO A FAILURE, THE ENTIRE PUMP AND



Kelly Young
Dirigo Software
PO Box 53
Readfield, ME 04355

ds@dirigosoftware.com
www.dirigosoftware.com

HOUSING OR DELIVERY UNIT (SUCTION JET ASSEMBLY) DO NOT NEED TO BE REPLACED AS WEL

TSB Report for: 2000 BMW X5

Mfg Bulletin #: **SI-B61-15-09** Repl Bulletin #:
Bulletin Date: **20100401**
Component: **110000 ELECTRICAL SYSTEM**

BMW: VARIOUS ELECTRICAL PROBLEMS. ON THE VEHICLE, VARIOUS ELECTRICAL PROBLEMS ARE POSSIBLE. WARNING LAMPS ILLUMINATED IN THE INSTRUMENT CLUSTER; CHECK CONTROL MESSAGES; SYSTEMS INOPERATIVE; FUSE BLOWN; WIPERS IN DEFAULT MODE (PERMANENTLY O

TSB Report for: 2000 BMW X5

Mfg Bulletin #: **SI-B61-15-09** Repl Bulletin #:
Bulletin Date: **20100401**
Component: **114000 ELECTRICAL SYSTEM:WIRING**

BMW: VARIOUS ELECTRICAL PROBLEMS. ON THE VEHICLE, VARIOUS ELECTRICAL PROBLEMS ARE POSSIBLE. WARNING LAMPS ILLUMINATED IN THE INSTRUMENT CLUSTER; CHECK CONTROL MESSAGES; SYSTEMS INOPERATIVE; FUSE BLOWN; WIPERS IN DEFAULT MODE (PERMANENTLY O

TSB Report for: 2000 BMW X5

Mfg Bulletin #: **SIB-32-04-07** Repl Bulletin #:
Bulletin Date: **20100601**
Component: **015000 STEERING:HYDRAULIC POWER ASSIST SYSTEM**

BMW: A NEW TECHNICAL PROCESS HAS BEEN CREATED FOR BMW TO IDENTIFY CAUSES OF STEERING COMPLAINTS WITH A WIDE RANGE OF MODELS. *RM

TSB Report for: 2000 BMW X5

Mfg Bulletin #: **SIB-32-04-07** Repl Bulletin #:
Bulletin Date: **20100601**
Component: **016000 STEERING:ELECTRIC POWER ASSIST SYSTEM**

BMW: A NEW TECHNICAL PROCESS HAS BEEN CREATED FOR BMW TO IDENTIFY CAUSES OF STEERING COMPLAINTS WITH A WIDE RANGE OF MODELS. *RM



Kelly Young
Dirigo Software
PO Box 53
Readfield, ME 04355

ds@dirigosoftware.com
www.dirigosoftware.com

TSB Report for: 2000 BMW X5

Mfg Bulletin #: **SIB-16-03-10** Repl Bulletin #:
Bulletin Date: **20100601**
Component: **061200 ENGINE AND ENGINE COOLING:ENGINE:DIESEL**

BMW: WARNING MESSAGE ON ABOUT LOW DIESEL EXHAUST FUEL LEVEL AND THAT THE ENGINE WILL NOT RESTART WITHIN 999 MILES. THE LIGHT COMES ON A FEW THOUSAND MILES EARLIER THAN A RECOMMENDED OIL CHANGE. *RM

TSB Report for: 2000 BMW X5

Mfg Bulletin #: **SIB-16-03-10** Repl Bulletin #:
Bulletin Date: **20100601**
Component: **080000 FUEL SYSTEM, DIESEL**

BMW: WARNING MESSAGE ON ABOUT LOW DIESEL EXHAUST FUEL LEVEL AND THAT THE ENGINE WILL NOT RESTART WITHIN 999 MILES. THE LIGHT COMES ON A FEW THOUSAND MILES EARLIER THAN A RECOMMENDED OIL CHANGE. *RM

TSB Report for: 2000 BMW X5

Mfg Bulletin #: **SIB-13-07-10** Repl Bulletin #:
Bulletin Date: **20100601**
Component: **061000 ENGINE AND ENGINE COOLING:ENGINE**

BMW: THERE IS A ROUGH ENGINE IDLE AND "SERVICE ENGINE SOON LIGHT" WHEN DRIVING DOWNHILL IN HIGH ALTITUDES DURING COLD WEATHER. THERE MAY BE SIX DIFFERENT FAULT CODES. *RM

TSB Report for: 2000 BMW X5

Mfg Bulletin #: **SIB-13-02-10** Repl Bulletin #:
Bulletin Date: **20100601**
Component: **070000 FUEL SYSTEM, GASOLINE**

BMW: IT IS NOW POSSIBLE TO PERFORM A FUEL QUALITY DETECTION TEST ON VEHICLES WITH AN N54 ENGINE. *RM

TSB Report for: 2000 BMW X5

Mfg Bulletin #: **SIB-13-02-10** Repl Bulletin #:
Bulletin Date: **20100601**
Component: **080000 FUEL SYSTEM, DIESEL**

BMW: IT IS NOW POSSIBLE TO PERFORM A FUEL QUALITY DETECTION TEST ON VEHICLES WITH AN N54 ENGINE. *RM



Kelly Young
Dirigo Software
PO Box 53
Readfield, ME 04355

ds@dirigosoftware.com
www.dirigosoftware.com

TSB Report for: 2000 BMW X5

Mfg Bulletin #: **SIB-13-06-10** Repl Bulletin #:
Bulletin Date: **20100601**
Component: **061000 ENGINE AND ENGINE COOLING:ENGINE**

BMW: A SERVICE ENGINE SOON LIGHT COMES ON. THE ENGINE WILL ONLY OPERATE TO 1500 RPMS AND LACKS POWER. THERE IS A SOFTWARE APPLICATION ERROR. *RM

TSB Report for: 2000 BMW X5

Mfg Bulletin #: **SIB-13-06-10** Repl Bulletin #:
Bulletin Date: **20100601**
Component: **118000 ELECTRICAL SYSTEM: SOFTWARE**

BMW: A SERVICE ENGINE SOON LIGHT COMES ON. THE ENGINE WILL ONLY OPERATE TO 1500 RPMS AND LACKS POWER. THERE IS A SOFTWARE APPLICATION ERROR. *RM

TSB Report for: 2000 BMW X5

Mfg Bulletin #: **SIB-11-08-03** Repl Bulletin #:
Bulletin Date: **20100701**
Component: **061000 ENGINE AND ENGINE COOLING:ENGINE**

BMW: SIX DIFFERENT MODELS EQUIPPED WITH THE M54 ENGINE COULD HAVE VALVE COVERS BREAK IN COLD WEATHER AND RUIN THE ENGINE. THIS IS DUE TO MOISTURE ACCUMULATION. *RM

TSB Report for: 2000 BMW X5

Mfg Bulletin #: **SIB-63-02-01** Repl Bulletin #:
Bulletin Date: **20100801**
Component: **120000 EXTERIOR LIGHTING**

BMW: PROCEDURE FOR DETERMINING AND REPLACING INCANDESCENT AND HALOGEN LIGHT BULBS UNDER WARRANTY. *RM

TSB Report for: 2000 BMW X5

Mfg Bulletin #: **SIB-61-08-10** Repl Bulletin #:
Bulletin Date: **20100801**
Component: **110000 ELECTRICAL SYSTEM**

BMW: ELCTRONICALLY DISCONNECTING THE JUNCTION BOX WITHOUT DISCONNECTING THE BATTERY WILL CAUSE DAMAGE TO THE REAR POWER DISTRIBUTION BOX. *RM

TSB Report for: 2000 BMW X5

Mfg Bulletin #: **SIB-61-08-10** Repl Bulletin #:
Bulletin Date: **20100801**
Component: **111000 ELECTRICAL SYSTEM:BATTERY**

BMW: ELCTRONICALLY DISCONNECTING THE JUNCTION BOX WITHOUT DISCONNECTING THE



Kelly Young
Dirigo Software
PO Box 53
Readfield, ME 04355

ds@dirigosoftware.com
www.dirigosoftware.com

BATTERY WILL CAUSE DAMAGE TO THE REAR POWER DISTRIBUTION BOX. *RM

TSB Report for: 2000 BMW X5

Mfg Bulletin #: **SIB-61-08-10** Repl Bulletin #: Bulletin Date: **20100801**
Component: **353000 EQUIPMENT:ELECTRICAL**

BMW: ELCTRONICALLY DISCONNECTING THE JUNCTION BOX WITHOUT DISCONNECTING THE BATTERY WILL CAUSE DAMAGE TO THE REAR POWER DISTRIBUTION BOX. *RM

TSB Report for: 2000 BMW X5

Mfg Bulletin #: **SIB-51-26-10** Repl Bulletin #: Bulletin Date: **20100801**
Component: **114000 ELECTRICAL SYSTEM:WIRING**

BMW: MODEL E70 EQUIPPED WITH AN AUTOMATIC TAILGATE. THE REAR TAILGATE MAY NOT OPERATE IN EITHER DIRECTION DUE TO WIRING DAMAGE. *RM

TSB Report for: 2000 BMW X5

Mfg Bulletin #: **SIB-51-26-10** Repl Bulletin #: Bulletin Date: **20100801**
Component: **162500 STRUCTURE:BODY:TAILGATE**

BMW: MODEL E70 EQUIPPED WITH AN AUTOMATIC TAILGATE. THE REAR TAILGATE MAY NOT OPERATE IN EITHER DIRECTION DUE TO WIRING DAMAGE. *RM

TSB Report for: 2000 BMW X5

Mfg Bulletin #: **SIB-65-36-09** Repl Bulletin #: Bulletin Date: **20100901**
Component: **114000 ELECTRICAL SYSTEM:WIRING**

BMW: THE AIRBAG WARNING LAMP IS ILLUMINATED DUE TO A SOFTWARE ERROR. *RM

TSB Report for: 2000 BMW X5

Mfg Bulletin #: **SIB-65-36-09** Repl Bulletin #: Bulletin Date: **20100901**
Component: **140000 AIR BAGS**

BMW: THE AIRBAG WARNING LAMP IS ILLUMINATED DUE TO A SOFTWARE ERROR. *RM



Kelly Young
Dirigo Software
PO Box 53
Readfield, ME 04355

ds@dirigosoftware.com
www.dirigosoftware.com

TSB Report for: 2000 BMW X5

Mfg Bulletin #: **SIB-65-36-09** Repl Bulletin #:
Component: **118000 ELECTRICAL SYSTEM: SOFTWARE** Bulletin Date: **20100901**

BMW: THE AIRBAG WARNING LAMP IS ILLUMINATED DUE TO A SOFTWARE ERROR. *RM

TSB Report for: 2000 BMW X5

Mfg Bulletin #: **SIB-52-08-09** Repl Bulletin #:
Component: **221600 SEATS:FRONT ASSEMBLY:POWER ADJUST** Bulletin Date: **20101001**

BMW: THERE ARE NOISES WHEN ADJUSTING THE FRONT DRIVER OR PASSENGER SEATES. *RM

TSB Report for: 2000 BMW X5

Mfg Bulletin #: **SIB-63-10-09** Repl Bulletin #:
Component: **125000 EXTERIOR LIGHTING:BRAKE LIGHTS** Bulletin Date: **20110301**

BMW: THE BRAKE LIGHT FAILS AND THE BULB HOLDER IS DEFORMED DUE TO HIGH TEMPERATURES AND THE COMPOSITION OF THE HOLDER. *RM

TSB Report for: 2000 BMW X5

Mfg Bulletin #: **SIB-12-15-11** Repl Bulletin #:
Component: **061000 ENGINE AND ENGINE COOLING:ENGINE** Bulletin Date: **20110701**

BMW: THE SERVICE ENGINE SOON LIGHT IS ON. THERE ARE TROUBLE CODES STORED FOR THE CRANKSHAFT SENSOR. NO DRIVEABILITY ISSUES. *RM

TSB Report for: 2000 BMW X5

Mfg Bulletin #: **SIB-63-04-10** Repl Bulletin #:
Component: **120000 EXTERIOR LIGHTING** Bulletin Date: **20100301**

BMW: THE BULB HAS FAILED ON THE DAYTIME RUNNING LAMP. *PE

TSB Report for: 2000 BMW X5

Mfg Bulletin #: **SIB-63-04-10** Repl Bulletin #:
Component: **121000 EXTERIOR LIGHTING:HEADLIGHTS** Bulletin Date: **20100301**

BMW: THE BULB HAS FAILED ON THE DAYTIME RUNNING LAMP. *PE



Kelly Young
Dirigo Software
PO Box 53
Readfield, ME 04355

ds@dirigosoftware.com
www.dirigosoftware.com

TSB Report for: 2000 BMW X5

Mfg Bulletin #: **SIB-63-05-11** Repl Bulletin #: Bulletin Date: **20110901**
Component: **121000 EXTERIOR LIGHTING:HEADLIGHTS**

BMW: ON CERTAIN VEHICLES, THE XENON HEADLAMP OFTEN HAVE NO TROUBLE FOUND WHEN RETURNED AND TESTED THRU WARRANTY PARTS SYSTEM. THE ROOT CAUSE IS NOT POSSIBLE TO BE IDENTIFY. *PE

TSB Report for: 2001 BMW X5

Mfg Bulletin #: **651201** Repl Bulletin #: Bulletin Date: **20011101**
Component: **110000 ELECTRICAL SYSTEM**

CUSTOMERS MAY COMPLAIN OF A DISCHARGED BATTERY WITH THE ALPINE CD53 RADIO. *TT

TSB Report for: 2001 BMW X5

Mfg Bulletin #: **651201** Repl Bulletin #: **651201** Bulletin Date: **20011201**
Component: **110000 ELECTRICAL SYSTEM**

REVISED INFORMATION REGARDING ALPINE CD53 RADIO CAUSING DEAD BATTERY CONDITION. *TT

TSB Report for: 2001 BMW X5

Mfg Bulletin #: **651201** Repl Bulletin #: Bulletin Date: **20020101**
Component: **353400 EQUIPMENT:ELECTRICAL:RADIO/TAPE DECK/CD ETC.**

ON SOME PARKED VEHICLES, THE ALPINE CD53 RADIO CAUSES THE BUS TO WAKE UP AT AMBIENT TEMPERATURES BELOW 40F, THE BATTERY COULD ALSO BECOME DISCHARGED. *TT

TSB Report for: 2001 BMW X5

Mfg Bulletin #: **SI651201** Repl Bulletin #: Bulletin Date: **20020101**
Component: **353400 EQUIPMENT:ELECTRICAL:RADIO/TAPE DECK/CD ETC.**

SUBJECT REGARDING SERVICE ACTION TO REPROGRAM ALPINE CD53 RADIO. *JG

TSB Report for: 2001 BMW X5

Mfg Bulletin #: **SI515401** Repl Bulletin #: Bulletin Date: **20020202**
Component: **330000 INTERIOR LIGHTING**

SOME CUSTOMERS MAY COMPLAIN OF THE LUGGAGE COMPARTMENT (HATCH) INTERIOR LIGHT BEING LOOSE OR BROKEN. *JG



Kelly Young
Dirigo Software
PO Box 53
Readfield, ME 04355

ds@dirigosoftware.com
www.dirigosoftware.com

TSB Report for: 2001 BMW X5

Mfg Bulletin #: **SIB120302** Repl Bulletin #: Bulletin Date: **20020501**
Component: **061100 ENGINE AND ENGINE COOLING:ENGINE:GASOLINE**

SUBJECT REGARDING DME REPROGRAMMING FOR CHECK ENGINE LIGHT. *TT

TSB Report for: 2001 BMW X5

Mfg Bulletin #: **510307** Repl Bulletin #: Bulletin Date: **20070201**
Component: **176100 LATCHES/LOCKS/LINKAGES:HOOD:LATCH**

INSTALL HOOD LATCH CORROSION RESISTANT CLIP. *KB

TSB Report for: 2001 BMW X5

Mfg Bulletin #: **SI B61 11 07** Repl Bulletin #: Bulletin Date: **20071101**
Component: **110000 ELECTRICAL SYSTEM**

MISSING CLIP ON POWER CABLE CAUSES VARIOUS ELECTRICAL COMPLAINTS. *NJ

TSB Report for: 2001 BMW X5

Mfg Bulletin #: **SI B 340307** Repl Bulletin #: **SI B34-03-07** Bulletin Date: **20080601**
Component: **114000 ELECTRICAL SYSTEM:WIRING**

DSC WARNING LAMP ILLUMINATED. E70 (X5) VEHICLES PRODUCED UP TO JANUARY 28, 2007. *PE
UPDATED 9/10/08. *PE

TSB Report for: 2001 BMW X5

Mfg Bulletin #: **SI B34 01 08** Repl Bulletin #: Bulletin Date: **20080401**
Component: **053000 PARKING BRAKE:INDICATOR LIGHT**

THE PARKING BRAKE WARNING IS ILLUMINATED AND FAULT CODE 6032 IS STORED. FOR MODEL
E70 (X5). *PE

TSB Report for: 2001 BMW X5

Mfg Bulletin #: **SI B37-03-07** Repl Bulletin #: Bulletin Date: **20080101**
Component: **020000 SUSPENSION**

BMW: DYNAMIC DRIVE (ARS) FRONT SWAY BAR REPAIRS. E70 (X5) WITH SPORT PACKAGE OPTION
CODE ZSP. *PE



Kelly Young
Dirigo Software
PO Box 53
Readfield, ME 04355

ds@dirigosoftware.com
www.dirigosoftware.com

TSB Report for: 2001 BMW X5

Mfg Bulletin #: **SI B63-04-08** Repl Bulletin #:
Component: **121000 EXTERIOR LIGHTING:HEADLIGHTS** Bulletin Date: **20080601**

BMW: HEADLAMP MOISTURE: FAULT DIAGNOSTICS. WATER OR CONDENSATION IN ONE OR BOTH HEADLAMPS. MODELS 5 SERIES, 6 SERIES, 7 SERIES, X5, X6, 1 SERIES, AND 3 SERIES. MODEL YEARS 2000-20008. *PE

TSB Report for: 2001 BMW X5

Mfg Bulletin #: **SI-B51-30-08** Repl Bulletin #:
Component: **160000 STRUCTURE** Bulletin Date: **20081101**

BMW: WATER LEAK IN THE FRONT RIGHT FOOTWELL AREA CAUSING THE CARPET TO BECOME WET. *PE

TSB Report for: 2001 BMW X5

Mfg Bulletin #: **SI-B51-30-08** Repl Bulletin #:
Component: **161000 STRUCTURE:FRAME AND MEMBERS** Bulletin Date: **20081101**

BMW: WATER LEAK IN THE FRONT RIGHT FOOTWELL AREA CAUSING THE CARPET TO BECOME WET. *PE

TSB Report for: 2001 BMW X5

Mfg Bulletin #: **SI-B51-30-08** Repl Bulletin #:
Component: **162000 STRUCTURE:BODY** Bulletin Date: **20081101**

BMW: WATER LEAK IN THE FRONT RIGHT FOOTWELL AREA CAUSING THE CARPET TO BECOME WET. *PE

TSB Report for: 2001 BMW X5

Mfg Bulletin #: **SI-B51-30-08** Repl Bulletin #:
Component: **162800 STRUCTURE:BODY:HOOD** Bulletin Date: **20081101**

BMW: WATER LEAK IN THE FRONT RIGHT FOOTWELL AREA CAUSING THE CARPET TO BECOME WET. *PE



Kelly Young
Dirigo Software
PO Box 53
Readfield, ME 04355

ds@dirigosoftware.com
www.dirigosoftware.com

TSB Report for: 2001 BMW X5

Mfg Bulletin #: **SI-B-11-01-0** Repl Bulletin #: Bulletin Date: **20090301**
Component: **061000 ENGINE AND ENGINE COOLING:ENGINE**

BMW: SMALL NUMBER OF VEHICLES EXPERIENCE PROBLEMS RANGING FROM LEAKING OIL FILLER CAPS, LEAKING OR BROKEN VALVE COVERS, TO COMPLETE ENGINE FAILURE IN EXTREMELY COLD CLIMATE CONDITIONS. MOISTURE ACCUMULATING IN ENGINE CRANKCASE VENTILATION V

TSB Report for: 2001 BMW X5

Mfg Bulletin #: **SI-B-11-01-0** Repl Bulletin #: Bulletin Date: **20090301**
Component: **061200 ENGINE AND ENGINE COOLING:ENGINE:DIESEL**

BMW: SMALL NUMBER OF VEHICLES EXPERIENCE PROBLEMS RANGING FROM LEAKING OIL FILLER CAPS, LEAKING OR BROKEN VALVE COVERS, TO COMPLETE ENGINE FAILURE IN EXTREMELY COLD CLIMATE CONDITIONS. MOISTURE ACCUMULATING IN ENGINE CRANKCASE VENTILATION V

TSB Report for: 2001 BMW X5

Mfg Bulletin #: **SI-B-11-01-0** Repl Bulletin #: Bulletin Date: **20090301**
Component: **063110 ENGINE AND ENGINE COOLING:EXHAUST SYSTEM:EMISSION CONTROL:CRANKCASE (PCV)**

BMW: SMALL NUMBER OF VEHICLES EXPERIENCE PROBLEMS RANGING FROM LEAKING OIL FILLER CAPS, LEAKING OR BROKEN VALVE COVERS, TO COMPLETE ENGINE FAILURE IN EXTREMELY COLD CLIMATE CONDITIONS. MOISTURE ACCUMULATING IN ENGINE CRANKCASE VENTILATION V

TSB Report for: 2001 BMW X5

Mfg Bulletin #: **SI-B130209** Repl Bulletin #: Bulletin Date: **20090301**
Component: **080000 FUEL SYSTEM, DIESEL**

BMW: DIESEL: DIAGNOSIS FOR LOW PRESSURE FUEL SUPPLY FAULTS. SERVICE ENGINE SOON LAMP IS ILLUMINATED (A FUEL PUMP MALFUNCTION MESSAGE IS DISPLAYED IN THE CC) AND A COMBINATION OF THE FOLLOWING FAULT CODES MAY BE STORED IN THE DDE CONTROL MOD

TSB Report for: 2001 BMW X5

Mfg Bulletin #: **SIB-65-75-06** Repl Bulletin #: **SIB-65-75-06** Bulletin Date: **20110801**
Component: **140000 AIR BAGS**

BMW SERVICE CAMPAIGN: SEE DOCUMENT SEARCH BUTTON FOR OWNER LETTER. THE AIRBAG WARNING LAMP (AWL) IS ILLUMINATED, TOGETHER WITH THE PASSENGER AIRBAG STATUS LAMP (POL). THE PROBLEM MAY BE INTERMITTENT. MICROCRACKS IN THE OC3 SEAT MAT. *PE



Kelly Young
Dirigo Software
PO Box 53
Readfield, ME 04355

ds@dirigosoftware.com
www.dirigosoftware.com

TSB Report for: 2001 BMW X5

Mfg Bulletin #: **SI-B31-01-08** Repl Bulletin #:
Bulletin Date: **20090901**
Component: **105200 POWER TRAIN:DRIVELINE:CONSTANT VELOCITY JOINT**

BMW: REPLACEMENT OF FRONT OUTER CV JOINT. COMPLAINTS OF CLICKING OR GRINDING NOISES COMING FROM THE FRONT AXLE AREA WHEN MAKING A TURN. THE FRONT OUTER CONSTANT VELOCITY JOINT BOOT IS SPLIT OPEN AND THE JOINT IS ALREADY DAMAGED.

TSB Report for: 2001 BMW X5

Mfg Bulletin #: **SIB-61-15-09** Repl Bulletin #:
Bulletin Date: **20100401**
Component: **110000 ELECTRICAL SYSTEM**

BMW VEHICLES: VARIOUS ELECTRICAL PROBLEMS ARE POSSIBLE ON THE VEHICLE: WARNING LAMPS ILLUMINATED IN THE INSTRUMENT CLUSTER; CHECK CONTROL MESSAGES; SYSTEMS INOPERATIVE; FUSE BLOWN; WIPERS IN DEFAULT MODE (PERMANENTLY ON); AND FAULT CODES F

TSB Report for: 2001 BMW X5

Mfg Bulletin #: **SIB-61-15-09** Repl Bulletin #:
Bulletin Date: **20100401**
Component: **117000 DIGITAL INSTRUMENT PANEL**

BMW VEHICLES: VARIOUS ELECTRICAL PROBLEMS ARE POSSIBLE ON THE VEHICLE: WARNING LAMPS ILLUMINATED IN THE INSTRUMENT CLUSTER; CHECK CONTROL MESSAGES; SYSTEMS INOPERATIVE; FUSE BLOWN; WIPERS IN DEFAULT MODE (PERMANENTLY ON); AND FAULT CODES F

TSB Report for: 2001 BMW X5

Mfg Bulletin #: **SIB-34-03-07** Repl Bulletin #:
Bulletin Date: **20091001**
Component: **110000 ELECTRICAL SYSTEM**

BMW VEHICLES: DSC WARNING LAMP ILLUMINATED. THE DSC (DYNAMIC STABILITY CONTROL) WARNING LAMP IS ILLUMINATED AND SOME OR ALL OF THE FOLLOWING FAULT CODES ARE STORED: 6E58; 6E04; 53BA; D36F; 55C3; 6ECA; AND THE WIPERS MAY ALSO BE OPERATING

TSB Report for: 2001 BMW X5

Mfg Bulletin #: **SIB-34-03-07** Repl Bulletin #:
Bulletin Date: **20091001**
Component: **114000 ELECTRICAL SYSTEM:WIRING**

BMW VEHICLES: DSC WARNING LAMP ILLUMINATED. THE DSC (DYNAMIC STABILITY CONTROL) WARNING LAMP IS ILLUMINATED AND SOME OR ALL OF THE FOLLOWING FAULT CODES ARE STORED: 6E58; 6E04; 53BA; D36F; 55C3; 6ECA; AND THE WIPERS MAY ALSO BE OPERATING



Kelly Young
Dirigo Software
PO Box 53
Readfield, ME 04355

ds@dirigosoftware.com
www.dirigosoftware.com

TSB Report for: 2001 BMW X5

Mfg Bulletin #: **SIB-34-03-07** Repl Bulletin #:
Bulletin Date: **20091001**
Component: **136000 VISIBILITY:WINDSHIELD WIPER/WASHER**

BMW VEHICLES: DSC WARNING LAMP ILLUMINATED. THE DSC (DYNAMIC STABILITY CONTROL) WARNING LAMP IS ILLUMINATED AND SOME OR ALL OF THE FOLLOWING FAULT CODES ARE STORED: 6E58; 6E04; 53BA; D36F; 55C3; 6ECA; AND THE WIPERS MAY ALSO BE OPERATING

TSB Report for: 2001 BMW X5

Mfg Bulletin #: **SIB-34-03-07** Repl Bulletin #:
Bulletin Date: **20091001**
Component: **025000 ELECTRONIC STABILITY CONTROL**

BMW VEHICLES: DSC WARNING LAMP ILLUMINATED. THE DSC (DYNAMIC STABILITY CONTROL) WARNING LAMP IS ILLUMINATED AND SOME OR ALL OF THE FOLLOWING FAULT CODES ARE STORED: 6E58; 6E04; 53BA; D36F; 55C3; 6ECA; AND THE WIPERS MAY ALSO BE OPERATING

TSB Report for: 2001 BMW X5

Mfg Bulletin #: **SIB-13-02-09** Repl Bulletin #:
Bulletin Date: **20091001**
Component: **061200 ENGINE AND ENGINE COOLING:ENGINE:DIESEL**

BMW VEHICLES: DIAGNOSIS FOR LOW PRESSURE FUEL SUPPLY FAULTS. THE SERVICE ENGINE SOON LAMP IS ILLUMINATED (A FUEL PUMP MALFUCTION MESSAGE IS DISPLAYED IN THE CC), AND A COMBINATION OF THE FOLLOWING FAULT CODES MAY BE STORED IN THE DDE CONT

TSB Report for: 2001 BMW X5

Mfg Bulletin #: **SIB-12-09-08** Repl Bulletin #:
Bulletin Date: **20080201**
Component: **062200 ENGINE AND ENGINE COOLING:COOLING SYSTEM:FAN**

BMW VEHICLE: DRIVEABILITY COMPLAINTS DUE TO COOLING FAN RELAY FAILURE. THE CUSTOMER MAY COMPLAIN OF INTERMITTENT DRIVEABILITY PROBLEMS, DESCRIBED AS-ENGINE IS LACKING POWER WHEN ACCELERATING UPHILL; TRANSMISSION WILL NOT UPSHIFT UNDER HEA

TSB Report for: 2001 BMW X5

Mfg Bulletin #: **SIB-12-09-08** Repl Bulletin #:
Bulletin Date: **20080201**
Component: **110000 ELECTRICAL SYSTEM**

BMW VEHICLE: DRIVEABILITY COMPLAINTS DUE TO COOLING FAN RELAY FAILURE. THE CUSTOMER MAY COMPLAIN OF INTERMITTENT DRIVEABILITY PROBLEMS, DESCRIBED AS-ENGINE IS LACKING POWER WHEN ACCELERATING UPHILL; TRANSMISSION WILL NOT UPSHIFT UNDER HEA



Kelly Young
Dirigo Software
PO Box 53
Readfield, ME 04355

ds@dirigosoftware.com
www.dirigosoftware.com

TSB Report for: 2001 BMW X5

Mfg Bulletin #: **SIB-12-23-07** Repl Bulletin #:
Component: **061000 ENGINE AND ENGINE COOLING:ENGINE** Bulletin Date: **20071101**

BMW VEHICLE: FC 2EF4 CHARACTERISTIC MAP THERMOSTAT. COMPLAINTS THAT THE SERVICE ENGINE SOON LAMP IS ILLUMINATED. FAULT CODE 2EF4 CHARACTERISTIC MAP THERMOSTAT IS STORED IN DME FAULT MEMORY. DME SOFTWARE CALIBRATION RELATED TO HIGH HEATIN

TSB Report for: 2001 BMW X5

Mfg Bulletin #: **SIB-12-23-07** Repl Bulletin #:
Component: **353000 EQUIPMENT:ELECTRICAL** Bulletin Date: **20071101**

BMW VEHICLE: FC 2EF4 CHARACTERISTIC MAP THERMOSTAT. COMPLAINTS THAT THE SERVICE ENGINE SOON LAMP IS ILLUMINATED. FAULT CODE 2EF4 CHARACTERISTIC MAP THERMOSTAT IS STORED IN DME FAULT MEMORY. DME SOFTWARE CALIBRATION RELATED TO HIGH HEATIN

TSB Report for: 2001 BMW X5

Mfg Bulletin #: **SIB-12-23-07** Repl Bulletin #:
Component: **118000 ELECTRICAL SYSTEM: SOFTWARE** Bulletin Date: **20071101**

BMW VEHICLE: FC 2EF4 CHARACTERISTIC MAP THERMOSTAT. COMPLAINTS THAT THE SERVICE ENGINE SOON LAMP IS ILLUMINATED. FAULT CODE 2EF4 CHARACTERISTIC MAP THERMOSTAT IS STORED IN DME FAULT MEMORY. DME SOFTWARE CALIBRATION RELATED TO HIGH HEATIN

TSB Report for: 2001 BMW X5

Mfg Bulletin #: **SIB-61-11-07** Repl Bulletin #:
Component: **110000 ELECTRICAL SYSTEM** Bulletin Date: **20071101**

BMW VEHICLE: MISSING CLIP ON POWER CABLE CAUSES VARIOUS ELECTRICAL COMPLAINTS. VEHICLE WILL NOT START. INSTRUMENT CLUSTER OR DISPLAYS ARE FLICKERING. REMOTE CONTROL WILL NOT UNLOCK VEHICLE. VARIOUS CONTROL MODULES CANNOT BE ACCESSED USIN

TSB Report for: 2001 BMW X5

Mfg Bulletin #: **SIB-61-13-07** Repl Bulletin #:
Component: **110000 ELECTRICAL SYSTEM** Bulletin Date: **20071101**

BMW VEHICLE: ELECTRONIC MALFUNCTION CC MESSAGE CAUSED BY SHORTED WIRING. THE ELECTRONIC MALFUNCTION CHECK CONTROL MESSAGE MAY BE DISPLAYED; THE SOUNDS SYSTEM EMITS A STATIC NOISE FROM THE SPEAKERS; THE RFK (REAR VIEW CAMERA) DOES NOT PAN;



Kelly Young
Dirigo Software
PO Box 53
Readfield, ME 04355

ds@dirigosoftware.com
www.dirigosoftware.com

TSB Report for: 2001 BMW X5

Mfg Bulletin #: **SIB-61-13-07** Repl Bulletin #: Bulletin Date: **20071101**
Component: **114000 ELECTRICAL SYSTEM:WIRING**

BMW VEHICLE: ELECTRONIC MALFUNCTION CC MESSAGE CAUSED BY SHORTED WIRING. THE ELECTRONIC MALFUNCTION CHECK CONTROL MESSAGE MAY BE DISPLAYED; THE SOUNDS SYSTEM EMITS A STATIC NOISE FROM THE SPEAKERS; THE RFK (REAR VIEW CAMERA) DOES NOT PAN;

TSB Report for: 2001 BMW X5

Mfg Bulletin #: **SIB-61-13-07** Repl Bulletin #: Bulletin Date: **20071101**
Component: **353000 EQUIPMENT:ELECTRICAL**

BMW VEHICLE: ELECTRONIC MALFUNCTION CC MESSAGE CAUSED BY SHORTED WIRING. THE ELECTRONIC MALFUNCTION CHECK CONTROL MESSAGE MAY BE DISPLAYED; THE SOUNDS SYSTEM EMITS A STATIC NOISE FROM THE SPEAKERS; THE RFK (REAR VIEW CAMERA) DOES NOT PAN;

TSB Report for: 2001 BMW X5

Mfg Bulletin #: **SIB-61-13-07** Repl Bulletin #: Bulletin Date: **20071101**
Component: **118000 ELECTRICAL SYSTEM: SOFTWARE**

BMW VEHICLE: ELECTRONIC MALFUNCTION CC MESSAGE CAUSED BY SHORTED WIRING. THE ELECTRONIC MALFUNCTION CHECK CONTROL MESSAGE MAY BE DISPLAYED; THE SOUNDS SYSTEM EMITS A STATIC NOISE FROM THE SPEAKERS; THE RFK (REAR VIEW CAMERA) DOES NOT PAN;

TSB Report for: 2001 BMW X5

Mfg Bulletin #: **SIB-36-05-07** Repl Bulletin #: Bulletin Date: **20071201**
Component: **199000 TIRES:PRESSURE MONITORING AND REGULATING SYSTEMS**

BMW: TIRE WARNING LIGHT ILLUMINATED DUE TO LOW AMBIENT TEMPERATURE. MODEL E90, E91 (3 SERIES); E92, E92 (3 SERIES); E60 (5 SERIES); E60 (M5); E63, E64 (6 SERIES); E63, E64 (M6); E65, E66 (7 SERIES); E70 (X5); E83 (X3); AND E85, E86 (Z4).

TSB Report for: 2001 BMW X5

Mfg Bulletin #: **SIB-16-02-09** Repl Bulletin #: Bulletin Date: **20091201**
Component: **072100 FUEL SYSTEM, GASOLINE:DELIVERY:FUEL PUMP**

BMW VEHICLES: FUEL LEVEL SENSOR REPAIRS. WHERE IT IS NECESSARY TO REPLACE THE RIGHT OR THE LEFT SIDE FUEL LEVEL SENSOR DUE TO A FAILURE, THE ENTIRE PUMP AND



Kelly Young
Dirigo Software
PO Box 53
Readfield, ME 04355

ds@dirigosoftware.com
www.dirigosoftware.com

HOUSING OR DELIVERY UNIT (SUCTION JET ASSEMBLY) DO NOT NEED TO BE REPLACED AS WEL

TSB Report for: 2001 BMW X5

Mfg Bulletin #: **SI-B61-15-09** Repl Bulletin #: Bulletin Date: **20100401**
Component: **110000 ELECTRICAL SYSTEM**

BMW: VARIOUS ELECTRICAL PROBLEMS. ON THE VEHICLE, VARIOUS ELECTRICAL PROBLEMS ARE POSSIBLE. WARNING LAMPS ILLUMINATED IN THE INSTRUMENT CLUSTER; CHECK CONTROL MESSAGES; SYSTEMS INOPERATIVE; FUSE BLOWN; WIPERS IN DEFAULT MODE (PERMANENTLY O

TSB Report for: 2001 BMW X5

Mfg Bulletin #: **SI-B61-15-09** Repl Bulletin #: Bulletin Date: **20100401**
Component: **114000 ELECTRICAL SYSTEM:WIRING**

BMW: VARIOUS ELECTRICAL PROBLEMS. ON THE VEHICLE, VARIOUS ELECTRICAL PROBLEMS ARE POSSIBLE. WARNING LAMPS ILLUMINATED IN THE INSTRUMENT CLUSTER; CHECK CONTROL MESSAGES; SYSTEMS INOPERATIVE; FUSE BLOWN; WIPERS IN DEFAULT MODE (PERMANENTLY O

TSB Report for: 2001 BMW X5

Mfg Bulletin #: **SIB-32-04-07** Repl Bulletin #: Bulletin Date: **20100601**
Component: **015000 STEERING:HYDRAULIC POWER ASSIST SYSTEM**

BMW: A NEW TECHNICAL PROCESS HAS BEEN CREATED FOR BMW TO IDENTIFY CAUSES OF STEERING COMPLAINTS WITH A WIDE RANGE OF MODELS. *RM

TSB Report for: 2001 BMW X5

Mfg Bulletin #: **SIB-32-04-07** Repl Bulletin #: Bulletin Date: **20100601**
Component: **016000 STEERING:ELECTRIC POWER ASSIST SYSTEM**

BMW: A NEW TECHNICAL PROCESS HAS BEEN CREATED FOR BMW TO IDENTIFY CAUSES OF STEERING COMPLAINTS WITH A WIDE RANGE OF MODELS. *RM



Kelly Young
Dirigo Software
PO Box 53
Readfield, ME 04355

ds@dirigosoftware.com
www.dirigosoftware.com

TSB Report for: 2001 BMW X5

Mfg Bulletin #: **SIB-16-03-10** Repl Bulletin #: Bulletin Date: **20100601**
Component: **061200 ENGINE AND ENGINE COOLING:ENGINE:DIESEL**

BMW: WARNING MESSAGE ON ABOUT LOW DIESEL EXHAUST FUEL LEVEL AND THAT THE ENGINE WILL NOT RESTART WITHIN 999 MILES. THE LIGHT COMES ON A FEW THOUSAND MILES EARLIER THAN A RECOMMENDED OIL CHANGE. *RM

TSB Report for: 2001 BMW X5

Mfg Bulletin #: **SIB-16-03-10** Repl Bulletin #: Bulletin Date: **20100601**
Component: **080000 FUEL SYSTEM, DIESEL**

BMW: WARNING MESSAGE ON ABOUT LOW DIESEL EXHAUST FUEL LEVEL AND THAT THE ENGINE WILL NOT RESTART WITHIN 999 MILES. THE LIGHT COMES ON A FEW THOUSAND MILES EARLIER THAN A RECOMMENDED OIL CHANGE. *RM

TSB Report for: 2001 BMW X5

Mfg Bulletin #: **SIB-13-07-10** Repl Bulletin #: Bulletin Date: **20100601**
Component: **061000 ENGINE AND ENGINE COOLING:ENGINE**

BMW: THERE IS A ROUGH ENGINE IDLE AND "SERVICE ENGINE SOON LIGHT" WHEN DRIVING DOWNHILL IN HIGH ALTITUDES DURING COLD WEATHER. THERE MAY BE SIX DIFFERENT FAULT CODES. *RM

TSB Report for: 2001 BMW X5

Mfg Bulletin #: **SIB-13-02-10** Repl Bulletin #: Bulletin Date: **20100601**
Component: **070000 FUEL SYSTEM, GASOLINE**

BMW: IT IS NOW POSSIBLE TO PERFORM A FUEL QUALITY DETECTION TEST ON VEHICLES WITH AN N54 ENGINE. *RM

TSB Report for: 2001 BMW X5

Mfg Bulletin #: **SIB-13-02-10** Repl Bulletin #: Bulletin Date: **20100601**
Component: **080000 FUEL SYSTEM, DIESEL**

BMW: IT IS NOW POSSIBLE TO PERFORM A FUEL QUALITY DETECTION TEST ON VEHICLES WITH AN N54 ENGINE. *RM



Kelly Young
Dirigo Software
PO Box 53
Readfield, ME 04355

ds@dirigosoftware.com
www.dirigosoftware.com

TSB Report for: 2001 BMW X5

Mfg Bulletin #: **SIB-13-06-10** Repl Bulletin #:
Bulletin Date: **20100601**
Component: **061000 ENGINE AND ENGINE COOLING:ENGINE**

BMW: A SERVICE ENGINE SOON LIGHT COMES ON. THE ENGINE WILL ONLY OPERATE TO 1500 RPMS AND LACKS POWER. THERE IS A SOFTWARE APPLICATION ERROR. *RM

TSB Report for: 2001 BMW X5

Mfg Bulletin #: **SIB-13-06-10** Repl Bulletin #:
Bulletin Date: **20100601**
Component: **118000 ELECTRICAL SYSTEM: SOFTWARE**

BMW: A SERVICE ENGINE SOON LIGHT COMES ON. THE ENGINE WILL ONLY OPERATE TO 1500 RPMS AND LACKS POWER. THERE IS A SOFTWARE APPLICATION ERROR. *RM

TSB Report for: 2001 BMW X5

Mfg Bulletin #: **SIB-11-08-03** Repl Bulletin #:
Bulletin Date: **20100701**
Component: **061000 ENGINE AND ENGINE COOLING:ENGINE**

BMW: SIX DIFFERENT MODELS EQUIPPED WITH THE M54 ENGINE COULD HAVE VALVE COVERS BREAK IN COLD WEATHER AND RUIN THE ENGINE. THIS IS DUE TO MOISTURE ACCUMULATION. *RM

TSB Report for: 2001 BMW X5

Mfg Bulletin #: **SIB-63-02-01** Repl Bulletin #:
Bulletin Date: **20100801**
Component: **120000 EXTERIOR LIGHTING**

BMW: PROCEDURE FOR DETERMINING AND REPLACING INCANDESCENT AND HALOGEN LIGHT BULBS UNDER WARRANTY. *RM

TSB Report for: 2001 BMW X5

Mfg Bulletin #: **SIB-61-08-10** Repl Bulletin #:
Bulletin Date: **20100801**
Component: **110000 ELECTRICAL SYSTEM**

BMW: ELCTRONICALLY DISCONNECTING THE JUNCTION BOX WITHOUT DISCONNECTING THE BATTERY WILL CAUSE DAMAGE TO THE REAR POWER DISTRIBUTION BOX. *RM

TSB Report for: 2001 BMW X5

Mfg Bulletin #: **SIB-61-08-10** Repl Bulletin #:
Bulletin Date: **20100801**
Component: **111000 ELECTRICAL SYSTEM:BATTERY**

BMW: ELCTRONICALLY DISCONNECTING THE JUNCTION BOX WITHOUT DISCONNECTING THE



Kelly Young
Dirigo Software
PO Box 53
Readfield, ME 04355

ds@dirigosoftware.com
www.dirigosoftware.com

BATTERY WILL CAUSE DAMAGE TO THE REAR POWER DISTRIBUTION BOX. *RM

TSB Report for: 2001 BMW X5

Mfg Bulletin #: **SIB-61-08-10** Repl Bulletin #: Bulletin Date: **20100801**
Component: **353000 EQUIPMENT:ELECTRICAL**

BMW: ELCTRONICALLY DISCONNECTING THE JUNCTION BOX WITHOUT DISCONNECTING THE BATTERY WILL CAUSE DAMAGE TO THE REAR POWER DISTRIBUTION BOX. *RM

TSB Report for: 2001 BMW X5

Mfg Bulletin #: **SIB-51-26-10** Repl Bulletin #: Bulletin Date: **20100801**
Component: **114000 ELECTRICAL SYSTEM:WIRING**

BMW: MODEL E70 EQUIPPED WITH AN AUTOMATIC TAILGATE. THE REAR TAILGATE MAY NOT OPERATE IN EITHER DIRECTION DUE TO WIRING DAMAGE. *RM

TSB Report for: 2001 BMW X5

Mfg Bulletin #: **SIB-51-26-10** Repl Bulletin #: Bulletin Date: **20100801**
Component: **162500 STRUCTURE:BODY:TAILGATE**

BMW: MODEL E70 EQUIPPED WITH AN AUTOMATIC TAILGATE. THE REAR TAILGATE MAY NOT OPERATE IN EITHER DIRECTION DUE TO WIRING DAMAGE. *RM

TSB Report for: 2001 BMW X5

Mfg Bulletin #: **SIB-65-36-09** Repl Bulletin #: Bulletin Date: **20100901**
Component: **114000 ELECTRICAL SYSTEM:WIRING**

BMW: THE AIRBAG WARNING LAMP IS ILLUMINATED DUE TO A SOFTWARE ERROR. *RM

TSB Report for: 2001 BMW X5

Mfg Bulletin #: **SIB-65-36-09** Repl Bulletin #: Bulletin Date: **20100901**
Component: **140000 AIR BAGS**

BMW: THE AIRBAG WARNING LAMP IS ILLUMINATED DUE TO A SOFTWARE ERROR. *RM



Kelly Young
Dirigo Software
PO Box 53
Readfield, ME 04355

ds@dirigosoftware.com
www.dirigosoftware.com

TSB Report for: 2001 BMW X5

Mfg Bulletin #: **SIB-65-36-09** Repl Bulletin #: Bulletin Date: **20100901**
Component: **118000 ELECTRICAL SYSTEM: SOFTWARE**

BMW: THE AIRBAG WARNING LAMP IS ILLUMINATED DUE TO A SOFTWARE ERROR. *RM

TSB Report for: 2001 BMW X5

Mfg Bulletin #: **SIB-52-08-09** Repl Bulletin #: Bulletin Date: **20101001**
Component: **221600 SEATS:FRONT ASSEMBLY:POWER ADJUST**

BMW: THERE ARE NOISES WHEN ADJUSTING THE FRONT DRIVER OR PASSENGER SEATES. *RM

TSB Report for: 2001 BMW X5

Mfg Bulletin #: **SIB-63-10-09** Repl Bulletin #: Bulletin Date: **20110301**
Component: **125000 EXTERIOR LIGHTING:BRAKE LIGHTS**

BMW: THE BRAKE LIGHT FAILS AND THE BULB HOLDER IS DEFORMED DUE TO HIGH TEMPERATURES AND THE COMPOSITION OF THE HOLDER. *RM

TSB Report for: 2001 BMW X5

Mfg Bulletin #: **SIB-12-15-11** Repl Bulletin #: Bulletin Date: **20110701**
Component: **061000 ENGINE AND ENGINE COOLING:ENGINE**

BMW: THE SERVICE ENGINE SOON LIGHT IS ON. THERE ARE TROUBLE CODES STORED FOR THE CRANKSHAFT SENSOR. NO DRIVEABILITY ISSUES. *RM

TSB Report for: 2001 BMW X5

Mfg Bulletin #: **SIB-63-04-10** Repl Bulletin #: Bulletin Date: **20100301**
Component: **120000 EXTERIOR LIGHTING**

BMW: THE BULB HAS FAILED ON THE DAYTIME RUNNING LAMP. *PE

TSB Report for: 2001 BMW X5

Mfg Bulletin #: **SIB-63-04-10** Repl Bulletin #: Bulletin Date: **20100301**
Component: **121000 EXTERIOR LIGHTING:HEADLIGHTS**

BMW: THE BULB HAS FAILED ON THE DAYTIME RUNNING LAMP. *PE



Kelly Young
Dirigo Software
PO Box 53
Readfield, ME 04355

ds@dirigosoftware.com
www.dirigosoftware.com

TSB Report for: 2001 BMW X5

Mfg Bulletin #: **SIB-63-05-11** Repl Bulletin #: Bulletin Date: **20110901**
Component: **121000 EXTERIOR LIGHTING:HEADLIGHTS**

BMW: ON CERTAIN VEHICLES, THE XENON HEADLAMP OFTEN HAVE NO TROUBLE FOUND WHEN RETURNED AND TESTED THRU WARRANTY PARTS SYSTEM. THE ROOT CAUSE IS NOT POSSIBLE TO BE IDENTIFY. *PE

TSB Report for: 2002 BMW X5

Mfg Bulletin #: **515301** Repl Bulletin #: Bulletin Date: **20011201**
Component: **162300 STRUCTURE:BODY:DOOR**

SUBJECT REGARDING INCORRECT MATERIAL IN THE REAR HATCH SWITCH THAT MAY CAUSE THE SWITCH TO OPERATE THE ACTUATOR MOTOR WITHOUT THE SWITCH BEING DEPRESSED. *TT

TSB Report for: 2002 BMW X5

Mfg Bulletin #: **SI515301** Repl Bulletin #: Bulletin Date: **20020201**
Component: **133000 VISIBILITY:POWER WINDOW DEVICES AND CONTROLS**

INFORMATION REGARDING SERVICE ACTION TO CHECK REAR HATCH SWITCH. *YH

TSB Report for: 2002 BMW X5

Mfg Bulletin #: **135002** Repl Bulletin #: Bulletin Date: **20021101**
Component: **090000 FUEL SYSTEM, OTHER**

INTAKE AIR BOOT LOOSE. *TT

TSB Report for: 2002 BMW X5

Mfg Bulletin #: **125003** Repl Bulletin #: Bulletin Date: **20030101**
Component: **110000 ELECTRICAL SYSTEM**

REPROGRAM OF DME CONTROL MODULE. *TT

TSB Report for: 2002 BMW X5

Mfg Bulletin #: **510307** Repl Bulletin #: Bulletin Date: **20070201**
Component: **176100 LATCHES/LOCKS/LINKAGES:HOOD:LATCH**

INSTALL HOOD LATCH CORROSION RESISTANT CLIP. *KB



Kelly Young
Dirigo Software
PO Box 53
Readfield, ME 04355

ds@dirigosoftware.com
www.dirigosoftware.com

TSB Report for: 2002 BMW X5

Mfg Bulletin #: **SI B61 11 07** Repl Bulletin #: Bulletin Date: **20071101**
Component: **110000 ELECTRICAL SYSTEM**

MISSING CLIP ON POWER CABLE CAUSES VARIOUS ELECTRICAL COMPLAINTS. *NJ

TSB Report for: 2002 BMW X5

Mfg Bulletin #: **SI B 340307** Repl Bulletin #: **SI B34-03-07** Bulletin Date: **20080601**
Component: **114000 ELECTRICAL SYSTEM:WIRING**

DSC WARNING LAMP ILLUMINATED. E70 (X5) VEHICLES PRODUCED UP TO JANUARY 28, 2007. *PE
UPDATED 9/10/08. *PE

TSB Report for: 2002 BMW X5

Mfg Bulletin #: **SI B34 01 08** Repl Bulletin #: Bulletin Date: **20080401**
Component: **053000 PARKING BRAKE:INDICATOR LIGHT**

THE PARKING BRAKE WARNING IS ILLUMINATED AND FAULT CODE 6032 IS STORED. FOR MODEL
E70 (X5). *PE

TSB Report for: 2002 BMW X5

Mfg Bulletin #: **SI B37-03-07** Repl Bulletin #: Bulletin Date: **20080101**
Component: **020000 SUSPENSION**

BMW: DYNAMIC DRIVE (ARS) FRONT SWAY BAR REPAIRS. E70 (X5) WITH SPORT PACKAGE OPTION
CODE ZSP. *PE

TSB Report for: 2002 BMW X5

Mfg Bulletin #: **SI B63-04-08** Repl Bulletin #: Bulletin Date: **20080601**
Component: **121000 EXTERIOR LIGHTING:HEADLIGHTS**

BMW: HEADLAMP MOISTURE: FAULT DIAGNOSTICS. WATER OR CONDENSATION IN ONE OR BOTH
HEADLAMPS. MODELS 5 SERIES, 6 SERIES, 7 SERIES, X5, X6, 1 SERIES, AND 3 SERIES. MODEL
YEARS 2000-20008. *PE

TSB Report for: 2002 BMW X5

Mfg Bulletin #: **SI-B51-30-08** Repl Bulletin #: Bulletin Date: **20081101**
Component: **160000 STRUCTURE**

BMW: WATER LEAK IN THE FRONT RIGHT FOOTWELL AREA CAUSING THE CARPET TO BECOME



Kelly Young
Dirigo Software
PO Box 53
Readfield, ME 04355

ds@dirigosoftware.com
www.dirigosoftware.com

WET. *PE

TSB Report for: 2002 BMW X5

Mfg Bulletin #: **SI-B51-30-08** Repl Bulletin #:
Bulletin Date: **20081101**
Component: **161000 STRUCTURE:FRAME AND MEMBERS**

BMW: WATER LEAK IN THE FRONT RIGHT FOOTWELL AREA CAUSING THE CARPET TO BECOME
WET. *PE

TSB Report for: 2002 BMW X5

Mfg Bulletin #: **SI-B51-30-08** Repl Bulletin #:
Bulletin Date: **20081101**
Component: **162000 STRUCTURE:BODY**

BMW: WATER LEAK IN THE FRONT RIGHT FOOTWELL AREA CAUSING THE CARPET TO BECOME
WET. *PE

TSB Report for: 2002 BMW X5

Mfg Bulletin #: **SI-B51-30-08** Repl Bulletin #:
Bulletin Date: **20081101**
Component: **162800 STRUCTURE:BODY:HOOD**

BMW: WATER LEAK IN THE FRONT RIGHT FOOTWELL AREA CAUSING THE CARPET TO BECOME
WET. *PE

TSB Report for: 2002 BMW X5

Mfg Bulletin #: **SI-B-11-01-0** Repl Bulletin #:
Bulletin Date: **20090301**
Component: **061000 ENGINE AND ENGINE COOLING:ENGINE**

BMW: SMALL NUMBER OF VEHICLES EXPERIENCE PROBLEMS RANGING FROM LEAKING OIL FILLER
CAPS, LEAKING OR BROKEN VALVE COVERS, TO COMPLETE ENGINE FAILURE IN EXTREMELY COLD
CLIMATE CONDITIONS. MOISTURE ACCUMULATING IN ENGINE CRANKCASE VENTILATION V

TSB Report for: 2002 BMW X5

Mfg Bulletin #: **SI-B-11-01-0** Repl Bulletin #:
Bulletin Date: **20090301**
Component: **061200 ENGINE AND ENGINE COOLING:ENGINE:DIESEL**

BMW: SMALL NUMBER OF VEHICLES EXPERIENCE PROBLEMS RANGING FROM LEAKING OIL FILLER



Kelly Young
Dirigo Software
PO Box 53
Readfield, ME 04355

ds@dirigosoftware.com
www.dirigosoftware.com

CAPS, LEAKING OR BROKEN VALVE COVERS, TO COMPLETE ENGINE FAILURE IN EXTREMELY COLD CLIMATE CONDITIONS. MOISTURE ACCUMULATING IN ENGINE CRANKCASE VENTILATION V

TSB Report for: 2002 BMW X5

Mfg Bulletin #: **SI-B-11-01-0** Repl Bulletin #: Bulletin Date: **20090301**

Component: **063110 ENGINE AND ENGINE COOLING:EXHAUST SYSTEM:EMISSION CONTROL:CRANKCASE (PCV)**

BMW: SMALL NUMBER OF VEHICLES EXPERIENCE PROBLEMS RANGING FROM LEAKING OIL FILLER CAPS, LEAKING OR BROKEN VALVE COVERS, TO COMPLETE ENGINE FAILURE IN EXTREMELY COLD CLIMATE CONDITIONS. MOISTURE ACCUMULATING IN ENGINE CRANKCASE VENTILATION V

TSB Report for: 2002 BMW X5

Mfg Bulletin #: **SI-B130209** Repl Bulletin #: Bulletin Date: **20090301**

Component: **080000 FUEL SYSTEM, DIESEL**

BMW: DIESEL: DIAGNOSIS FOR LOW PRESSURE FUEL SUPPLY FAULTS. SERVICE ENGINE SOON LAMP IS ILLUMINATED (A FUEL PUMP MALFUNCTION MESSAGE IS DISPLAYED IN THE CC) AND A COMBINATION OF THE FOLLOWING FAULT CODES MAY BE STORED IN THE DDE CONTROL MOD

TSB Report for: 2002 BMW X5

Mfg Bulletin #: **SIB-65-75-06** Repl Bulletin #: **SIB-65-75-06** Bulletin Date: **20110801**

Component: **140000 AIR BAGS**

BMW SERVICE CAMPAIGN: SEE DOCUMENT SEARCH BUTTON FOR OWNER LETTER. THE AIRBAG WARNING LAMP (AWL) IS ILLUMINATED, TOGETHER WITH THE PASSENGER AIRBAG STATUS LAMP (POL). THE PROBLEM MAY BE INTERMITTENT. MICROCRACKS IN THE OC3 SEAT MAT. *PE

TSB Report for: 2002 BMW X5

Mfg Bulletin #: **SI-B31-01-08** Repl Bulletin #: Bulletin Date: **20090901**

Component: **105200 POWER TRAIN:DRIVELINE:CONSTANT VELOCITY JOINT**

BMW: REPLACEMENT OF FRONT OUTER CV JOINT. COMPLAINTS OF CLICKING OR GRINDING NOISES COMING FROM THE FRONT AXLE AREA WHEN MAKING A TURN. THE FRONT OUTER CONSTANT VELOCITY JOINT BOOT IS SPLIT OPEN AND THE JOINT IS ALREADY DAMAGED.



Kelly Young
Dirigo Software
PO Box 53
Readfield, ME 04355

ds@dirigosoftware.com
www.dirigosoftware.com

TSB Report for: 2002 BMW X5

Mfg Bulletin #: **SIB-61-15-09** Repl Bulletin #: Bulletin Date: **20100401**
Component: **110000 ELECTRICAL SYSTEM**

BMW VEHICLES: VARIOUS ELECTRICAL PROBLEMS ARE POSSIBLE ON THE VEHICLE: WARNING LAMPS ILLUMINATED IN THE INSTRUMENT CLUSTER; CHECK CONTROL MESSAGES; SYSTEMS INOPERATIVE; FUSE BLOWN; WIPERS IN DEFAULT MODE (PERMANENTLY ON); AND FAULT CODES F

TSB Report for: 2002 BMW X5

Mfg Bulletin #: **SIB-61-15-09** Repl Bulletin #: Bulletin Date: **20100401**
Component: **117000 DIGITAL INSTRUMENT PANEL**

BMW VEHICLES: VARIOUS ELECTRICAL PROBLEMS ARE POSSIBLE ON THE VEHICLE: WARNING LAMPS ILLUMINATED IN THE INSTRUMENT CLUSTER; CHECK CONTROL MESSAGES; SYSTEMS INOPERATIVE; FUSE BLOWN; WIPERS IN DEFAULT MODE (PERMANENTLY ON); AND FAULT CODES F

TSB Report for: 2002 BMW X5

Mfg Bulletin #: **SIB-34-03-07** Repl Bulletin #: Bulletin Date: **20091001**
Component: **110000 ELECTRICAL SYSTEM**

BMW VEHICLES: DSC WARNING LAMP ILLUMINATED. THE DSC (DYNAMIC STABILITY CONTROL) WARNING LAMP IS ILLUMINATED AND SOME OR ALL OF THE FOLLOWING FAULT CODES ARE STORED: 6E58; 6E04; 53BA; D36F; 55C3; 6ECA; AND THE WIPERS MAY ALSO BE OPERATING

TSB Report for: 2002 BMW X5

Mfg Bulletin #: **SIB-34-03-07** Repl Bulletin #: Bulletin Date: **20091001**
Component: **114000 ELECTRICAL SYSTEM:WIRING**

BMW VEHICLES: DSC WARNING LAMP ILLUMINATED. THE DSC (DYNAMIC STABILITY CONTROL) WARNING LAMP IS ILLUMINATED AND SOME OR ALL OF THE FOLLOWING FAULT CODES ARE STORED: 6E58; 6E04; 53BA; D36F; 55C3; 6ECA; AND THE WIPERS MAY ALSO BE OPERATING

TSB Report for: 2002 BMW X5

Mfg Bulletin #: **SIB-34-03-07** Repl Bulletin #: Bulletin Date: **20091001**
Component: **136000 VISIBILITY:WINDSHIELD WIPER/WASHER**

BMW VEHICLES: DSC WARNING LAMP ILLUMINATED. THE DSC (DYNAMIC STABILITY CONTROL) WARNING LAMP IS ILLUMINATED AND SOME OR ALL OF THE FOLLOWING FAULT CODES ARE STORED: 6E58; 6E04; 53BA; D36F; 55C3; 6ECA; AND THE WIPERS MAY ALSO BE OPERATING



Kelly Young
Dirigo Software
PO Box 53
Readfield, ME 04355

ds@dirigosoftware.com
www.dirigosoftware.com

TSB Report for: 2002 BMW X5

Mfg Bulletin #: **SIB-34-03-07** Repl Bulletin #: Bulletin Date: **20091001**
Component: **025000 ELECTRONIC STABILITY CONTROL**

BMW VEHICLES: DSC WARNING LAMP ILLUMINATED. THE DSC (DYNAMIC STABILITY CONTROL) WARNING LAMP IS ILLUMINATED AND SOME OR ALL OF THE FOLLOWING FAULT CODES ARE STORED: 6E58; 6E04; 53BA; D36F; 55C3; 6ECA; AND THE WIPERS MAY ALSO BE OPERATING

TSB Report for: 2002 BMW X5

Mfg Bulletin #: **SIB-13-02-09** Repl Bulletin #: Bulletin Date: **20091001**
Component: **061200 ENGINE AND ENGINE COOLING:ENGINE:DIESEL**

BMW VEHICLES: DIAGNOSIS FOR LOW PRESSURE FUEL SUPPLY FAULTS. THE SERVICE ENGINE SOON LAMP IS ILLUMINATED (A FUEL PUMP MALFUCTION MESSAGE IS DISPLAYED IN THE CC), AND A COMBINATION OF THE FOLLOWING FAULT CODES MAY BE STORED IN THE DDE CONT

TSB Report for: 2002 BMW X5

Mfg Bulletin #: **SIB-12-09-08** Repl Bulletin #: Bulletin Date: **20080201**
Component: **062200 ENGINE AND ENGINE COOLING:COOLING SYSTEM:FAN**

BMW VEHICLE: DRIVEABILITY COMPLAINTS DUE TO COOLING FAN RELAY FAILURE. THE CUSTOMER MAY COMPLAIN OF INTERMITTENT DRIVEABILITY PROBLEMS, DESCRIBED AS-ENGINE IS LACKING POWER WHEN ACCELERATING UPHILL; TRANSMISSION WILL NOT UPSHIFT UNDER HEA

TSB Report for: 2002 BMW X5

Mfg Bulletin #: **SIB-12-09-08** Repl Bulletin #: Bulletin Date: **20080201**
Component: **110000 ELECTRICAL SYSTEM**

BMW VEHICLE: DRIVEABILITY COMPLAINTS DUE TO COOLING FAN RELAY FAILURE. THE CUSTOMER MAY COMPLAIN OF INTERMITTENT DRIVEABILITY PROBLEMS, DESCRIBED AS-ENGINE IS LACKING POWER WHEN ACCELERATING UPHILL; TRANSMISSION WILL NOT UPSHIFT UNDER HEA

TSB Report for: 2002 BMW X5

Mfg Bulletin #: **SIB-12-23-07** Repl Bulletin #: Bulletin Date: **20071101**
Component: **061000 ENGINE AND ENGINE COOLING:ENGINE**

BMW VEHICLE: FC 2EF4 CHARACTERISTIC MAP THERMOSTAT. COMPLAINTS THAT THE SERVICE ENGINE SOON LAMP IS ILLUMINATED. FAULT CODE 2EF4 CHARACTERISTIC MAP THERMOSTAT IS STORED IN DME FAULT MEMORY. DME SOFTWARE CALIBRATION RELATED TO HIGH HEATIN



Kelly Young
Dirigo Software
PO Box 53
Readfield, ME 04355

ds@dirigosoftware.com
www.dirigosoftware.com

TSB Report for: 2002 BMW X5

Mfg Bulletin #: **SIB-12-23-07** Repl Bulletin #: Bulletin Date: **20071101**
Component: **353000 EQUIPMENT:ELECTRICAL**

BMW VEHICLE: FC 2EF4 CHARACTERISTIC MAP THERMOSTAT. COMPLAINTS THAT THE SERVICE ENGINE SOON LAMP IS ILLUMINATED. FAULT CODE 2EF4 CHARACTERISTIC MAP THERMOSTAT IS STORED IN DME FAULT MEMORY. DME SOFTWARE CALIBRATION RELATED TO HIGH HEATIN

TSB Report for: 2002 BMW X5

Mfg Bulletin #: **SIB-12-23-07** Repl Bulletin #: Bulletin Date: **20071101**
Component: **118000 ELECTRICAL SYSTEM: SOFTWARE**

BMW VEHICLE: FC 2EF4 CHARACTERISTIC MAP THERMOSTAT. COMPLAINTS THAT THE SERVICE ENGINE SOON LAMP IS ILLUMINATED. FAULT CODE 2EF4 CHARACTERISTIC MAP THERMOSTAT IS STORED IN DME FAULT MEMORY. DME SOFTWARE CALIBRATION RELATED TO HIGH HEATIN

TSB Report for: 2002 BMW X5

Mfg Bulletin #: **SIB-61-11-07** Repl Bulletin #: Bulletin Date: **20071101**
Component: **110000 ELECTRICAL SYSTEM**

BMW VEHICLE: MISSING CLIP ON POWER CABLE CAUSES VARIOUS ELECTRICAL COMPLAINTS. VEHICLE WILL NOT START. INSTRUMENT CLUSTER OR DISPLAYS ARE FLICKERING. REMOTE CONTROL WILL NOT UNLOCK VEHICLE. VARIOUS CONTROL MODULES CANNOT BE ACCESSED USIN

TSB Report for: 2002 BMW X5

Mfg Bulletin #: **SIB-61-13-07** Repl Bulletin #: Bulletin Date: **20071101**
Component: **110000 ELECTRICAL SYSTEM**

BMW VEHICLE: ELECTRONIC MALFUNCTION CC MESSAGE CAUSED BY SHORTED WIRING. THE ELECTRONIC MALFUNCTION CHECK CONTROL MESSAGE MAY BE DISPLAYED; THE SOUNDS SYSTEM EMITS A STATIC NOISE FROM THE SPEAKERS; THE RFK (REAR VIEW CAMERA) DOES NOT PAN;

TSB Report for: 2002 BMW X5

Mfg Bulletin #: **SIB-61-13-07** Repl Bulletin #: Bulletin Date: **20071101**
Component: **114000 ELECTRICAL SYSTEM:WIRING**

BMW VEHICLE: ELECTRONIC MALFUNCTION CC MESSAGE CAUSED BY SHORTED WIRING. THE ELECTRONIC MALFUNCTION CHECK CONTROL MESSAGE MAY BE DISPLAYED; THE SOUNDS SYSTEM EMITS A STATIC NOISE FROM THE SPEAKERS; THE RFK (REAR VIEW CAMERA) DOES NOT PAN;



Kelly Young
Dirigo Software
PO Box 53
Readfield, ME 04355

ds@dirigosoftware.com
www.dirigosoftware.com

TSB Report for: 2002 BMW X5

Mfg Bulletin #: **SIB-61-13-07** Repl Bulletin #:
Component: **353000 EQUIPMENT:ELECTRICAL** Bulletin Date: **20071101**

BMW VEHICLE: ELECTRONIC MALFUNCTION CC MESSAGE CAUSED BY SHORTED WIRING. THE ELECTRONIC MALFUNCTION CHECK CONTROL MESSAGE MAY BE DISPLAYED; THE SOUNDS SYSTEM EMITS A STATIC NOISE FROM THE SPEAKERS; THE RFK (REAR VIEW CAMERA) DOES NOT PAN;

TSB Report for: 2002 BMW X5

Mfg Bulletin #: **SIB-61-13-07** Repl Bulletin #:
Component: **118000 ELECTRICAL SYSTEM: SOFTWARE** Bulletin Date: **20071101**

BMW VEHICLE: ELECTRONIC MALFUNCTION CC MESSAGE CAUSED BY SHORTED WIRING. THE ELECTRONIC MALFUNCTION CHECK CONTROL MESSAGE MAY BE DISPLAYED; THE SOUNDS SYSTEM EMITS A STATIC NOISE FROM THE SPEAKERS; THE RFK (REAR VIEW CAMERA) DOES NOT PAN;

TSB Report for: 2002 BMW X5

Mfg Bulletin #: **SIB-36-05-07** Repl Bulletin #:
Component: **199000 TIRES:PRESSURE MONITORING AND REGULATING SYSTEMS** Bulletin Date: **20071201**

BMW: TIRE WARNING LIGHT ILLUMINATED DUE TO LOW AMBIENT TEMPERATURE. MODEL E90, E91 (3 SERIES); E92, E92 (3 SERIES); E60 (5 SERIES); E60 (M5); E63, E64 (6 SERIES); E63, E64 (M6); E65, E66 (7 SERIES); E70 (X5); E83 (X3); AND E85, E86 (Z4).

TSB Report for: 2002 BMW X5

Mfg Bulletin #: **SIB-16-02-09** Repl Bulletin #:
Component: **072100 FUEL SYSTEM, GASOLINE:DELIVERY:FUEL PUMP** Bulletin Date: **20091201**

BMW VEHICLES: FUEL LEVEL SENSOR REPAIRS. WHERE IT IS NECESSARY TO REPLACE THE RIGHT OR THE LEFT SIDE FUEL LEVEL SENSOR DUE TO A FAILURE, THE ENTIRE PUMP AND HOUSING OR DELIVERY UNIT (SUCTION JET ASSEMBLY) DO NOT NEED TO BE REPLACED AS WEL

TSB Report for: 2002 BMW X5

Mfg Bulletin #: **SI-B61-15-09** Repl Bulletin #:
Component: **110000 ELECTRICAL SYSTEM** Bulletin Date: **20100401**

BMW: VARIOUS ELECTRICAL PROBLEMS. ON THE VEHICLE, VARIOUS ELECTRICAL PROBLEMS ARE POSSIBLE. WARNING LAMPS ILLUMINATED IN THE INSTRUMENT CLUSTER; CHECK CONTROL MESSAGES; SYSTEMS INOPERATIVE; FUSE BLOWN; WIPERS IN DEFAULT MODE (PERMANENTLY O

TSB Report for: 2002 BMW X5

Mfg Bulletin #: **SI-B61-15-09** Repl Bulletin #:
Component: **114000 ELECTRICAL SYSTEM:WIRING** Bulletin Date: **20100401**

BMW: VARIOUS ELECTRICAL PROBLEMS. ON THE VEHICLE, VARIOUS ELECTRICAL PROBLEMS ARE POSSIBLE. WARNING LAMPS ILLUMINATED IN THE INSTRUMENT CLUSTER; CHECK CONTROL MESSAGES; SYSTEMS INOPERATIVE; FUSE BLOWN; WIPERS IN DEFAULT MODE (PERMANENTLY O

TSB Report for: 2002 BMW X5

Mfg Bulletin #: **SIB-32-04-07** Repl Bulletin #:
Component: **015000 STEERING:HYDRAULIC POWER ASSIST SYSTEM** Bulletin Date: **20100601**

BMW: A NEW TECHNICAL PROCESS HAS BEEN CREATED FOR BMW TO IDENTIFY CAUSES OF STEERING COMPLAINTS WITH A WIDE RANGE OF MODELS. *RM

TSB Report for: 2002 BMW X5

Mfg Bulletin #: **SIB-32-04-07** Repl Bulletin #:
Component: **016000 STEERING:ELECTRIC POWER ASSIST SYSTEM** Bulletin Date: **20100601**

BMW: A NEW TECHNICAL PROCESS HAS BEEN CREATED FOR BMW TO IDENTIFY CAUSES OF STEERING COMPLAINTS WITH A WIDE RANGE OF MODELS. *RM

TSB Report for: 2002 BMW X5

Mfg Bulletin #: **SIB-16-03-10** Repl Bulletin #:
Component: **061200 ENGINE AND ENGINE COOLING:ENGINE:DIESEL** Bulletin Date: **20100601**

BMW: WARNING MESSAGE ON ABOUT LOW DIESEL EXHAUST FUEL LEVEL AND THAT THE ENGINE WILL NOT RESTART WITHIN 999 MILES. THE LIGHT COMES ON A FEW THOUSAND MILES EARLIER THAN A RECOMMENDED OIL CHANGE. *RM

TSB Report for: 2002 BMW X5

Mfg Bulletin #: **SIB-16-03-10** Repl Bulletin #:
Component: **080000 FUEL SYSTEM, DIESEL** Bulletin Date: **20100601**

BMW: WARNING MESSAGE ON ABOUT LOW DIESEL EXHAUST FUEL LEVEL AND THAT THE ENGINE WILL NOT RESTART WITHIN 999 MILES. THE LIGHT COMES ON A FEW THOUSAND MILES EARLIER THAN A RECOMMENDED OIL CHANGE. *RM



Kelly Young
Dirigo Software
PO Box 53
Readfield, ME 04355

ds@dirigosoftware.com
www.dirigosoftware.com

TSB Report for: 2002 BMW X5

Mfg Bulletin #: **SIB-13-07-10** Repl Bulletin #:
Bulletin Date: **20100601**
Component: **061000 ENGINE AND ENGINE COOLING:ENGINE**

BMW: THERE IS A ROUGH ENGINE IDLE AND "SERVICE ENGINE SOON LIGHT" WHEN DRIVING DOWNHILL IN HIGH ALTITUDES DURING COLD WEATHER. THERE MAY BE SIX DIFFERENT FAULT CODES. *RM

TSB Report for: 2002 BMW X5

Mfg Bulletin #: **SIB-13-02-10** Repl Bulletin #:
Bulletin Date: **20100601**
Component: **070000 FUEL SYSTEM, GASOLINE**

BMW: IT IS NOW POSSIBLE TO PERFORM A FUEL QUALITY DETECTION TEST ON VEHICLES WITH AN N54 ENGINE. *RM

TSB Report for: 2002 BMW X5

Mfg Bulletin #: **SIB-13-02-10** Repl Bulletin #:
Bulletin Date: **20100601**
Component: **080000 FUEL SYSTEM, DIESEL**

BMW: IT IS NOW POSSIBLE TO PERFORM A FUEL QUALITY DETECTION TEST ON VEHICLES WITH AN N54 ENGINE. *RM

TSB Report for: 2002 BMW X5

Mfg Bulletin #: **SIB-13-06-10** Repl Bulletin #:
Bulletin Date: **20100601**
Component: **061000 ENGINE AND ENGINE COOLING:ENGINE**

BMW: A SERVICE ENGINE SOON LIGHT COMES ON. THE ENGINE WILL ONLY OPERATE TO 1500 RPMS AND LACKS POWER. THERE IS A SOFTWARE APPLICATION ERROR. *RM

TSB Report for: 2002 BMW X5

Mfg Bulletin #: **SIB-13-06-10** Repl Bulletin #:
Bulletin Date: **20100601**
Component: **118000 ELECTRICAL SYSTEM: SOFTWARE**

BMW: A SERVICE ENGINE SOON LIGHT COMES ON. THE ENGINE WILL ONLY OPERATE TO 1500 RPMS AND LACKS POWER. THERE IS A SOFTWARE APPLICATION ERROR. *RM



Kelly Young
Dirigo Software
PO Box 53
Readfield, ME 04355

ds@dirigosoftware.com
www.dirigosoftware.com

TSB Report for: 2002 BMW X5

Mfg Bulletin #: **SIB-11-08-03** Repl Bulletin #: Bulletin Date: **20100701**
Component: **061000 ENGINE AND ENGINE COOLING:ENGINE**

BMW: SIX DIFFERENT MODELS EQUIPPED WITH THE M54 ENGINE COULD HAVE VALVE COVERS BREAK IN COLD WEATHER AND RUIN THE ENGINE. THIS IS DUE TO MOISTURE ACCUMULATION. *RM

TSB Report for: 2002 BMW X5

Mfg Bulletin #: **SIB-63-02-01** Repl Bulletin #: Bulletin Date: **20100801**
Component: **120000 EXTERIOR LIGHTING**

BMW: PROCEDURE FOR DETERMINING AND REPLACING INCANDESCENT AND HALOGEN LIGHT BULBS UNDER WARRANTY. *RM

TSB Report for: 2002 BMW X5

Mfg Bulletin #: **SIB-61-08-10** Repl Bulletin #: Bulletin Date: **20100801**
Component: **110000 ELECTRICAL SYSTEM**

BMW: ELCTRONICALLY DISCONNECTING THE JUNCTION BOX WITHOUT DISCONNECTING THE BATTERY WILL CAUSE DAMAGE TO THE REAR POWER DISTRIBUTION BOX. *RM

TSB Report for: 2002 BMW X5

Mfg Bulletin #: **SIB-61-08-10** Repl Bulletin #: Bulletin Date: **20100801**
Component: **111000 ELECTRICAL SYSTEM:BATTERY**

BMW: ELCTRONICALLY DISCONNECTING THE JUNCTION BOX WITHOUT DISCONNECTING THE BATTERY WILL CAUSE DAMAGE TO THE REAR POWER DISTRIBUTION BOX. *RM

TSB Report for: 2002 BMW X5

Mfg Bulletin #: **SIB-61-08-10** Repl Bulletin #: Bulletin Date: **20100801**
Component: **353000 EQUIPMENT:ELECTRICAL**

BMW: ELCTRONICALLY DISCONNECTING THE JUNCTION BOX WITHOUT DISCONNECTING THE BATTERY WILL CAUSE DAMAGE TO THE REAR POWER DISTRIBUTION BOX. *RM

TSB Report for: 2002 BMW X5

Mfg Bulletin #: **SIB-51-26-10** Repl Bulletin #: Bulletin Date: **20100801**
Component: **114000 ELECTRICAL SYSTEM:WIRING**

BMW: MODEL E70 EQUIPPED WITH AN AUTOMATIC TAILGATE. THE REAR TAILGATE MAY NOT



Kelly Young
Dirigo Software
PO Box 53
Readfield, ME 04355

ds@dirigosoftware.com
www.dirigosoftware.com

OPERATE IN EITHER DIRECTION DUE TO WIRING DAMAGE. *RM

TSB Report for: 2002 BMW X5

Mfg Bulletin #: **SIB-51-26-10** Repl Bulletin #:
Bulletin Date: **20100801**
Component: **162500 STRUCTURE:BODY:TAILGATE**

BMW: MODEL E70 EQUIPPED WITH AN AUTOMATIC TAILGATE. THE REAR TAILGATE MAY NOT OPERATE IN EITHER DIRECTION DUE TO WIRING DAMAGE. *RM

TSB Report for: 2002 BMW X5

Mfg Bulletin #: **SIB-65-36-09** Repl Bulletin #:
Bulletin Date: **20100901**
Component: **114000 ELECTRICAL SYSTEM:WIRING**

BMW: THE AIRBAG WARNING LAMP IS ILLUMINATED DUE TO A SOFTWARE ERROR. *RM

TSB Report for: 2002 BMW X5

Mfg Bulletin #: **SIB-65-36-09** Repl Bulletin #:
Bulletin Date: **20100901**
Component: **140000 AIR BAGS**

BMW: THE AIRBAG WARNING LAMP IS ILLUMINATED DUE TO A SOFTWARE ERROR. *RM

TSB Report for: 2002 BMW X5

Mfg Bulletin #: **SIB-65-36-09** Repl Bulletin #:
Bulletin Date: **20100901**
Component: **118000 ELECTRICAL SYSTEM: SOFTWARE**

BMW: THE AIRBAG WARNING LAMP IS ILLUMINATED DUE TO A SOFTWARE ERROR. *RM

TSB Report for: 2002 BMW X5

Mfg Bulletin #: **SIB-52-08-09** Repl Bulletin #:
Bulletin Date: **20101001**
Component: **221600 SEATS:FRONT ASSEMBLY:POWER ADJUST**

BMW: THERE ARE NOISES WHEN ADJUSTING THE FRONT DRIVER OR PASSENGER SEATES. *RM



Kelly Young
Dirigo Software
PO Box 53
Readfield, ME 04355

ds@dirigosoftware.com
www.dirigosoftware.com

TSB Report for: 2002 BMW X5

Mfg Bulletin #: **SIB-63-10-09** Repl Bulletin #:
Bulletin Date: **20110301**
Component: **125000 EXTERIOR LIGHTING: BRAKE LIGHTS**

BMW: THE BRAKE LIGHT FAILS AND THE BULB HOLDER IS DEFORMED DUE TO HIGH TEMPERATURES AND THE COMPOSITION OF THE HOLDER. *RM

TSB Report for: 2002 BMW X5

Mfg Bulletin #: **SIB-12-15-11** Repl Bulletin #:
Bulletin Date: **20110701**
Component: **061000 ENGINE AND ENGINE COOLING: ENGINE**

BMW: THE SERVICE ENGINE SOON LIGHT IS ON. THERE ARE TROUBLE CODES STORED FOR THE CRANKSHAFT SENSOR. NO DRIVEABILITY ISSUES. *RM

TSB Report for: 2002 BMW X5

Mfg Bulletin #: **SIB-63-04-10** Repl Bulletin #:
Bulletin Date: **20100301**
Component: **120000 EXTERIOR LIGHTING**

BMW: THE BULB HAS FAILED ON THE DAYTIME RUNNING LAMP. *PE

TSB Report for: 2002 BMW X5

Mfg Bulletin #: **SIB-63-04-10** Repl Bulletin #:
Bulletin Date: **20100301**
Component: **121000 EXTERIOR LIGHTING: HEADLIGHTS**

BMW: THE BULB HAS FAILED ON THE DAYTIME RUNNING LAMP. *PE

TSB Report for: 2002 BMW X5

Mfg Bulletin #: **SIB-63-05-11** Repl Bulletin #:
Bulletin Date: **20110901**
Component: **121000 EXTERIOR LIGHTING: HEADLIGHTS**

BMW: ON CERTAIN VEHICLES, THE XENON HEADLAMP OFTEN HAVE NO TROUBLE FOUND WHEN RETURNED AND TESTED THRU WARRANTY PARTS SYSTEM. THE ROOT CAUSE IS NOT POSSIBLE TO BE IDENTIFY. *PE

TSB Report for: 2003 BMW X5

Mfg Bulletin #: **335003** Repl Bulletin #:
Bulletin Date: **20031001**
Component: **106000 POWER TRAIN: AXLE ASSEMBLY**

SERVICE ACTION ON CHECKING REAR AXLE DIFFERENTIAL BOLTS. *TT



Kelly Young
Dirigo Software
PO Box 53
Readfield, ME 04355

ds@dirigosoftware.com
www.dirigosoftware.com

TSB Report for: 2003 BMW X5

Mfg Bulletin #: **1220404** Repl Bulletin #: **1220404** Bulletin Date: **20041022**
Component: **060000 ENGINE AND ENGINE COOLING**

POOR THROTTLE RESPONSE FROM A STOP. THIS SERVICE MEASURE SUPERSEDES SMM1220404 DATED 04/07/2004. *EH

TSB Report for: 2003 BMW X5

Mfg Bulletin #: **2420205** Repl Bulletin #: **240106** Bulletin Date: **20060101**
Component: **103000 POWER TRAIN:AUTOMATIC TRANSMISSION**

HARSH 2-1 DOWNSHIFT. *EH BMW E35. *SC X5 FROM 10/03 UP TO 04/05. *TT

TSB Report for: 2003 BMW X5

Mfg Bulletin #: **5420105** Repl Bulletin #: Bulletin Date: **20050421**
Component: **134000 VISIBILITY:SUN ROOF ASSEMBLY**

PANORAMIC ROOF WON'T CLOSE FROM THE VENT POSITION. *EH

TSB Report for: 2003 BMW X5

Mfg Bulletin #: **510307** Repl Bulletin #: Bulletin Date: **20070201**
Component: **176100 LATCHES/LOCKS/LINKAGES:HOOD:LATCH**

INSTALL HOOD LATCH CORROSION RESISTANT CLIP. *KB

TSB Report for: 2003 BMW X5

Mfg Bulletin #: **SI B61 11 07** Repl Bulletin #: Bulletin Date: **20071101**
Component: **110000 ELECTRICAL SYSTEM**

MISSING CLIP ON POWER CABLE CAUSES VARIOUS ELECTRICAL COMPLAINTS. *NJ

TSB Report for: 2003 BMW X5

Mfg Bulletin #: **SI B 340307** Repl Bulletin #: **SI B34-03-07** Bulletin Date: **20080601**
Component: **114000 ELECTRICAL SYSTEM:WIRING**

DSC WARNING LAMP ILLUMINATED. E70 (X5) VEHICLES PRODUCED UP TO JANUARY 28, 2007. *PE UPDATED 9/10/08. *PE



Kelly Young
Dirigo Software
PO Box 53
Readfield, ME 04355

ds@dirigosoftware.com
www.dirigosoftware.com

TSB Report for: 2003 BMW X5

Mfg Bulletin #: **SI B12 04 08** Repl Bulletin #:
Component: **061000 ENGINE AND ENGINE COOLING:ENGINE** Bulletin Date: **20080401**

E53 WITH M54 AND GM5 - REPROGRAM DME. E53 (X5) WITH M54 ENGINE AND GM5 TRANSMISSION PRODUCED 9/3003 - 10/2004. *PE

TSB Report for: 2003 BMW X5

Mfg Bulletin #: **SI B12 04 08** Repl Bulletin #:
Component: **103000 POWER TRAIN:AUTOMATIC TRANSMISSION** Bulletin Date: **20080401**

E53 WITH M54 AND GM5 - REPROGRAM DME. E53 (X5) WITH M54 ENGINE AND GM5 TRANSMISSION PRODUCED 9/3003 - 10/2004. *PE

TSB Report for: 2003 BMW X5

Mfg Bulletin #: **SI B34 01 08** Repl Bulletin #:
Component: **053000 PARKING BRAKE:INDICATOR LIGHT** Bulletin Date: **20080401**

THE PARKING BRAKE WARNING IS ILLUMINATED AND FAULT CODE 6032 IS STORED. FOR MODEL E70 (X5). *PE

TSB Report for: 2003 BMW X5

Mfg Bulletin #: **SI B37-03-07** Repl Bulletin #:
Component: **020000 SUSPENSION** Bulletin Date: **20080101**

BMW: DYNAMIC DRIVE (ARS) FRONT SWAY BAR REPAIRS. E70 (X5) WITH SPORT PACKAGE OPTION CODE ZSP. *PE

TSB Report for: 2003 BMW X5

Mfg Bulletin #: **SI B63-04-08** Repl Bulletin #:
Component: **121000 EXTERIOR LIGHTING:HEADLIGHTS** Bulletin Date: **20080601**

BMW: HEADLAMP MOISTURE: FAULT DIAGNOSTICS. WATER OR CONDENSATION IN ONE OR BOTH HEADLAMPS. MODELS 5 SERIES, 6 SERIES, 7 SERIES, X5, X6, 1 SERIES, AND 3 SERIES. MODEL YEARS 2000-20008. *PE



Kelly Young
Dirigo Software
PO Box 53
Readfield, ME 04355

ds@dirigosoftware.com
www.dirigosoftware.com

TSB Report for: 2003 BMW X5

Mfg Bulletin #: **SI-B51-30-08** Repl Bulletin #: Bulletin Date: **20081101**
Component: **160000 STRUCTURE**

BMW: WATER LEAK IN THE FRONT RIGHT FOOTWELL AREA CAUSING THE CARPET TO BECOME WET. *PE

TSB Report for: 2003 BMW X5

Mfg Bulletin #: **SI-B51-30-08** Repl Bulletin #: Bulletin Date: **20081101**
Component: **161000 STRUCTURE:FRAME AND MEMBERS**

BMW: WATER LEAK IN THE FRONT RIGHT FOOTWELL AREA CAUSING THE CARPET TO BECOME WET. *PE

TSB Report for: 2003 BMW X5

Mfg Bulletin #: **SI-B51-30-08** Repl Bulletin #: Bulletin Date: **20081101**
Component: **162000 STRUCTURE:BODY**

BMW: WATER LEAK IN THE FRONT RIGHT FOOTWELL AREA CAUSING THE CARPET TO BECOME WET. *PE

TSB Report for: 2003 BMW X5

Mfg Bulletin #: **SI-B51-30-08** Repl Bulletin #: Bulletin Date: **20081101**
Component: **162800 STRUCTURE:BODY:HOOD**

BMW: WATER LEAK IN THE FRONT RIGHT FOOTWELL AREA CAUSING THE CARPET TO BECOME WET. *PE

TSB Report for: 2003 BMW X5

Mfg Bulletin #: **SI-B-11-01-0** Repl Bulletin #: Bulletin Date: **20090301**
Component: **061000 ENGINE AND ENGINE COOLING:ENGINE**

BMW: SMALL NUMBER OF VEHICLES EXPERIENCE PROBLEMS RANGING FROM LEAKING OIL FILLER CAPS, LEAKING OR BROKEN VALVE COVERS, TO COMPLETE ENGINE FAILURE IN EXTREMELY COLD CLIMATE CONDITIONS. MOISTURE ACCUMULATING IN ENGINE CRANKCASE VENTILATION V



Kelly Young
Dirigo Software
PO Box 53
Readfield, ME 04355

ds@dirigosoftware.com
www.dirigosoftware.com

TSB Report for: 2003 BMW X5

Mfg Bulletin #: **SI-B-11-01-0** Repl Bulletin #: Bulletin Date: **20090301**
Component: **061200 ENGINE AND ENGINE COOLING:ENGINE:DIESEL**

BMW: SMALL NUMBER OF VEHICLES EXPERIENCE PROBLEMS RANGING FROM LEAKING OIL FILLER CAPS, LEAKING OR BROKEN VALVE COVERS, TO COMPLETE ENGINE FAILURE IN EXTREMELY COLD CLIMATE CONDITIONS. MOISTURE ACCUMULATING IN ENGINE CRANKCASE VENTILATION V

TSB Report for: 2003 BMW X5

Mfg Bulletin #: **SI-B-11-01-0** Repl Bulletin #: Bulletin Date: **20090301**
Component: **063110 ENGINE AND ENGINE COOLING:EXHAUST SYSTEM:EMISSION CONTROL:CRANKCASE (PCV)**

BMW: SMALL NUMBER OF VEHICLES EXPERIENCE PROBLEMS RANGING FROM LEAKING OIL FILLER CAPS, LEAKING OR BROKEN VALVE COVERS, TO COMPLETE ENGINE FAILURE IN EXTREMELY COLD CLIMATE CONDITIONS. MOISTURE ACCUMULATING IN ENGINE CRANKCASE VENTILATION V

TSB Report for: 2003 BMW X5

Mfg Bulletin #: **SI-B130209** Repl Bulletin #: Bulletin Date: **20090301**
Component: **080000 FUEL SYSTEM, DIESEL**

BMW: DIESEL: DIAGNOSIS FOR LOW PRESSURE FUEL SUPPLY FAULTS. SERVICE ENGINE SOON LAMP IS ILLUMINATED (A FUEL PUMP MALFUNCTION MESSAGE IS DISPLAYED IN THE CC) AND A COMBINATION OF THE FOLLOWING FAULT CODES MAY BE STORED IN THE DDE CONTROL MOD

TSB Report for: 2003 BMW X5

Mfg Bulletin #: **SIB-65-75-06** Repl Bulletin #: **SIB-65-75-06** Bulletin Date: **20110801**
Component: **140000 AIR BAGS**

BMW SERVICE CAMPAIGN: SEE DOCUMENT SEARCH BUTTON FOR OWNER LETTER. THE AIRBAG WARNING LAMP (AWL) IS ILLUMINATED, TOGETHER WITH THE PASSENGER AIRBAG STATUS LAMP (POL). THE PROBLEM MAY BE INTERMITTENT. MICROCRACKS IN THE OC3 SEAT MAT. *PE

TSB Report for: 2003 BMW X5

Mfg Bulletin #: **SI-B31-01-08** Repl Bulletin #: Bulletin Date: **20090901**
Component: **105200 POWER TRAIN:DRIVELINE:CONSTANT VELOCITY JOINT**

BMW: REPLACEMENT OF FRONT OUTER CV JOINT. COMPLAINTS OF CLICKING OR GRINDING NOISES COMING FROM THE FRONT AXLE AREA WHEN MAKING A TURN. THE FRONT OUTER CONSTANT VELOCITY JOINT BOOT IS SPLIT OPEN AND THE JOINT IS ALREADY DAMAGED.



Kelly Young
Dirigo Software
PO Box 53
Readfield, ME 04355

ds@dirigosoftware.com
www.dirigosoftware.com

TSB Report for: 2003 BMW X5

Mfg Bulletin #: **SIB-61-15-09** Repl Bulletin #:
Component: **110000 ELECTRICAL SYSTEM** Bulletin Date: **20100401**

BMW VEHICLES: VARIOUS ELECTRICAL PROBLEMS ARE POSSIBLE ON THE VEHICLE: WARNING LAMPS ILLUMINATED IN THE INSTRUMENT CLUSTER; CHECK CONTROL MESSAGES; SYSTEMS INOPERATIVE; FUSE BLOWN; WIPERS IN DEFAULT MODE (PERMANENTLY ON); AND FAULT CODES F

TSB Report for: 2003 BMW X5

Mfg Bulletin #: **SIB-61-15-09** Repl Bulletin #:
Component: **117000 DIGITAL INSTRUMENT PANEL** Bulletin Date: **20100401**

BMW VEHICLES: VARIOUS ELECTRICAL PROBLEMS ARE POSSIBLE ON THE VEHICLE: WARNING LAMPS ILLUMINATED IN THE INSTRUMENT CLUSTER; CHECK CONTROL MESSAGES; SYSTEMS INOPERATIVE; FUSE BLOWN; WIPERS IN DEFAULT MODE (PERMANENTLY ON); AND FAULT CODES F

TSB Report for: 2003 BMW X5

Mfg Bulletin #: **SIB-34-03-07** Repl Bulletin #:
Component: **110000 ELECTRICAL SYSTEM** Bulletin Date: **20091001**

BMW VEHICLES: DSC WARNING LAMP ILLUMINATED. THE DSC (DYNAMIC STABILITY CONTROL) WARNING LAMP IS ILLUMINATED AND SOME OR ALL OF THE FOLLOWING FAULT CODES ARE STORED: 6E58; 6E04; 53BA; D36F; 55C3; 6ECA; AND THE WIPERS MAY ALSO BE OPERATING

TSB Report for: 2003 BMW X5

Mfg Bulletin #: **SIB-34-03-07** Repl Bulletin #:
Component: **114000 ELECTRICAL SYSTEM:WIRING** Bulletin Date: **20091001**

BMW VEHICLES: DSC WARNING LAMP ILLUMINATED. THE DSC (DYNAMIC STABILITY CONTROL) WARNING LAMP IS ILLUMINATED AND SOME OR ALL OF THE FOLLOWING FAULT CODES ARE STORED: 6E58; 6E04; 53BA; D36F; 55C3; 6ECA; AND THE WIPERS MAY ALSO BE OPERATING

TSB Report for: 2003 BMW X5

Mfg Bulletin #: **SIB-34-03-07** Repl Bulletin #:
Component: **136000 VISIBILITY:WINDSHIELD WIPER/WASHER** Bulletin Date: **20091001**

BMW VEHICLES: DSC WARNING LAMP ILLUMINATED. THE DSC (DYNAMIC STABILITY CONTROL) WARNING LAMP IS ILLUMINATED AND SOME OR ALL OF THE FOLLOWING FAULT CODES ARE STORED: 6E58; 6E04; 53BA; D36F; 55C3; 6ECA; AND THE WIPERS MAY ALSO BE OPERATING



Kelly Young
Dirigo Software
PO Box 53
Readfield, ME 04355

ds@dirigosoftware.com
www.dirigosoftware.com

TSB Report for: 2003 BMW X5

Mfg Bulletin #: **SIB-34-03-07** Repl Bulletin #:
Bulletin Date: **20091001**
Component: **025000 ELECTRONIC STABILITY CONTROL**

BMW VEHICLES: DSC WARNING LAMP ILLUMINATED. THE DSC (DYNAMIC STABILITY CONTROL) WARNING LAMP IS ILLUMINATED AND SOME OR ALL OF THE FOLLOWING FAULT CODES ARE STORED: 6E58; 6E04; 53BA; D36F; 55C3; 6ECA; AND THE WIPERS MAY ALSO BE OPERATING

TSB Report for: 2003 BMW X5

Mfg Bulletin #: **SIB-13-02-09** Repl Bulletin #:
Bulletin Date: **20091001**
Component: **061200 ENGINE AND ENGINE COOLING:ENGINE:DIESEL**

BMW VEHICLES: DIAGNOSIS FOR LOW PRESSURE FUEL SUPPLY FAULTS. THE SERVICE ENGINE SOON LAMP IS ILLUMINATED (A FUEL PUMP MALFUCTION MESSAGE IS DISPLAYED IN THE CC), AND A COMBINATION OF THE FOLLOWING FAULT CODES MAY BE STORED IN THE DDE CONT

TSB Report for: 2003 BMW X5

Mfg Bulletin #: **SIB-12-09-08** Repl Bulletin #:
Bulletin Date: **20080201**
Component: **062200 ENGINE AND ENGINE COOLING:COOLING SYSTEM:FAN**

BMW VEHICLE: DRIVEABILITY COMPLAINTS DUE TO COOLING FAN RELAY FAILURE. THE CUSTOMER MAY COMPLAIN OF INTERMITTENT DRIVEABILITY PROBLEMS, DESCRIBED AS-ENGINE IS LACKING POWER WHEN ACCELERATING UPHILL; TRANSMISSION WILL NOT UPSHIFT UNDER HEA

TSB Report for: 2003 BMW X5

Mfg Bulletin #: **SIB-12-09-08** Repl Bulletin #:
Bulletin Date: **20080201**
Component: **110000 ELECTRICAL SYSTEM**

BMW VEHICLE: DRIVEABILITY COMPLAINTS DUE TO COOLING FAN RELAY FAILURE. THE CUSTOMER MAY COMPLAIN OF INTERMITTENT DRIVEABILITY PROBLEMS, DESCRIBED AS-ENGINE IS LACKING POWER WHEN ACCELERATING UPHILL; TRANSMISSION WILL NOT UPSHIFT UNDER HEA

TSB Report for: 2003 BMW X5

Mfg Bulletin #: **SIB-12-23-07** Repl Bulletin #:
Bulletin Date: **20071101**
Component: **061000 ENGINE AND ENGINE COOLING:ENGINE**

BMW VEHICLE: FC 2EF4 CHARACTERISTIC MAP THERMOSTAT. COMPLAINTS THAT THE SERVICE ENGINE SOON LAMP IS ILLUMINATED. FAULT CODE 2EF4 CHARACTERISTIC MAP THERMOSTAT IS STORED IN DME FAULT MEMORY. DME SOFTWARE CALIBRATION RELATED TO HIGH HEATIN



Kelly Young
Dirigo Software
PO Box 53
Readfield, ME 04355

ds@dirigosoftware.com
www.dirigosoftware.com

TSB Report for: 2003 BMW X5

Mfg Bulletin #: **SIB-12-23-07** Repl Bulletin #: Bulletin Date: **20071101**
Component: **353000 EQUIPMENT:ELECTRICAL**

BMW VEHICLE: FC 2EF4 CHARACTERISTIC MAP THERMOSTAT. COMPLAINTS THAT THE SERVICE ENGINE SOON LAMP IS ILLUMINATED. FAULT CODE 2EF4 CHARACTERISTIC MAP THERMOSTAT IS STORED IN DME FAULT MEMORY. DME SOFTWARE CALIBRATION RELATED TO HIGH HEATIN

TSB Report for: 2003 BMW X5

Mfg Bulletin #: **SIB-12-23-07** Repl Bulletin #: Bulletin Date: **20071101**
Component: **118000 ELECTRICAL SYSTEM: SOFTWARE**

BMW VEHICLE: FC 2EF4 CHARACTERISTIC MAP THERMOSTAT. COMPLAINTS THAT THE SERVICE ENGINE SOON LAMP IS ILLUMINATED. FAULT CODE 2EF4 CHARACTERISTIC MAP THERMOSTAT IS STORED IN DME FAULT MEMORY. DME SOFTWARE CALIBRATION RELATED TO HIGH HEATIN

TSB Report for: 2003 BMW X5

Mfg Bulletin #: **SIB-61-11-07** Repl Bulletin #: Bulletin Date: **20071101**
Component: **110000 ELECTRICAL SYSTEM**

BMW VEHICLE: MISSING CLIP ON POWER CABLE CAUSES VARIOUS ELECTRICAL COMPLAINTS. VEHICLE WILL NOT START. INSTRUMENT CLUSTER OR DISPLAYS ARE FLICKERING. REMOTE CONTROL WILL NOT UNLOCK VEHICLE. VARIOUS CONTROL MODULES CANNOT BE ACCESSED USIN

TSB Report for: 2003 BMW X5

Mfg Bulletin #: **SIB-61-13-07** Repl Bulletin #: Bulletin Date: **20071101**
Component: **110000 ELECTRICAL SYSTEM**

BMW VEHICLE: ELECTRONIC MALFUNCTION CC MESSAGE CAUSED BY SHORTED WIRING. THE ELECTRONIC MALFUNCTION CHECK CONTROL MESSAGE MAY BE DISPLAYED; THE SOUNDS SYSTEM EMITS A STATIC NOISE FROM THE SPEAKERS; THE RFK (REAR VIEW CAMERA) DOES NOT PAN;

TSB Report for: 2003 BMW X5

Mfg Bulletin #: **SIB-61-13-07** Repl Bulletin #: Bulletin Date: **20071101**
Component: **114000 ELECTRICAL SYSTEM:WIRING**

BMW VEHICLE: ELECTRONIC MALFUNCTION CC MESSAGE CAUSED BY SHORTED WIRING. THE ELECTRONIC MALFUNCTION CHECK CONTROL MESSAGE MAY BE DISPLAYED; THE SOUNDS SYSTEM EMITS A STATIC NOISE FROM THE SPEAKERS; THE RFK (REAR VIEW CAMERA) DOES NOT PAN;



Kelly Young
Dirigo Software
PO Box 53
Readfield, ME 04355

ds@dirigosoftware.com
www.dirigosoftware.com

TSB Report for: 2003 BMW X5

Mfg Bulletin #: **SIB-61-13-07** Repl Bulletin #: Bulletin Date: **20071101**
Component: **353000 EQUIPMENT:ELECTRICAL**

BMW VEHICLE: ELECTRONIC MALFUNCTION CC MESSAGE CAUSED BY SHORTED WIRING. THE ELECTRONIC MALFUNCTION CHECK CONTROL MESSAGE MAY BE DISPLAYED; THE SOUNDS SYSTEM EMITS A STATIC NOISE FROM THE SPEAKERS; THE RFK (REAR VIEW CAMERA) DOES NOT PAN;

TSB Report for: 2003 BMW X5

Mfg Bulletin #: **SIB-61-13-07** Repl Bulletin #: Bulletin Date: **20071101**
Component: **118000 ELECTRICAL SYSTEM: SOFTWARE**

BMW VEHICLE: ELECTRONIC MALFUNCTION CC MESSAGE CAUSED BY SHORTED WIRING. THE ELECTRONIC MALFUNCTION CHECK CONTROL MESSAGE MAY BE DISPLAYED; THE SOUNDS SYSTEM EMITS A STATIC NOISE FROM THE SPEAKERS; THE RFK (REAR VIEW CAMERA) DOES NOT PAN;

TSB Report for: 2003 BMW X5

Mfg Bulletin #: **SIB-36-05-07** Repl Bulletin #: Bulletin Date: **20071201**
Component: **199000 TIRES:PRESSURE MONITORING AND REGULATING SYSTEMS**

BMW: TIRE WARNING LIGHT ILLUMINATED DUE TO LOW AMBIENT TEMPERATURE. MODEL E90, E91(3 SERIES);E92, E92 (3 SERIES); E60 (5 SERIES); E60 (M5); E63, E64 (6 SERIES); E63, E64 (M6); E65, E66 (7 SERIES); E70 (X5); E83 (X3); AND E85, E86 (Z4).

TSB Report for: 2003 BMW X5

Mfg Bulletin #: **SIB-16-02-09** Repl Bulletin #: Bulletin Date: **20091201**
Component: **072100 FUEL SYSTEM, GASOLINE:DELIVERY:FUEL PUMP**

BMW VEHICLES: FUEL LEVEL SENSOR REPAIRS. WHERE IT IS NECESSARY TO REPLACE THE RIGHT OR THE LEFT SIDE FUEL LEVEL SENSOR DUE TO A FAILURE, THE ENTIRE PUMP AND HOUSING OR DELIVERY UNIT (SUCTION JET ASSEMBLY) DO NOT NEED TO BE REPLACED AS WEL

TSB Report for: 2003 BMW X5

Mfg Bulletin #: **SI-B61-15-09** Repl Bulletin #: Bulletin Date: **20100401**
Component: **110000 ELECTRICAL SYSTEM**

BMW: VARIOUS ELECTRICAL PROBLEMS. ON THE VEHICLE, VARIOUS ELECTRICAL PROBLEMS ARE POSSIBLE. WARNING LAMPS ILLUMINATED IN THE INSTRUMENT CLUSTER; CHECK CONTROL MESSAGES; SYSTEMS INOPERATIVE; FUSE BLOWN; WIPERS IN DEFAULT MODE (PERMANENTLY O



Kelly Young
Dirigo Software
PO Box 53
Readfield, ME 04355

ds@dirigosoftware.com
www.dirigosoftware.com

TSB Report for: 2003 BMW X5

Mfg Bulletin #: **SI-B61-15-09** Repl Bulletin #:
Component: **114000 ELECTRICAL SYSTEM:WIRING** Bulletin Date: **20100401**

BMW: VARIOUS ELECTRICAL PROBLEMS. ON THE VEHICLE, VARIOUS ELECTRICAL PROBLEMS ARE POSSIBLE. WARNING LAMPS ILLUMINATED IN THE INSTRUMENT CLUSTER; CHECK CONTROL MESSAGES; SYSTEMS INOPERATIVE; FUSE BLOWN; WIPERS IN DEFAULT MODE (PERMANENTLY O

TSB Report for: 2003 BMW X5

Mfg Bulletin #: **SIB-32-04-07** Repl Bulletin #:
Component: **015000 STEERING:HYDRAULIC POWER ASSIST SYSTEM** Bulletin Date: **20100601**

BMW: A NEW TECHNICAL PROCESS HAS BEEN CREATED FOR BMW TO IDENTIFY CAUSES OF STEERING COMPLAINTS WITH A WIDE RANGE OF MODELS. *RM

TSB Report for: 2003 BMW X5

Mfg Bulletin #: **SIB-32-04-07** Repl Bulletin #:
Component: **016000 STEERING:ELECTRIC POWER ASSIST SYSTEM** Bulletin Date: **20100601**

BMW: A NEW TECHNICAL PROCESS HAS BEEN CREATED FOR BMW TO IDENTIFY CAUSES OF STEERING COMPLAINTS WITH A WIDE RANGE OF MODELS. *RM

TSB Report for: 2003 BMW X5

Mfg Bulletin #: **SIB-16-03-10** Repl Bulletin #:
Component: **061200 ENGINE AND ENGINE COOLING:ENGINE:DIESEL** Bulletin Date: **20100601**

BMW: WARNING MESSAGE ON ABOUT LOW DIESEL EXHAUST FUEL LEVEL AND THAT THE ENGINE WILL NOT RESTART WITHIN 999 MILES. THE LIGHT COMES ON A FEW THOUSAND MILES EARLIER THAN A RECOMMENDED OIL CHANGE. *RM

TSB Report for: 2003 BMW X5

Mfg Bulletin #: **SIB-16-03-10** Repl Bulletin #:
Component: **080000 FUEL SYSTEM, DIESEL** Bulletin Date: **20100601**

BMW: WARNING MESSAGE ON ABOUT LOW DIESEL EXHAUST FUEL LEVEL AND THAT THE ENGINE WILL NOT RESTART WITHIN 999 MILES. THE LIGHT COMES ON A FEW THOUSAND MILES EARLIER THAN A RECOMMENDED OIL CHANGE. *RM



Kelly Young
Dirigo Software
PO Box 53
Readfield, ME 04355

ds@dirigosoftware.com
www.dirigosoftware.com

TSB Report for: 2003 BMW X5

Mfg Bulletin #: **SIB-13-07-10** Repl Bulletin #:
Component: **061000 ENGINE AND ENGINE COOLING:ENGINE** Bulletin Date: **20100601**

BMW: THERE IS A ROUGH ENGINE IDLE AND "SERVICE ENGINE SOON LIGHT" WHEN DRIVING DOWNHILL IN HIGH ALTITUDES DURING COLD WEATHER. THERE MAY BE SIX DIFFERENT FAULT CODES. *RM

TSB Report for: 2003 BMW X5

Mfg Bulletin #: **SIB-13-02-10** Repl Bulletin #:
Component: **070000 FUEL SYSTEM, GASOLINE** Bulletin Date: **20100601**

BMW: IT IS NOW POSSIBLE TO PERFORM A FUEL QUALITY DETECTION TEST ON VEHICLES WITH AN N54 ENGINE. *RM

TSB Report for: 2003 BMW X5

Mfg Bulletin #: **SIB-13-02-10** Repl Bulletin #:
Component: **080000 FUEL SYSTEM, DIESEL** Bulletin Date: **20100601**

BMW: IT IS NOW POSSIBLE TO PERFORM A FUEL QUALITY DETECTION TEST ON VEHICLES WITH AN N54 ENGINE. *RM

TSB Report for: 2003 BMW X5

Mfg Bulletin #: **SIB-13-06-10** Repl Bulletin #:
Component: **061000 ENGINE AND ENGINE COOLING:ENGINE** Bulletin Date: **20100601**

BMW: A SERVICE ENGINE SOON LIGHT COMES ON. THE ENGINE WILL ONLY OPERATE TO 1500 RPMS AND LACKS POWER. THERE IS A SOFTWARE APPLICATION ERROR. *RM

TSB Report for: 2003 BMW X5

Mfg Bulletin #: **SIB-13-06-10** Repl Bulletin #:
Component: **118000 ELECTRICAL SYSTEM: SOFTWARE** Bulletin Date: **20100601**

BMW: A SERVICE ENGINE SOON LIGHT COMES ON. THE ENGINE WILL ONLY OPERATE TO 1500 RPMS AND LACKS POWER. THERE IS A SOFTWARE APPLICATION ERROR. *RM



Kelly Young
Dirigo Software
PO Box 53
Readfield, ME 04355

ds@dirigosoftware.com
www.dirigosoftware.com

TSB Report for: 2003 BMW X5

Mfg Bulletin #: **SIB-11-08-03** Repl Bulletin #: Bulletin Date: **20100701**
Component: **061000 ENGINE AND ENGINE COOLING:ENGINE**

BMW: SIX DIFFERENT MODELS EQUIPPED WITH THE M54 ENGINE COULD HAVE VALVE COVERS BREAK IN COLD WEATHER AND RUIN THE ENGINE. THIS IS DUE TO MOISTURE ACCUMULATION. *RM

TSB Report for: 2003 BMW X5

Mfg Bulletin #: **SIB-63-02-01** Repl Bulletin #: Bulletin Date: **20100801**
Component: **120000 EXTERIOR LIGHTING**

BMW: PROCEDURE FOR DETERMINING AND REPLACING INCANDESCENT AND HALOGEN LIGHT BULBS UNDER WARRANTY. *RM

TSB Report for: 2003 BMW X5

Mfg Bulletin #: **SIB-61-08-10** Repl Bulletin #: Bulletin Date: **20100801**
Component: **110000 ELECTRICAL SYSTEM**

BMW: ELCTRONICALLY DISCONNECTING THE JUNCTION BOX WITHOUT DISCONNECTING THE BATTERY WILL CAUSE DAMAGE TO THE REAR POWER DISTRIBUTION BOX. *RM

TSB Report for: 2003 BMW X5

Mfg Bulletin #: **SIB-61-08-10** Repl Bulletin #: Bulletin Date: **20100801**
Component: **111000 ELECTRICAL SYSTEM:BATTERY**

BMW: ELCTRONICALLY DISCONNECTING THE JUNCTION BOX WITHOUT DISCONNECTING THE BATTERY WILL CAUSE DAMAGE TO THE REAR POWER DISTRIBUTION BOX. *RM

TSB Report for: 2003 BMW X5

Mfg Bulletin #: **SIB-61-08-10** Repl Bulletin #: Bulletin Date: **20100801**
Component: **353000 EQUIPMENT:ELECTRICAL**

BMW: ELCTRONICALLY DISCONNECTING THE JUNCTION BOX WITHOUT DISCONNECTING THE BATTERY WILL CAUSE DAMAGE TO THE REAR POWER DISTRIBUTION BOX. *RM

TSB Report for: 2003 BMW X5

Mfg Bulletin #: **SIB-51-26-10** Repl Bulletin #: Bulletin Date: **20100801**
Component: **114000 ELECTRICAL SYSTEM:WIRING**

BMW: MODEL E70 EQUIPPED WITH AN AUTOMATIC TAILGATE. THE REAR TAILGATE MAY NOT



Kelly Young
Dirigo Software
PO Box 53
Readfield, ME 04355

ds@dirigosoftware.com
www.dirigosoftware.com

OPERATE IN EITHER DIRECTION DUE TO WIRING DAMAGE. *RM

TSB Report for: 2003 BMW X5

Mfg Bulletin #: **SIB-51-26-10** Repl Bulletin #: Bulletin Date: **20100801**
Component: **162500 STRUCTURE:BODY:TAILGATE**

BMW: MODEL E70 EQUIPPED WITH AN AUTOMATIC TAILGATE. THE REAR TAILGATE MAY NOT OPERATE IN EITHER DIRECTION DUE TO WIRING DAMAGE. *RM

TSB Report for: 2003 BMW X5

Mfg Bulletin #: **SIB-65-36-09** Repl Bulletin #: Bulletin Date: **20100901**
Component: **114000 ELECTRICAL SYSTEM:WIRING**

BMW: THE AIRBAG WARNING LAMP IS ILLUMINATED DUE TO A SOFTWARE ERROR. *RM

TSB Report for: 2003 BMW X5

Mfg Bulletin #: **SIB-65-36-09** Repl Bulletin #: Bulletin Date: **20100901**
Component: **140000 AIR BAGS**

BMW: THE AIRBAG WARNING LAMP IS ILLUMINATED DUE TO A SOFTWARE ERROR. *RM

TSB Report for: 2003 BMW X5

Mfg Bulletin #: **SIB-65-36-09** Repl Bulletin #: Bulletin Date: **20100901**
Component: **118000 ELECTRICAL SYSTEM: SOFTWARE**

BMW: THE AIRBAG WARNING LAMP IS ILLUMINATED DUE TO A SOFTWARE ERROR. *RM

TSB Report for: 2003 BMW X5

Mfg Bulletin #: **SIB-52-08-09** Repl Bulletin #: Bulletin Date: **20101001**
Component: **221600 SEATS:FRONT ASSEMBLY:POWER ADJUST**

BMW: THERE ARE NOISES WHEN ADJUSTING THE FRONT DRIVER OR PASSENGER SEATES. *RM



Kelly Young
Dirigo Software
PO Box 53
Readfield, ME 04355

ds@dirigosoftware.com
www.dirigosoftware.com

TSB Report for: 2003 BMW X5

Mfg Bulletin #: **SIB-63-10-09** Repl Bulletin #: Bulletin Date: **20110301**
Component: **125000 EXTERIOR LIGHTING: BRAKE LIGHTS**

BMW: THE BRAKE LIGHT FAILS AND THE BULB HOLDER IS DEFORMED DUE TO HIGH TEMPERATURES AND THE COMPOSITION OF THE HOLDER. *RM

TSB Report for: 2003 BMW X5

Mfg Bulletin #: **SIB-12-15-11** Repl Bulletin #: Bulletin Date: **20110701**
Component: **061000 ENGINE AND ENGINE COOLING: ENGINE**

BMW: THE SERVICE ENGINE SOON LIGHT IS ON. THERE ARE TROUBLE CODES STORED FOR THE CRANKSHAFT SENSOR. NO DRIVEABILITY ISSUES. *RM

TSB Report for: 2003 BMW X5

Mfg Bulletin #: **SIB-63-04-10** Repl Bulletin #: Bulletin Date: **20100301**
Component: **120000 EXTERIOR LIGHTING**

BMW: THE BULB HAS FAILED ON THE DAYTIME RUNNING LAMP. *PE

TSB Report for: 2003 BMW X5

Mfg Bulletin #: **SIB-63-04-10** Repl Bulletin #: Bulletin Date: **20100301**
Component: **121000 EXTERIOR LIGHTING: HEADLIGHTS**

BMW: THE BULB HAS FAILED ON THE DAYTIME RUNNING LAMP. *PE

TSB Report for: 2003 BMW X5

Mfg Bulletin #: **SIB-63-05-11** Repl Bulletin #: Bulletin Date: **20110901**
Component: **121000 EXTERIOR LIGHTING: HEADLIGHTS**

BMW: ON CERTAIN VEHICLES, THE XENON HEADLAMP OFTEN HAVE NO TROUBLE FOUND WHEN RETURNED AND TESTED THRU WARRANTY PARTS SYSTEM. THE ROOT CAUSE IS NOT POSSIBLE TO BE IDENTIFY. *PE

TSB Report for: 2004 BMW X5

Mfg Bulletin #: **5120604** Repl Bulletin #: Bulletin Date: **20040618**
Component: **174200 LATCHES/LOCKS/LINKAGES: HATCHBACK/LIFTGATE: LOCK**

UPPER HATCH LIGHTS ARE ON WHEN THE HATCH IS CLOSED; UPPER HATCH OPENS BY ITSELF; UPPER HATCH WILL NOT SOFT CLOSE (SCA FUNCTION INACTIVATE). *TT



Kelly Young
Dirigo Software
PO Box 53
Readfield, ME 04355

ds@dirigosoftware.com
www.dirigosoftware.com

TSB Report for: 2004 BMW X5

Mfg Bulletin #: **1220404** Repl Bulletin #: **1220404** Bulletin Date: **20041022**
Component: **060000 ENGINE AND ENGINE COOLING**

POOR THROTTLE RESPONSE FROM A STOP. THIS SERVICE MEASURE SUPERSEDES SMM1220404 DATED 04/07/2004. *EH

TSB Report for: 2004 BMW X5

Mfg Bulletin #: **07122004** Repl Bulletin #: Bulletin Date: **20040712**
Component: **061000 ENGINE AND ENGINE COOLING:ENGINE**

RETAIL DELIVERY STOP ON 2004 MY 8 & 12 CYLINDER VEHICLES PRODUCED MAY 2004 THROUGH JULY 2004. DUE TO A MANUFACTURING ERROR, THE ENGINE CONTROL MODULE MAIL FAIL. THIS COULD CAUSE THE VEHICLE TO STALL UNEXPECTEDLY OR FAIL TO START AT ALL.

TSB Report for: 2004 BMW X5

Mfg Bulletin #: **07142004** Repl Bulletin #: Bulletin Date: **20040714**
Component: **061000 ENGINE AND ENGINE COOLING:ENGINE**

PART 2. SERVICE ACTION & DELIVERY STOP. *TT

TSB Report for: 2004 BMW X5

Mfg Bulletin #: **1220405** Repl Bulletin #: Bulletin Date: **20050211**
Component: **110000 ELECTRICAL SYSTEM**

CHECK ENGINE LAMP ILLUMINATED INTAKE AND AMBIENT TEMPERATURE FAULTS STORED IN DME. *EH

TSB Report for: 2004 BMW X5

Mfg Bulletin #: **110504** Repl Bulletin #: **110504** Bulletin Date: **20050601**
Component: **060000 ENGINE AND ENGINE COOLING**

M62TU/S62 SECONDARY AIR DIAGNOSTICS AND AIR DELIVERY PASSAGE CLEANING PROCEDURE. *EH UPDATE. *TT

TSB Report for: 2004 BMW X5

Mfg Bulletin #: **2420205** Repl Bulletin #: **240106** Bulletin Date: **20060101**
Component: **103000 POWER TRAIN:AUTOMATIC TRANSMISSION**

HARSH 2-1 DOWNSHIFT. *EH BMW E35. *SC X5 FROM 10/03 UP TO 04/05. *TT



Kelly Young
Dirigo Software
PO Box 53
Readfield, ME 04355

ds@dirigosoftware.com
www.dirigosoftware.com

TSB Report for: 2004 BMW X5

Mfg Bulletin #: **5420105** Repl Bulletin #: Bulletin Date: **20050421**
Component: **134000 VISIBILITY:SUN ROOF ASSEMBLY**

PANORAMIC ROOF WON'T CLOSE FROM THE VENT POSITION. *EH

TSB Report for: 2004 BMW X5

Mfg Bulletin #: **360106** Repl Bulletin #: Bulletin Date: **20060301**
Component: **190000 TIRES**

ERRONEOUS FLAT TIRE WARNING. *TT

TSB Report for: 2004 BMW X5

Mfg Bulletin #: **510307** Repl Bulletin #: Bulletin Date: **20070201**
Component: **176100 LATCHES/LOCKS/LINKAGES:HOOD:LATCH**

INSTALL HOOD LATCH CORROSION RESISTANT CLIP. *KB

TSB Report for: 2004 BMW X5

Mfg Bulletin #: **SI B61 11 07** Repl Bulletin #: Bulletin Date: **20071101**
Component: **110000 ELECTRICAL SYSTEM**

MISSING CLIP ON POWER CABLE CAUSES VARIOUS ELECTRICAL COMPLAINTS. *NJ

TSB Report for: 2004 BMW X5

Mfg Bulletin #: **SI B 340307** Repl Bulletin #: **SI B34-03-07** Bulletin Date: **20080601**
Component: **114000 ELECTRICAL SYSTEM:WIRING**

DSC WARNING LAMP ILLUMINATED. E70 (X5) VEHICLES PRODUCED UP TO JANUARY 28, 2007. *PE
UPDATED 9/10/08. *PE

TSB Report for: 2004 BMW X5

Mfg Bulletin #: **SI B12 08 08** Repl Bulletin #: Bulletin Date: **20080401**
Component: **061000 ENGINE AND ENGINE COOLING:ENGINE**

SERVICE ACTION ON MY 2005 AND 2006 E53 (X5) WITH M54 ENGINE AND GM5 TRANSMISSION
PRODUCED 09/2004-10/2006 - REPROGRAM DME. *PE



Kelly Young
Dirigo Software
PO Box 53
Readfield, ME 04355

ds@dirigosoftware.com
www.dirigosoftware.com

TSB Report for: 2004 BMW X5

Mfg Bulletin #: **SI B12 08 08** Repl Bulletin #:
Bulletin Date: **20080401**
Component: **103000 POWER TRAIN:AUTOMATIC TRANSMISSION**

SERVICE ACTION ON MY 2005 AND 2006 E53 (X5) WITH M54 ENGINE AND GM5 TRANSMISSION
PRODUCED 09/2004-10/2006 - REPROGRAM DME. *PE

TSB Report for: 2004 BMW X5

Mfg Bulletin #: **SI B12 04 08** Repl Bulletin #:
Bulletin Date: **20080401**
Component: **061000 ENGINE AND ENGINE COOLING:ENGINE**

E53 WITH M54 AND GM5 - REPROGRAM DME. E53 (X5) WITH M54 ENGINE AND GM5 TRANSMISSION
PRODUCED 9/3003 - 10/2004. *PE

TSB Report for: 2004 BMW X5

Mfg Bulletin #: **SI B12 04 08** Repl Bulletin #:
Bulletin Date: **20080401**
Component: **103000 POWER TRAIN:AUTOMATIC TRANSMISSION**

E53 WITH M54 AND GM5 - REPROGRAM DME. E53 (X5) WITH M54 ENGINE AND GM5 TRANSMISSION
PRODUCED 9/3003 - 10/2004. *PE

TSB Report for: 2004 BMW X5

Mfg Bulletin #: **SI B34 01 08** Repl Bulletin #:
Bulletin Date: **20080401**
Component: **053000 PARKING BRAKE:INDICATOR LIGHT**

THE PARKING BRAKE WARNING IS ILLUMINATED AND FAULT CODE 6032 IS STORED. FOR MODEL
E70 (X5). *PE

TSB Report for: 2004 BMW X5

Mfg Bulletin #: **SI B37-03-07** Repl Bulletin #:
Bulletin Date: **20080101**
Component: **020000 SUSPENSION**

BMW: DYNAMIC DRIVE (ARS) FRONT SWAY BAR REPAIRS. E70 (X5) WITH SPORT PACKAGE OPTION
CODE ZSP. *PE

TSB Report for: 2004 BMW X5

Mfg Bulletin #: **SI B63-04-08** Repl Bulletin #:
Bulletin Date: **20080601**
Component: **121000 EXTERIOR LIGHTING:HEADLIGHTS**

BMW: HEADLAMP MOISTURE: FAULT DIAGNOSTICS. WATER OR CONDENSATION IN ONE OR BOTH



Kelly Young
Dirigo Software
PO Box 53
Readfield, ME 04355

ds@dirigosoftware.com
www.dirigosoftware.com

HEADLAMPS. MODELS 5 SERIES, 6 SERIES, 7 SERIES, X5, X6, 1 SERIES, AND 3 SERIES. MODEL YEARS 2000-20008. *PE

TSB Report for: 2004 BMW X5

Mfg Bulletin #: **SI-B-12-04-0** Repl Bulletin #: Bulletin Date: **20101101**

Component: **061000 ENGINE AND ENGINE COOLING:ENGINE**

BMW: CHECK ENGINE LAMP ILLUMINATED AND/OR VEHICLE OVERHEATS. MODELS E83, E85, E86, E70, E90, E91, E92, E93, E60 AND E61. *PE UPDATED 5/24/11. *PE

TSB Report for: 2004 BMW X5

Mfg Bulletin #: **SI-B-12-04-0** Repl Bulletin #: Bulletin Date: **20101101**

Component: **110000 ELECTRICAL SYSTEM**

BMW: CHECK ENGINE LAMP ILLUMINATED AND/OR VEHICLE OVERHEATS. MODELS E83, E85, E86, E70, E90, E91, E92, E93, E60 AND E61. *PE UPDATED 5/24/11. *PE

TSB Report for: 2004 BMW X5

Mfg Bulletin #: **SI-B-12-04-0** Repl Bulletin #: Bulletin Date: **20101101**

Component: **117000 DIGITAL INSTRUMENT PANEL**

BMW: CHECK ENGINE LAMP ILLUMINATED AND/OR VEHICLE OVERHEATS. MODELS E83, E85, E86, E70, E90, E91, E92, E93, E60 AND E61. *PE UPDATED 5/24/11. *PE

TSB Report for: 2004 BMW X5

Mfg Bulletin #: **SI-B51-30-08** Repl Bulletin #: Bulletin Date: **20081101**

Component: **160000 STRUCTURE**

BMW: WATER LEAK IN THE FRONT RIGHT FOOTWELL AREA CAUSING THE CARPET TO BECOME WET. *PE

TSB Report for: 2004 BMW X5

Mfg Bulletin #: **SI-B51-30-08** Repl Bulletin #: Bulletin Date: **20081101**

Component: **161000 STRUCTURE:FRAME AND MEMBERS**

BMW: WATER LEAK IN THE FRONT RIGHT FOOTWELL AREA CAUSING THE CARPET TO BECOME



Kelly Young
Dirigo Software
PO Box 53
Readfield, ME 04355

ds@dirigosoftware.com
www.dirigosoftware.com

WET. *PE

TSB Report for: 2004 BMW X5

Mfg Bulletin #: **SI-B51-30-08** Repl Bulletin #:
Component: **162000 STRUCTURE:BODY** Bulletin Date: **20081101**

BMW: WATER LEAK IN THE FRONT RIGHT FOOTWELL AREA CAUSING THE CARPET TO BECOME WET. *PE

TSB Report for: 2004 BMW X5

Mfg Bulletin #: **SI-B51-30-08** Repl Bulletin #:
Component: **162800 STRUCTURE:BODY:HOOD** Bulletin Date: **20081101**

BMW: WATER LEAK IN THE FRONT RIGHT FOOTWELL AREA CAUSING THE CARPET TO BECOME WET. *PE

TSB Report for: 2004 BMW X5

Mfg Bulletin #: **SI-B-11-01-0** Repl Bulletin #:
Component: **061000 ENGINE AND ENGINE COOLING:ENGINE** Bulletin Date: **20090301**

BMW: SMALL NUMBER OF VEHICLES EXPERIENCE PROBLEMS RANGING FROM LEAKING OIL FILLER CAPS, LEAKING OR BROKEN VALVE COVERS, TO COMPLETE ENGINE FAILURE IN EXTREMELY COLD CLIMATE CONDITIONS. MOISTURE ACCUMULATING IN ENGINE CRANKCASE VENTILATION V

TSB Report for: 2004 BMW X5

Mfg Bulletin #: **SI-B-11-01-0** Repl Bulletin #:
Component: **061200 ENGINE AND ENGINE COOLING:ENGINE:DIESEL** Bulletin Date: **20090301**

BMW: SMALL NUMBER OF VEHICLES EXPERIENCE PROBLEMS RANGING FROM LEAKING OIL FILLER CAPS, LEAKING OR BROKEN VALVE COVERS, TO COMPLETE ENGINE FAILURE IN EXTREMELY COLD CLIMATE CONDITIONS. MOISTURE ACCUMULATING IN ENGINE CRANKCASE VENTILATION V

TSB Report for: 2004 BMW X5

Mfg Bulletin #: **SI-B-11-01-0** Repl Bulletin #: Bulletin Date: **20090301**

Component: **063110 ENGINE AND ENGINE COOLING:EXHAUST SYSTEM:EMISSION CONTROL:CRANKCASE (PCV)**

BMW: SMALL NUMBER OF VEHICLES EXPERIENCE PROBLEMS RANGING FROM LEAKING OIL FILLER CAPS, LEAKING OR BROKEN VALVE COVERS, TO COMPLETE ENGINE FAILURE IN EXTREMELY COLD CLIMATE CONDITIONS. MOISTURE ACCUMULATING IN ENGINE CRANKCASE VENTILATION V

TSB Report for: 2004 BMW X5

Mfg Bulletin #: **SI-B130209** Repl Bulletin #: Bulletin Date: **20090301**

Component: **080000 FUEL SYSTEM, DIESEL**

BMW: DIESEL: DIAGNOSIS FOR LOW PRESSURE FUEL SUPPLY FAULTS. SERVICE ENGINE SOON LAMP IS ILLUMINATED (A FUEL PUMP MALFUNCTION MESSAGE IS DISPLAYED IN THE CC) AND A COMBINATION OF THE FOLLOWING FAULT CODES MAY BE STORED IN THE DDE CONTROL MOD

TSB Report for: 2004 BMW X5

Mfg Bulletin #: **SIB-65-75-06** Repl Bulletin #: **SIB-65-75-06** Bulletin Date: **20110801**

Component: **140000 AIR BAGS**

BMW SERVICE CAMPAIGN: SEE DOCUMENT SEARCH BUTTON FOR OWNER LETTER. THE AIRBAG WARNING LAMP (AWL) IS ILLUMINATED, TOGETHER WITH THE PASSENGER AIRBAG STATUS LAMP (POL). THE PROBLEM MAY BE INTERMITTENT. MICROCRACKS IN THE OC3 SEAT MAT. *PE

TSB Report for: 2004 BMW X5

Mfg Bulletin #: **SI-B31-01-08** Repl Bulletin #: Bulletin Date: **20090901**

Component: **105200 POWER TRAIN:DRIVELINE:CONSTANT VELOCITY JOINT**

BMW: REPLACEMENT OF FRONT OUTER CV JOINT. COMPLAINTS OF CLICKING OR GRINDING NOISES COMING FROM THE FRONT AXLE AREA WHEN MAKING A TURN. THE FRONT OUTER CONSTANT VELOCITY JOINT BOOT IS SPLIT OPEN AND THE JOINT IS ALREADY DAMAGED.

TSB Report for: 2004 BMW X5

Mfg Bulletin #: **SIB-61-15-09** Repl Bulletin #: Bulletin Date: **20100401**

Component: **110000 ELECTRICAL SYSTEM**

BMW VEHICLES: VARIOUS ELECTRICAL PROBLEMS ARE POSSIBLE ON THE VEHICLE: WARNING LAMPS ILLUMINATED IN THE INSTRUMENT CLUSTER; CHECK CONTROL MESSAGES; SYSTEMS INOPERATIVE; FUSE BLOWN; WIPERS IN DEFAULT MODE (PERMANENTLY ON); AND FAULT CODES F



Kelly Young
Dirigo Software
PO Box 53
Readfield, ME 04355

ds@dirigosoftware.com
www.dirigosoftware.com

TSB Report for: 2004 BMW X5

Mfg Bulletin #: **SIB-61-15-09** Repl Bulletin #:
Component: **117000 DIGITAL INSTRUMENT PANEL** Bulletin Date: **20100401**

BMW VEHICLES: VARIOUS ELECTRICAL PROBLEMS ARE POSSIBLE ON THE VEHICLE: WARNING LAMPS ILLUMINATED IN THE INSTRUMENT CLUSTER; CHECK CONTROL MESSAGES; SYSTEMS INOPERATIVE; FUSE BLOWN; WIPERS IN DEFAULT MODE (PERMANENTLY ON); AND FAULT CODES F

TSB Report for: 2004 BMW X5

Mfg Bulletin #: **SIB-34-03-07** Repl Bulletin #:
Component: **110000 ELECTRICAL SYSTEM** Bulletin Date: **20091001**

BMW VEHICLES: DSC WARNING LAMP ILLUMINATED. THE DSC (DYNAMIC STABILITY CONTROL) WARNING LAMP IS ILLUMINATED AND SOME OR ALL OF THE FOLLOWING FAULT CODES ARE STORED: 6E58; 6E04; 53BA; D36F; 55C3; 6ECA; AND THE WIPERS MAY ALSO BE OPERATING

TSB Report for: 2004 BMW X5

Mfg Bulletin #: **SIB-34-03-07** Repl Bulletin #:
Component: **114000 ELECTRICAL SYSTEM:WIRING** Bulletin Date: **20091001**

BMW VEHICLES: DSC WARNING LAMP ILLUMINATED. THE DSC (DYNAMIC STABILITY CONTROL) WARNING LAMP IS ILLUMINATED AND SOME OR ALL OF THE FOLLOWING FAULT CODES ARE STORED: 6E58; 6E04; 53BA; D36F; 55C3; 6ECA; AND THE WIPERS MAY ALSO BE OPERATING

TSB Report for: 2004 BMW X5

Mfg Bulletin #: **SIB-34-03-07** Repl Bulletin #:
Component: **136000 VISIBILITY:WINDSHIELD WIPER/WASHER** Bulletin Date: **20091001**

BMW VEHICLES: DSC WARNING LAMP ILLUMINATED. THE DSC (DYNAMIC STABILITY CONTROL) WARNING LAMP IS ILLUMINATED AND SOME OR ALL OF THE FOLLOWING FAULT CODES ARE STORED: 6E58; 6E04; 53BA; D36F; 55C3; 6ECA; AND THE WIPERS MAY ALSO BE OPERATING

TSB Report for: 2004 BMW X5

Mfg Bulletin #: **SIB-34-03-07** Repl Bulletin #:
Component: **025000 ELECTRONIC STABILITY CONTROL** Bulletin Date: **20091001**

BMW VEHICLES: DSC WARNING LAMP ILLUMINATED. THE DSC (DYNAMIC STABILITY CONTROL) WARNING LAMP IS ILLUMINATED AND SOME OR ALL OF THE FOLLOWING FAULT CODES ARE STORED: 6E58; 6E04; 53BA; D36F; 55C3; 6ECA; AND THE WIPERS MAY ALSO BE OPERATING



Kelly Young
Dirigo Software
PO Box 53
Readfield, ME 04355

ds@dirigosoftware.com
www.dirigosoftware.com

TSB Report for: 2004 BMW X5

Mfg Bulletin #: **SIB-13-02-09** Repl Bulletin #: Bulletin Date: **20091001**
Component: **061200 ENGINE AND ENGINE COOLING:ENGINE:DIESEL**

BMW VEHICLES: DIAGNOSIS FOR LOW PRESSURE FUEL SUPPLY FAULTS. THE SERVICE ENGINE SOON LAMP IS ILLUMINATED (A FUEL PUMP MALFUCTION MESSAGE IS DISPLAYED IN THE CC), AND A COMBINATION OF THE FOLLOWING FAULT CODES MAY BE STORED IN THE DDE CONT

TSB Report for: 2004 BMW X5

Mfg Bulletin #: **SIB-12-09-08** Repl Bulletin #: Bulletin Date: **20080201**
Component: **062200 ENGINE AND ENGINE COOLING:COOLING SYSTEM:FAN**

BMW VEHICLE: DRIVEABILITY COMPLAINTS DUE TO COOLING FAN RELAY FAILURE. THE CUSTOMER MAY COMPLAIN OF INTERMITTENT DRIVEABILITY PROBLEMS, DESCRIBED AS-ENGINE IS LACKING POWER WHEN ACCELERATING UPHILL; TRANSMISSION WILL NOT UPSHIFT UNDER HEA

TSB Report for: 2004 BMW X5

Mfg Bulletin #: **SIB-12-09-08** Repl Bulletin #: Bulletin Date: **20080201**
Component: **110000 ELECTRICAL SYSTEM**

BMW VEHICLE: DRIVEABILITY COMPLAINTS DUE TO COOLING FAN RELAY FAILURE. THE CUSTOMER MAY COMPLAIN OF INTERMITTENT DRIVEABILITY PROBLEMS, DESCRIBED AS-ENGINE IS LACKING POWER WHEN ACCELERATING UPHILL; TRANSMISSION WILL NOT UPSHIFT UNDER HEA

TSB Report for: 2004 BMW X5

Mfg Bulletin #: **SIB-12-23-07** Repl Bulletin #: Bulletin Date: **20071101**
Component: **061000 ENGINE AND ENGINE COOLING:ENGINE**

BMW VEHICLE: FC 2EF4 CHARACTERISTIC MAP THERMOSTAT. COMPLAINTS THAT THE SERVICE ENGINE SOON LAMP IS ILLUMINATED. FAULT CODE 2EF4 CHARACTERISTIC MAP THERMOSTAT IS STORED IN DME FAULT MEMORY. DME SOFTWARE CALIBRATION RELATED TO HIGH HEATIN

TSB Report for: 2004 BMW X5

Mfg Bulletin #: **SIB-12-23-07** Repl Bulletin #: Bulletin Date: **20071101**
Component: **353000 EQUIPMENT:ELECTRICAL**

BMW VEHICLE: FC 2EF4 CHARACTERISTIC MAP THERMOSTAT. COMPLAINTS THAT THE SERVICE ENGINE SOON LAMP IS ILLUMINATED. FAULT CODE 2EF4 CHARACTERISTIC MAP THERMOSTAT IS STORED IN DME FAULT MEMORY. DME SOFTWARE CALIBRATION RELATED TO HIGH HEATIN



Kelly Young
Dirigo Software
PO Box 53
Readfield, ME 04355

ds@dirigosoftware.com
www.dirigosoftware.com

TSB Report for: 2004 BMW X5

Mfg Bulletin #: **SIB-12-23-07** Repl Bulletin #:
Component: **118000 ELECTRICAL SYSTEM: SOFTWARE** Bulletin Date: **20071101**

BMW VEHICLE: FC 2EF4 CHARACTERISTIC MAP THERMOSTAT. COMPLAINTS THAT THE SERVICE ENGINE SOON LAMP IS ILLUMINATED. FAULT CODE 2EF4 CHARACTERISTIC MAP THERMOSTAT IS STORED IN DME FAULT MEMORY. DME SOFTWARE CALIBRATION RELATED TO HIGH HEATIN

TSB Report for: 2004 BMW X5

Mfg Bulletin #: **SIB-61-11-07** Repl Bulletin #:
Component: **110000 ELECTRICAL SYSTEM** Bulletin Date: **20071101**

BMW VEHICLE: MISSING CLIP ON POWER CABLE CAUSES VARIOUS ELECTRICAL COMPLAINTS. VEHICLE WILL NOT START. INSTRUMENT CLUSTER OR DISPLAYS ARE FLICKERING. REMOTE CONTROL WILL NOT UNLOCK VEHICLE. VARIOUS CONTROL MODULES CANNOT BE ACCESSED USIN

TSB Report for: 2004 BMW X5

Mfg Bulletin #: **SIB-61-13-07** Repl Bulletin #:
Component: **110000 ELECTRICAL SYSTEM** Bulletin Date: **20071101**

BMW VEHICLE: ELECTRONIC MALFUNCTION CC MESSAGE CAUSED BY SHORTED WIRING. THE ELECTRONIC MALFUNCTION CHECK CONTROL MESSAGE MAY BE DISPLAYED; THE SOUNDS SYSTEM EMITS A STATIC NOISE FROM THE SPEAKERS; THE RFK (REAR VIEW CAMERA) DOES NOT PAN;

TSB Report for: 2004 BMW X5

Mfg Bulletin #: **SIB-61-13-07** Repl Bulletin #:
Component: **114000 ELECTRICAL SYSTEM:WIRING** Bulletin Date: **20071101**

BMW VEHICLE: ELECTRONIC MALFUNCTION CC MESSAGE CAUSED BY SHORTED WIRING. THE ELECTRONIC MALFUNCTION CHECK CONTROL MESSAGE MAY BE DISPLAYED; THE SOUNDS SYSTEM EMITS A STATIC NOISE FROM THE SPEAKERS; THE RFK (REAR VIEW CAMERA) DOES NOT PAN;

TSB Report for: 2004 BMW X5

Mfg Bulletin #: **SIB-61-13-07** Repl Bulletin #:
Component: **353000 EQUIPMENT:ELECTRICAL** Bulletin Date: **20071101**

BMW VEHICLE: ELECTRONIC MALFUNCTION CC MESSAGE CAUSED BY SHORTED WIRING. THE ELECTRONIC MALFUNCTION CHECK CONTROL MESSAGE MAY BE DISPLAYED; THE SOUNDS SYSTEM EMITS A STATIC NOISE FROM THE SPEAKERS; THE RFK (REAR VIEW CAMERA) DOES NOT



Kelly Young
Dirigo Software
PO Box 53
Readfield, ME 04355

ds@dirigosoftware.com
www.dirigosoftware.com

PAN;

TSB Report for: 2004 BMW X5

Mfg Bulletin #: **SIB-61-13-07** Repl Bulletin #:
Bulletin Date: **20071101**
Component: **118000 ELECTRICAL SYSTEM: SOFTWARE**

BMW VEHICLE: ELECTRONIC MALFUNCTION CC MESSAGE CAUSED BY SHORTED WIRING. THE ELECTRONIC MALFUNCTION CHECK CONTROL MESSAGE MAY BE DISPLAYED; THE SOUNDS SYSTEM EMITS A STATIC NOISE FROM THE SPEAKERS; THE RFK (REAR VIEW CAMERA) DOES NOT PAN;

TSB Report for: 2004 BMW X5

Mfg Bulletin #: **SIB-36-05-07** Repl Bulletin #:
Bulletin Date: **20071201**
Component: **199000 TIRES:PRESSURE MONITORING AND REGULATING SYSTEMS**

BMW: TIRE WARNING LIGHT ILLUMINATED DUE TO LOW AMBIENT TEMPERATURE. MODEL E90, E91(3 SERIES);E92, E92 (3 SERIES); E60 (5 SERIES); E60 (M5); E63, E64 (6 SERIES); E63, E64 (M6); E65, E66 (7 SERIES); E70 (X5); E83 (X3); AND E85, E86 (Z4).

TSB Report for: 2004 BMW X5

Mfg Bulletin #: **SIB-16-02-09** Repl Bulletin #:
Bulletin Date: **20091201**
Component: **072100 FUEL SYSTEM, GASOLINE:DELIVERY:FUEL PUMP**

BMW VEHICLES: FUEL LEVEL SENSOR REPAIRS. WHERE IT IS NECESSARY TO REPLACE THE RIGHT OR THE LEFT SIDE FUEL LEVEL SENSOR DUE TO A FAILURE, THE ENTIRE PUMP AND HOUSING OR DELIVERY UNIT (SUCTION JET ASSEMBLY) DO NOT NEED TO BE REPLACED AS WEL

TSB Report for: 2004 BMW X5

Mfg Bulletin #: **SI-B61-15-09** Repl Bulletin #:
Bulletin Date: **20100401**
Component: **110000 ELECTRICAL SYSTEM**

BMW: VARIOUS ELECTRICAL PROBLEMS. ON THE VEHICLE, VARIOUS ELECTRICAL PROBLEMS ARE POSSIBLE. WARNING LAMPS ILLUMINATED IN THE INSTRUMENT CLUSTER; CHECK CONTROL MESSAGES; SYSTEMS INOPERATIVE; FUSE BLOWN; WIPERS IN DEFAULT MODE (PERMANENTLY O



Kelly Young
Dirigo Software
PO Box 53
Readfield, ME 04355

ds@dirigosoftware.com
www.dirigosoftware.com

TSB Report for: 2004 BMW X5

Mfg Bulletin #: **SI-B61-15-09** Repl Bulletin #: Bulletin Date: **20100401**
Component: **114000 ELECTRICAL SYSTEM:WIRING**

BMW: VARIOUS ELECTRICAL PROBLEMS. ON THE VEHICLE, VARIOUS ELECTRICAL PROBLEMS ARE POSSIBLE. WARNING LAMPS ILLUMINATED IN THE INSTRUMENT CLUSTER; CHECK CONTROL MESSAGES; SYSTEMS INOPERATIVE; FUSE BLOWN; WIPERS IN DEFAULT MODE (PERMANENTLY O

TSB Report for: 2004 BMW X5

Mfg Bulletin #: **SIB-32-04-07** Repl Bulletin #: Bulletin Date: **20100601**
Component: **015000 STEERING:HYDRAULIC POWER ASSIST SYSTEM**

BMW: A NEW TECHNICAL PROCESS HAS BEEN CREATED FOR BMW TO IDENTIFY CAUSES OF STEERING COMPLAINTS WITH A WIDE RANGE OF MODELS. *RM

TSB Report for: 2004 BMW X5

Mfg Bulletin #: **SIB-32-04-07** Repl Bulletin #: Bulletin Date: **20100601**
Component: **016000 STEERING:ELECTRIC POWER ASSIST SYSTEM**

BMW: A NEW TECHNICAL PROCESS HAS BEEN CREATED FOR BMW TO IDENTIFY CAUSES OF STEERING COMPLAINTS WITH A WIDE RANGE OF MODELS. *RM

TSB Report for: 2004 BMW X5

Mfg Bulletin #: **SIB-16-03-10** Repl Bulletin #: Bulletin Date: **20100601**
Component: **061200 ENGINE AND ENGINE COOLING:ENGINE:DIESEL**

BMW: WARNING MESSAGE ON ABOUT LOW DIESEL EXHAUST FUEL LEVEL AND THAT THE ENGINE WILL NOT RESTART WITHIN 999 MILES. THE LIGHT COMES ON A FEW THOUSAND MILES EARLIER THAN A RECOMMENDED OIL CHANGE. *RM

TSB Report for: 2004 BMW X5

Mfg Bulletin #: **SIB-16-03-10** Repl Bulletin #: Bulletin Date: **20100601**
Component: **080000 FUEL SYSTEM, DIESEL**

BMW: WARNING MESSAGE ON ABOUT LOW DIESEL EXHAUST FUEL LEVEL AND THAT THE ENGINE WILL NOT RESTART WITHIN 999 MILES. THE LIGHT COMES ON A FEW THOUSAND MILES EARLIER THAN A RECOMMENDED OIL CHANGE. *RM



Kelly Young
Dirigo Software
PO Box 53
Readfield, ME 04355

ds@dirigosoftware.com
www.dirigosoftware.com

TSB Report for: 2004 BMW X5

Mfg Bulletin #: **SIB-13-07-10** Repl Bulletin #:
Component: **061000 ENGINE AND ENGINE COOLING:ENGINE** Bulletin Date: **20100601**

BMW: THERE IS A ROUGH ENGINE IDLE AND "SERVICE ENGINE SOON LIGHT" WHEN DRIVING DOWNHILL IN HIGH ALTITUDES DURING COLD WEATHER. THERE MAY BE SIX DIFFERENT FAULT CODES. *RM

TSB Report for: 2004 BMW X5

Mfg Bulletin #: **SIB-13-02-10** Repl Bulletin #:
Component: **070000 FUEL SYSTEM, GASOLINE** Bulletin Date: **20100601**

BMW: IT IS NOW POSSIBLE TO PERFORM A FUEL QUALITY DETECTION TEST ON VEHICLES WITH AN N54 ENGINE. *RM

TSB Report for: 2004 BMW X5

Mfg Bulletin #: **SIB-13-02-10** Repl Bulletin #:
Component: **080000 FUEL SYSTEM, DIESEL** Bulletin Date: **20100601**

BMW: IT IS NOW POSSIBLE TO PERFORM A FUEL QUALITY DETECTION TEST ON VEHICLES WITH AN N54 ENGINE. *RM

TSB Report for: 2004 BMW X5

Mfg Bulletin #: **SIB-13-06-10** Repl Bulletin #:
Component: **061000 ENGINE AND ENGINE COOLING:ENGINE** Bulletin Date: **20100601**

BMW: A SERVICE ENGINE SOON LIGHT COMES ON. THE ENGINE WILL ONLY OPERATE TO 1500 RPMS AND LACKS POWER. THERE IS A SOFTWARE APPLICATION ERROR. *RM

TSB Report for: 2004 BMW X5

Mfg Bulletin #: **SIB-13-06-10** Repl Bulletin #:
Component: **118000 ELECTRICAL SYSTEM: SOFTWARE** Bulletin Date: **20100601**

BMW: A SERVICE ENGINE SOON LIGHT COMES ON. THE ENGINE WILL ONLY OPERATE TO 1500 RPMS AND LACKS POWER. THERE IS A SOFTWARE APPLICATION ERROR. *RM



Kelly Young
Dirigo Software
PO Box 53
Readfield, ME 04355

ds@dirigosoftware.com
www.dirigosoftware.com

TSB Report for: 2004 BMW X5

Mfg Bulletin #: **SIB-11-08-03** Repl Bulletin #: Bulletin Date: **20100701**
Component: **061000 ENGINE AND ENGINE COOLING:ENGINE**

BMW: SIX DIFFERENT MODELS EQUIPPED WITH THE M54 ENGINE COULD HAVE VALVE COVERS BREAK IN COLD WEATHER AND RUIN THE ENGINE. THIS IS DUE TO MOISTURE ACCUMULATION. *RM

TSB Report for: 2004 BMW X5

Mfg Bulletin #: **SIB-63-02-01** Repl Bulletin #: Bulletin Date: **20100801**
Component: **120000 EXTERIOR LIGHTING**

BMW: PROCEDURE FOR DETERMINING AND REPLACING INCANDESCENT AND HALOGEN LIGHT BULBS UNDER WARRANTY. *RM

TSB Report for: 2004 BMW X5

Mfg Bulletin #: **SIB-61-08-10** Repl Bulletin #: Bulletin Date: **20100801**
Component: **110000 ELECTRICAL SYSTEM**

BMW: ELCTRONICALLY DISCONNECTING THE JUNCTION BOX WITHOUT DISCONNECTING THE BATTERY WILL CAUSE DAMAGE TO THE REAR POWER DISTRIBUTION BOX. *RM

TSB Report for: 2004 BMW X5

Mfg Bulletin #: **SIB-61-08-10** Repl Bulletin #: Bulletin Date: **20100801**
Component: **111000 ELECTRICAL SYSTEM:BATTERY**

BMW: ELCTRONICALLY DISCONNECTING THE JUNCTION BOX WITHOUT DISCONNECTING THE BATTERY WILL CAUSE DAMAGE TO THE REAR POWER DISTRIBUTION BOX. *RM

TSB Report for: 2004 BMW X5

Mfg Bulletin #: **SIB-61-08-10** Repl Bulletin #: Bulletin Date: **20100801**
Component: **353000 EQUIPMENT:ELECTRICAL**

BMW: ELCTRONICALLY DISCONNECTING THE JUNCTION BOX WITHOUT DISCONNECTING THE BATTERY WILL CAUSE DAMAGE TO THE REAR POWER DISTRIBUTION BOX. *RM

TSB Report for: 2004 BMW X5

Mfg Bulletin #: **SIB-51-26-10** Repl Bulletin #: Bulletin Date: **20100801**
Component: **114000 ELECTRICAL SYSTEM:WIRING**

BMW: MODEL E70 EQUIPPED WITH AN AUTOMATIC TAILGATE. THE REAR TAILGATE MAY NOT



Kelly Young
Dirigo Software
PO Box 53
Readfield, ME 04355

ds@dirigosoftware.com
www.dirigosoftware.com

OPERATE IN EITHER DIRECTION DUE TO WIRING DAMAGE. *RM

TSB Report for: 2004 BMW X5

Mfg Bulletin #: **SIB-51-26-10** Repl Bulletin #:
Bulletin Date: **20100801**
Component: **162500 STRUCTURE:BODY:TAILGATE**

BMW: MODEL E70 EQUIPPED WITH AN AUTOMATIC TAILGATE. THE REAR TAILGATE MAY NOT OPERATE IN EITHER DIRECTION DUE TO WIRING DAMAGE. *RM

TSB Report for: 2004 BMW X5

Mfg Bulletin #: **SIB-65-36-09** Repl Bulletin #:
Bulletin Date: **20100901**
Component: **114000 ELECTRICAL SYSTEM:WIRING**

BMW: THE AIRBAG WARNING LAMP IS ILLUMINATED DUE TO A SOFTWARE ERROR. *RM

TSB Report for: 2004 BMW X5

Mfg Bulletin #: **SIB-65-36-09** Repl Bulletin #:
Bulletin Date: **20100901**
Component: **140000 AIR BAGS**

BMW: THE AIRBAG WARNING LAMP IS ILLUMINATED DUE TO A SOFTWARE ERROR. *RM

TSB Report for: 2004 BMW X5

Mfg Bulletin #: **SIB-65-36-09** Repl Bulletin #:
Bulletin Date: **20100901**
Component: **118000 ELECTRICAL SYSTEM: SOFTWARE**

BMW: THE AIRBAG WARNING LAMP IS ILLUMINATED DUE TO A SOFTWARE ERROR. *RM

TSB Report for: 2004 BMW X5

Mfg Bulletin #: **SIB-52-08-09** Repl Bulletin #:
Bulletin Date: **20101001**
Component: **221600 SEATS:FRONT ASSEMBLY:POWER ADJUST**

BMW: THERE ARE NOISES WHEN ADJUSTING THE FRONT DRIVER OR PASSENGER SEATES. *RM

TSB Report for: 2004 BMW X5

Mfg Bulletin #: **SIB-63-10-09** Repl Bulletin #: Bulletin Date: **20110301**
Component: **125000 EXTERIOR LIGHTING: BRAKE LIGHTS**

BMW: THE BRAKE LIGHT FAILS AND THE BULB HOLDER IS DEFORMED DUE TO HIGH TEMPERATURES AND THE COMPOSITION OF THE HOLDER. *RM

TSB Report for: 2004 BMW X5

Mfg Bulletin #: **SIB-12-15-11** Repl Bulletin #: Bulletin Date: **20110701**
Component: **061000 ENGINE AND ENGINE COOLING: ENGINE**

BMW: THE SERVICE ENGINE SOON LIGHT IS ON. THERE ARE TROUBLE CODES STORED FOR THE CRANKSHAFT SENSOR. NO DRIVEABILITY ISSUES. *RM

TSB Report for: 2004 BMW X5

Mfg Bulletin #: **SIB-63-04-10** Repl Bulletin #: Bulletin Date: **20100301**
Component: **120000 EXTERIOR LIGHTING**

BMW: THE BULB HAS FAILED ON THE DAYTIME RUNNING LAMP. *PE

TSB Report for: 2004 BMW X5

Mfg Bulletin #: **SIB-63-04-10** Repl Bulletin #: Bulletin Date: **20100301**
Component: **121000 EXTERIOR LIGHTING: HEADLIGHTS**

BMW: THE BULB HAS FAILED ON THE DAYTIME RUNNING LAMP. *PE

TSB Report for: 2004 BMW X5

Mfg Bulletin #: **SIB-63-05-11** Repl Bulletin #: Bulletin Date: **20110901**
Component: **121000 EXTERIOR LIGHTING: HEADLIGHTS**

BMW: ON CERTAIN VEHICLES, THE XENON HEADLAMP OFTEN HAVE NO TROUBLE FOUND WHEN RETURNED AND TESTED THRU WARRANTY PARTS SYSTEM. THE ROOT CAUSE IS NOT POSSIBLE TO BE IDENTIFY. *PE

TSB Report for: 2005 BMW X5

Mfg Bulletin #: **7220005** Repl Bulletin #: **720206** Bulletin Date: **20060101**
Component: **141100 AIR BAGS: FRONTAL: SENSOR/CONTROL MODULE**

AIRBAG WARNING LIGHT IS ILLUMINATED, AND FAULT CODE 71 (SEAT OCCUPANCY DETECTOR) IS STORED IN MRS4RD. BMW E83 (X3). MODEL YEAR UNKNOWN. *TT



Kelly Young
Dirigo Software
PO Box 53
Readfield, ME 04355

ds@dirigosoftware.com
www.dirigosoftware.com

TSB Report for: 2005 BMW X5

Mfg Bulletin #: **2420205** Repl Bulletin #: **240106** Bulletin Date: **20060101**
Component: **103000 POWER TRAIN:AUTOMATIC TRANSMISSION**

HARSH 2-1 DOWNSHIFT. *EH BMW E35. *SC X5 FROM 10/03 UP TO 04/05. *TT

TSB Report for: 2005 BMW X5

Mfg Bulletin #: **360406** Repl Bulletin #: Bulletin Date: **20060401**
Component: **190000 TIRES**

NITROGEN INFLATED TIRES. *TT

TSB Report for: 2005 BMW X5

Mfg Bulletin #: **130206** Repl Bulletin #: Bulletin Date: **20060401**
Component: **070000 FUEL SYSTEM, GASOLINE**

TOP TIER DETERGENT GASOLINE IN BMW VEHICLES. *TT

TSB Report for: 2005 BMW X5

Mfg Bulletin #: **360106** Repl Bulletin #: Bulletin Date: **20060301**
Component: **190000 TIRES**

ERRONEOUS FLAT TIRE WARNING. *TT

TSB Report for: 2005 BMW X5

Mfg Bulletin #: **515001** Repl Bulletin #: **510206** Bulletin Date: **20060301**
Component: **162700 STRUCTURE:BODY:TRUNK LID**

TRUNK LID GRIP WATER INGRESS - INTERMITTENT TRUNK LID (LIFT GATE OR REAR HATCH) UNLOCKING OPERATIONS. *TT

TSB Report for: 2005 BMW X5

Mfg Bulletin #: **410206** Repl Bulletin #: Bulletin Date: **20060301**
Component: **162000 STRUCTURE:BODY**

WATER INGRESS - TRUNK FLOOR AREA. *TT



Kelly Young
Dirigo Software
PO Box 53
Readfield, ME 04355

ds@dirigosoftware.com
www.dirigosoftware.com

TSB Report for: 2005 BMW X5

Mfg Bulletin #: **510307** Repl Bulletin #: Bulletin Date: **20070201**
Component: **176100 LATCHES/LOCKS/LINKAGES:HOOD:LATCH**

INSTALL HOOD LATCH CORROSION RESISTANT CLIP. *KB

TSB Report for: 2005 BMW X5

Mfg Bulletin #: **SI B61 11 07** Repl Bulletin #: Bulletin Date: **20071101**
Component: **110000 ELECTRICAL SYSTEM**

MISSING CLIP ON POWER CABLE CAUSES VARIOUS ELECTRICAL COMPLAINTS. *NJ

TSB Report for: 2005 BMW X5

Mfg Bulletin #: **SI B 340307** Repl Bulletin #: **SI B34-03-07** Bulletin Date: **20080601**
Component: **114000 ELECTRICAL SYSTEM:WIRING**

DSC WARNING LAMP ILLUMINATED. E70 (X5) VEHICLES PRODUCED UP TO JANUARY 28, 2007. *PE
UPDATED 9/10/08. *PE

TSB Report for: 2005 BMW X5

Mfg Bulletin #: **SI B12 08 08** Repl Bulletin #: Bulletin Date: **20080401**
Component: **061000 ENGINE AND ENGINE COOLING:ENGINE**

SERVICE ACTION ON MY 2005 AND 2006 E53 (X5) WITH M54 ENGINE AND GM5 TRANSMISSION
PRODUCED 09/2004-10/2006 - REPROGRAM DME. *PE

TSB Report for: 2005 BMW X5

Mfg Bulletin #: **SI B12 08 08** Repl Bulletin #: Bulletin Date: **20080401**
Component: **103000 POWER TRAIN:AUTOMATIC TRANSMISSION**

SERVICE ACTION ON MY 2005 AND 2006 E53 (X5) WITH M54 ENGINE AND GM5 TRANSMISSION
PRODUCED 09/2004-10/2006 - REPROGRAM DME. *PE

TSB Report for: 2005 BMW X5

Mfg Bulletin #: **SI B34 01 08** Repl Bulletin #: Bulletin Date: **20080401**
Component: **053000 PARKING BRAKE:INDICATOR LIGHT**

THE PARKING BRAKE WARNING IS ILLUMINATED AND FAULT CODE 6032 IS STORED. FOR MODEL
E70 (X5). *PE



Kelly Young
Dirigo Software
PO Box 53
Readfield, ME 04355

ds@dirigosoftware.com
www.dirigosoftware.com

TSB Report for: 2005 BMW X5

Mfg Bulletin #: **SI B37-03-07** Repl Bulletin #:
Component: **020000 SUSPENSION** Bulletin Date: **20080101**

BMW: DYNAMIC DRIVE (ARS) FRONT SWAY BAR REPAIRS. E70 (X5) WITH SPORT PACKAGE OPTION CODE ZSP. *PE

TSB Report for: 2005 BMW X5

Mfg Bulletin #: **SI B63-04-08** Repl Bulletin #:
Component: **121000 EXTERIOR LIGHTING:HEADLIGHTS** Bulletin Date: **20080601**

BMW: HEADLAMP MOISTURE: FAULT DIAGNOSTICS. WATER OR CONDENSATION IN ONE OR BOTH HEADLAMPS. MODELS 5 SERIES, 6 SERIES, 7 SERIES, X5, X6, 1 SERIES, AND 3 SERIES. MODEL YEARS 2000-20008. *PE

TSB Report for: 2005 BMW X5

Mfg Bulletin #: **SI-B-12-04-0** Repl Bulletin #:
Component: **061000 ENGINE AND ENGINE COOLING:ENGINE** Bulletin Date: **20101101**

BMW: CHECK ENGINE LAMP ILLUMINATED AND/OR VEHICLE OVERHEATS. MODELS E83, E85, E86, E70, E90, E91, E92, E93, E60 AND E61. *PE UPDATED 5/24/11. *PE

TSB Report for: 2005 BMW X5

Mfg Bulletin #: **SI-B-12-04-0** Repl Bulletin #:
Component: **110000 ELECTRICAL SYSTEM** Bulletin Date: **20101101**

BMW: CHECK ENGINE LAMP ILLUMINATED AND/OR VEHICLE OVERHEATS. MODELS E83, E85, E86, E70, E90, E91, E92, E93, E60 AND E61. *PE UPDATED 5/24/11. *PE

TSB Report for: 2005 BMW X5

Mfg Bulletin #: **SI-B-12-04-0** Repl Bulletin #:
Component: **117000 DIGITAL INSTRUMENT PANEL** Bulletin Date: **20101101**

BMW: CHECK ENGINE LAMP ILLUMINATED AND/OR VEHICLE OVERHEATS. MODELS E83, E85, E86, E70, E90, E91, E92, E93, E60 AND E61. *PE UPDATED 5/24/11. *PE



Dirigo Software

Accident Reconstruction Software for the Professional



Kelly Young
Dirigo Software
PO Box 53
Readfield, ME 04355

ds@dirigosoftware.com
www.dirigosoftware.com

TSB Report for: 2005 BMW X5

Mfg Bulletin #: **SI-B51-30-08** Repl Bulletin #:
Component: **160000 STRUCTURE** Bulletin Date: **20081101**

BMW: WATER LEAK IN THE FRONT RIGHT FOOTWELL AREA CAUSING THE CARPET TO BECOME WET. *PE

TSB Report for: 2005 BMW X5

Mfg Bulletin #: **SI-B51-30-08** Repl Bulletin #:
Component: **161000 STRUCTURE:FRAME AND MEMBERS** Bulletin Date: **20081101**

BMW: WATER LEAK IN THE FRONT RIGHT FOOTWELL AREA CAUSING THE CARPET TO BECOME WET. *PE

TSB Report for: 2005 BMW X5

Mfg Bulletin #: **SI-B51-30-08** Repl Bulletin #:
Component: **162000 STRUCTURE:BODY** Bulletin Date: **20081101**

BMW: WATER LEAK IN THE FRONT RIGHT FOOTWELL AREA CAUSING THE CARPET TO BECOME WET. *PE

TSB Report for: 2005 BMW X5

Mfg Bulletin #: **SI-B51-30-08** Repl Bulletin #:
Component: **162800 STRUCTURE:BODY:HOOD** Bulletin Date: **20081101**

BMW: WATER LEAK IN THE FRONT RIGHT FOOTWELL AREA CAUSING THE CARPET TO BECOME WET. *PE

TSB Report for: 2005 BMW X5

Mfg Bulletin #: **SI-B-11-01-0** Repl Bulletin #:
Component: **061000 ENGINE AND ENGINE COOLING:ENGINE** Bulletin Date: **20090301**

BMW: SMALL NUMBER OF VEHICLES EXPERIENCE PROBLEMS RANGING FROM LEAKING OIL FILLER CAPS, LEAKING OR BROKEN VALVE COVERS, TO COMPLETE ENGINE FAILURE IN EXTREMELY COLD CLIMATE CONDITIONS. MOISTURE ACCUMULATING IN ENGINE CRANKCASE VENTILATION V

TSB Report for: 2005 BMW X5

Mfg Bulletin #: **SI-B-11-01-0** Repl Bulletin #: Bulletin Date: **20090301**
Component: **061200 ENGINE AND ENGINE COOLING:ENGINE:DIESEL**

BMW: SMALL NUMBER OF VEHICLES EXPERIENCE PROBLEMS RANGING FROM LEAKING OIL FILLER CAPS, LEAKING OR BROKEN VALVE COVERS, TO COMPLETE ENGINE FAILURE IN EXTREMELY COLD CLIMATE CONDITIONS. MOISTURE ACCUMULATING IN ENGINE CRANKCASE VENTILATION V

TSB Report for: 2005 BMW X5

Mfg Bulletin #: **SI-B-11-01-0** Repl Bulletin #: Bulletin Date: **20090301**
Component: **063110 ENGINE AND ENGINE COOLING:EXHAUST SYSTEM:EMISSION CONTROL:CRANKCASE (PCV)**

BMW: SMALL NUMBER OF VEHICLES EXPERIENCE PROBLEMS RANGING FROM LEAKING OIL FILLER CAPS, LEAKING OR BROKEN VALVE COVERS, TO COMPLETE ENGINE FAILURE IN EXTREMELY COLD CLIMATE CONDITIONS. MOISTURE ACCUMULATING IN ENGINE CRANKCASE VENTILATION V

TSB Report for: 2005 BMW X5

Mfg Bulletin #: **SI-B130209** Repl Bulletin #: Bulletin Date: **20090301**
Component: **080000 FUEL SYSTEM, DIESEL**

BMW: DIESEL: DIAGNOSIS FOR LOW PRESSURE FUEL SUPPLY FAULTS. SERVICE ENGINE SOON LAMP IS ILLUMINATED (A FUEL PUMP MALFUNCTION MESSAGE IS DISPLAYED IN THE CC) AND A COMBINATION OF THE FOLLOWING FAULT CODES MAY BE STORED IN THE DDE CONTROL MOD

TSB Report for: 2005 BMW X5

Mfg Bulletin #: **SIB-65-75-06** Repl Bulletin #: **SIB-65-75-06** Bulletin Date: **20110801**
Component: **140000 AIR BAGS**

BMW SERVICE CAMPAIGN: SEE DOCUMENT SEARCH BUTTON FOR OWNER LETTER. THE AIRBAG WARNING LAMP (AWL) IS ILLUMINATED, TOGETHER WITH THE PASSENGER AIRBAG STATUS LAMP (POL). THE PROBLEM MAY BE INTERMITTENT. MICROCRACKS IN THE OC3 SEAT MAT. *PE

TSB Report for: 2005 BMW X5

Mfg Bulletin #: **SI-B12-02-09** Repl Bulletin #: **SIB-12-02-09** Bulletin Date: **20090501**
Component: **071110 FUEL SYSTEM, GASOLINE:STORAGE:TANK ASSEMBLY:FILLER PIPE AND CAP**

BMW: SERVICE ENGINE SOON LAMP OR THE CHECK GAS CAP WARNINGS ARE ILLUMINATED WHILE DRIVING. WHEN DIAGNOSED, THE DME HAS STORED FAULTS FOR SMALL LEAK, MICRO LEAK, SUPER FINE LEAK, OR LARGE LEAK IN RELATION TO THE TANK VENTILATION OR EVAPORATI



Kelly Young
Dirigo Software
PO Box 53
Readfield, ME 04355

ds@dirigosoftware.com
www.dirigosoftware.com

TSB Report for: 2005 BMW X5

Mfg Bulletin #: **SI-B12-02-09** Repl Bulletin #: **SIB-12-02-09** Bulletin Date: **20090501**
Component: **091100 FUEL SYSTEM, OTHER:STORAGE:TANK ASSEMBLY**

BMW: SERVICE ENGINE SOON LAMP OR THE CHECK GAS CAP WARNINGS ARE ILLUMINATED WHILE DRIVING. WHEN DIAGNOSED, THE DME HAS STORED FAULTS FOR SMALL LEAK, MICRO LEAK, SUPER FINE LEAK, OR LARGE LEAK IN RELATION TO THE TANK VENTILATION OR EVAPORATI

TSB Report for: 2005 BMW X5

Mfg Bulletin #: **SI-B66-09-09** Repl Bulletin #: Bulletin Date: **20090901**
Component: **114000 ELECTRICAL SYSTEM:WIRING**

BMW: FAILURE OF REMOTE CONTROL LOCKING. INTERMITTENTLY OR PERMANENTLY, THE REMOTE CONTROL LOCKING IS INOPERATIVE. BOTH REMOTE KEYS ARE AFFECTED. IN SOME CASES, THE PARKING BRAKE WARNING IS ILLUMINATED IN THE INSTRUMENT CLUSTER AND FUSE

TSB Report for: 2005 BMW X5

Mfg Bulletin #: **SI-B31-01-08** Repl Bulletin #: Bulletin Date: **20090901**
Component: **105200 POWER TRAIN:DRIVELINE:CONSTANT VELOCITY JOINT**

BMW: REPLACEMENT OF FRONT OUTER CV JOINT. COMPLAINTS OF CLICKING OR GRINDING NOISES COMING FROM THE FRONT AXLE AREA WHEN MAKING A TURN. THE FRONT OUTER CONSTANT VELOCITY JOINT BOOT IS SPLIT OPEN AND THE JOINT IS ALREADY DAMAGED.

TSB Report for: 2005 BMW X5

Mfg Bulletin #: **SI-B31-01-08** Repl Bulletin #: Bulletin Date: **20090901**
Component: **106200 POWER TRAIN:AXLE ASSEMBLY:AXLE SHAFT**

BMW: REPLACEMENT OF FRONT OUTER CV JOINT. COMPLAINTS OF CLICKING OR GRINDING NOISES COMING FROM THE FRONT AXLE AREA WHEN MAKING A TURN. THE FRONT OUTER CONSTANT VELOCITY JOINT BOOT IS SPLIT OPEN AND THE JOINT IS ALREADY DAMAGED.

TSB Report for: 2005 BMW X5

Mfg Bulletin #: **SIB-61-15-09** Repl Bulletin #: Bulletin Date: **20100401**
Component: **110000 ELECTRICAL SYSTEM**

BMW VEHICLES: VARIOUS ELECTRICAL PROBLEMS ARE POSSIBLE ON THE VEHICLE: WARNING LAMPS ILLUMINATED IN THE INSTRUMENT CLUSTER; CHECK CONTROL MESSAGES; SYSTEMS INOPERATIVE; FUSE BLOWN; WIPERS IN DEFAULT MODE (PERMANENTLY ON); AND FAULT CODES F



Kelly Young
Dirigo Software
PO Box 53
Readfield, ME 04355

ds@dirigosoftware.com
www.dirigosoftware.com

TSB Report for: 2005 BMW X5

Mfg Bulletin #: **SIB-61-15-09** Repl Bulletin #:
Component: **117000 DIGITAL INSTRUMENT PANEL** Bulletin Date: **20100401**

BMW VEHICLES: VARIOUS ELECTRICAL PROBLEMS ARE POSSIBLE ON THE VEHICLE: WARNING LAMPS ILLUMINATED IN THE INSTRUMENT CLUSTER; CHECK CONTROL MESSAGES; SYSTEMS INOPERATIVE; FUSE BLOWN; WIPERS IN DEFAULT MODE (PERMANENTLY ON); AND FAULT CODES F

TSB Report for: 2005 BMW X5

Mfg Bulletin #: **SIB-34-03-07** Repl Bulletin #:
Component: **110000 ELECTRICAL SYSTEM** Bulletin Date: **20091001**

BMW VEHICLES: DSC WARNING LAMP ILLUMINATED. THE DSC (DYNAMIC STABILITY CONTROL) WARNING LAMP IS ILLUMINATED AND SOME OR ALL OF THE FOLLOWING FAULT CODES ARE STORED: 6E58; 6E04; 53BA; D36F; 55C3; 6ECA; AND THE WIPERS MAY ALSO BE OPERATING

TSB Report for: 2005 BMW X5

Mfg Bulletin #: **SIB-34-03-07** Repl Bulletin #:
Component: **114000 ELECTRICAL SYSTEM:WIRING** Bulletin Date: **20091001**

BMW VEHICLES: DSC WARNING LAMP ILLUMINATED. THE DSC (DYNAMIC STABILITY CONTROL) WARNING LAMP IS ILLUMINATED AND SOME OR ALL OF THE FOLLOWING FAULT CODES ARE STORED: 6E58; 6E04; 53BA; D36F; 55C3; 6ECA; AND THE WIPERS MAY ALSO BE OPERATING

TSB Report for: 2005 BMW X5

Mfg Bulletin #: **SIB-34-03-07** Repl Bulletin #:
Component: **136000 VISIBILITY:WINDSHIELD WIPER/WASHER** Bulletin Date: **20091001**

BMW VEHICLES: DSC WARNING LAMP ILLUMINATED. THE DSC (DYNAMIC STABILITY CONTROL) WARNING LAMP IS ILLUMINATED AND SOME OR ALL OF THE FOLLOWING FAULT CODES ARE STORED: 6E58; 6E04; 53BA; D36F; 55C3; 6ECA; AND THE WIPERS MAY ALSO BE OPERATING

TSB Report for: 2005 BMW X5

Mfg Bulletin #: **SIB-34-03-07** Repl Bulletin #:
Component: **025000 ELECTRONIC STABILITY CONTROL** Bulletin Date: **20091001**

BMW VEHICLES: DSC WARNING LAMP ILLUMINATED. THE DSC (DYNAMIC STABILITY CONTROL) WARNING LAMP IS ILLUMINATED AND SOME OR ALL OF THE FOLLOWING FAULT CODES ARE STORED: 6E58; 6E04; 53BA; D36F; 55C3; 6ECA; AND THE WIPERS MAY ALSO BE OPERATING



Kelly Young
Dirigo Software
PO Box 53
Readfield, ME 04355

ds@dirigosoftware.com
www.dirigosoftware.com

TSB Report for: 2005 BMW X5

Mfg Bulletin #: **SIB-13-02-09** Repl Bulletin #: Bulletin Date: **20091001**
Component: **061200 ENGINE AND ENGINE COOLING:ENGINE:DIESEL**

BMW VEHICLES: DIAGNOSIS FOR LOW PRESSURE FUEL SUPPLY FAULTS. THE SERVICE ENGINE SOON LAMP IS ILLUMINATED (A FUEL PUMP MALFUCTION MESSAGE IS DISPLAYED IN THE CC), AND A COMBINATION OF THE FOLLOWING FAULT CODES MAY BE STORED IN THE DDE CONT

TSB Report for: 2005 BMW X5

Mfg Bulletin #: **SIB-12-26-09** Repl Bulletin #: Bulletin Date: **20091001**
Component: **061000 ENGINE AND ENGINE COOLING:ENGINE**

BMW VEHICLES: EDK THROTTLE POTENTIOMETER FAULTS-DIAGNOSIS. MODELS E60, E63, E64, E65, E66, AND E70. THE SERVICE ENGINE SOON AND DSC/DTC WARNING LAMPS ARE ILLUMINATED. THE ENGINE ENTERS THE POWER REDUCTION (FAIL SAFE) MODE. *PE

TSB Report for: 2005 BMW X5

Mfg Bulletin #: **SIB-12-26-09** Repl Bulletin #: Bulletin Date: **20091001**
Component: **061200 ENGINE AND ENGINE COOLING:ENGINE:DIESEL**

BMW VEHICLES: EDK THROTTLE POTENTIOMETER FAULTS-DIAGNOSIS. MODELS E60, E63, E64, E65, E66, AND E70. THE SERVICE ENGINE SOON AND DSC/DTC WARNING LAMPS ARE ILLUMINATED. THE ENGINE ENTERS THE POWER REDUCTION (FAIL SAFE) MODE. *PE

TSB Report for: 2005 BMW X5

Mfg Bulletin #: **SIB-12-09-08** Repl Bulletin #: Bulletin Date: **20080201**
Component: **062200 ENGINE AND ENGINE COOLING:COOLING SYSTEM:FAN**

BMW VEHICLE: DRIVEABILITY COMPLAINTS DUE TO COOLING FAN RELAY FAILURE. THE CUSTOMER MAY COMPLAIN OF INTERMITTENT DRIVEABILITY PROBLEMS, DESCRIBED AS-ENGINE IS LACKING POWER WHEN ACCELERATING UPHILL; TRANSMISSION WILL NOT UPSHIFT UNDER HEA

TSB Report for: 2005 BMW X5

Mfg Bulletin #: **SIB-12-09-08** Repl Bulletin #: Bulletin Date: **20080201**
Component: **110000 ELECTRICAL SYSTEM**

BMW VEHICLE: DRIVEABILITY COMPLAINTS DUE TO COOLING FAN RELAY FAILURE. THE CUSTOMER MAY COMPLAIN OF INTERMITTENT DRIVEABILITY PROBLEMS, DESCRIBED AS-ENGINE IS LACKING POWER WHEN ACCELERATING UPHILL; TRANSMISSION WILL NOT UPSHIFT UNDER HEA



Kelly Young
Dirigo Software
PO Box 53
Readfield, ME 04355

ds@dirigosoftware.com
www.dirigosoftware.com

TSB Report for: 2005 BMW X5

Mfg Bulletin #: **SIB-12-23-07** Repl Bulletin #:
Bulletin Date: **20071101**
Component: **061000 ENGINE AND ENGINE COOLING:ENGINE**

BMW VEHICLE: FC 2EF4 CHARACTERISTIC MAP THERMOSTAT. COMPLAINTS THAT THE SERVICE ENGINE SOON LAMP IS ILLUMINATED. FAULT CODE 2EF4 CHARACTERISTIC MAP THERMOSTAT IS STORED IN DME FAULT MEMORY. DME SOFTWARE CALIBRATION RELATED TO HIGH HEATIN

TSB Report for: 2005 BMW X5

Mfg Bulletin #: **SIB-12-23-07** Repl Bulletin #:
Bulletin Date: **20071101**
Component: **353000 EQUIPMENT:ELECTRICAL**

BMW VEHICLE: FC 2EF4 CHARACTERISTIC MAP THERMOSTAT. COMPLAINTS THAT THE SERVICE ENGINE SOON LAMP IS ILLUMINATED. FAULT CODE 2EF4 CHARACTERISTIC MAP THERMOSTAT IS STORED IN DME FAULT MEMORY. DME SOFTWARE CALIBRATION RELATED TO HIGH HEATIN

TSB Report for: 2005 BMW X5

Mfg Bulletin #: **SIB-12-23-07** Repl Bulletin #:
Bulletin Date: **20071101**
Component: **118000 ELECTRICAL SYSTEM: SOFTWARE**

BMW VEHICLE: FC 2EF4 CHARACTERISTIC MAP THERMOSTAT. COMPLAINTS THAT THE SERVICE ENGINE SOON LAMP IS ILLUMINATED. FAULT CODE 2EF4 CHARACTERISTIC MAP THERMOSTAT IS STORED IN DME FAULT MEMORY. DME SOFTWARE CALIBRATION RELATED TO HIGH HEATIN

TSB Report for: 2005 BMW X5

Mfg Bulletin #: **SIB-61-11-07** Repl Bulletin #:
Bulletin Date: **20071101**
Component: **110000 ELECTRICAL SYSTEM**

BMW VEHICLE: MISSING CLIP ON POWER CABLE CAUSES VARIOUS ELECTRICAL COMPLAINTS. VEHICLE WILL NOT START. INSTRUMENT CLUSTER OR DISPLAYS ARE FLICKERING. REMOTE CONTROL WILL NOT UNLOCK VEHICLE. VARIOUS CONTROL MODULES CANNOT BE ACCESSED USIN

TSB Report for: 2005 BMW X5

Mfg Bulletin #: **SIB-61-13-07** Repl Bulletin #:
Bulletin Date: **20071101**
Component: **110000 ELECTRICAL SYSTEM**

BMW VEHICLE: ELECTRONIC MALFUNCTION CC MESSAGE CAUSED BY SHORTED WIRING. THE ELECTRONIC MALFUNCTION CHECK CONTROL MESSAGE MAY BE DISPLAYED; THE SOUNDS SYSTEM EMITS A STATIC NOISE FROM THE SPEAKERS; THE RFK (REAR VIEW CAMERA) DOES NOT PAN;



Kelly Young
Dirigo Software
PO Box 53
Readfield, ME 04355

ds@dirigosoftware.com
www.dirigosoftware.com

TSB Report for: 2005 BMW X5

Mfg Bulletin #: **SIB-61-13-07** Repl Bulletin #: Bulletin Date: **20071101**
Component: **114000 ELECTRICAL SYSTEM:WIRING**

BMW VEHICLE: ELECTRONIC MALFUNCTION CC MESSAGE CAUSED BY SHORTED WIRING. THE ELECTRONIC MALFUNCTION CHECK CONTROL MESSAGE MAY BE DISPLAYED; THE SOUNDS SYSTEM EMITS A STATIC NOISE FROM THE SPEAKERS; THE RFK (REAR VIEW CAMERA) DOES NOT PAN;

TSB Report for: 2005 BMW X5

Mfg Bulletin #: **SIB-61-13-07** Repl Bulletin #: Bulletin Date: **20071101**
Component: **353000 EQUIPMENT:ELECTRICAL**

BMW VEHICLE: ELECTRONIC MALFUNCTION CC MESSAGE CAUSED BY SHORTED WIRING. THE ELECTRONIC MALFUNCTION CHECK CONTROL MESSAGE MAY BE DISPLAYED; THE SOUNDS SYSTEM EMITS A STATIC NOISE FROM THE SPEAKERS; THE RFK (REAR VIEW CAMERA) DOES NOT PAN;

TSB Report for: 2005 BMW X5

Mfg Bulletin #: **SIB-61-13-07** Repl Bulletin #: Bulletin Date: **20071101**
Component: **118000 ELECTRICAL SYSTEM: SOFTWARE**

BMW VEHICLE: ELECTRONIC MALFUNCTION CC MESSAGE CAUSED BY SHORTED WIRING. THE ELECTRONIC MALFUNCTION CHECK CONTROL MESSAGE MAY BE DISPLAYED; THE SOUNDS SYSTEM EMITS A STATIC NOISE FROM THE SPEAKERS; THE RFK (REAR VIEW CAMERA) DOES NOT PAN;

TSB Report for: 2005 BMW X5

Mfg Bulletin #: **SIB-36-05-07** Repl Bulletin #: Bulletin Date: **20071201**
Component: **199000 TIRES:PRESSURE MONITORING AND REGULATING SYSTEMS**

BMW: TIRE WARNING LIGHT ILLUMINATED DUE TO LOW AMBIENT TEMPERATURE. MODEL E90, E91 (3 SERIES); E92, E92 (3 SERIES); E60 (5 SERIES); E60 (M5); E63, E64 (6 SERIES); E63, E64 (M6); E65, E66 (7 SERIES); E70 (X5); E83 (X3); AND E85, E86 (Z4).

TSB Report for: 2005 BMW X5

Mfg Bulletin #: **SIB-16-02-09** Repl Bulletin #: Bulletin Date: **20091201**
Component: **072100 FUEL SYSTEM, GASOLINE:DELIVERY:FUEL PUMP**

BMW VEHICLES: FUEL LEVEL SENSOR REPAIRS. WHERE IT IS NECESSARY TO REPLACE THE RIGHT OR THE LEFT SIDE FUEL LEVEL SENSOR DUE TO A FAILURE, THE ENTIRE PUMP AND



Kelly Young
Dirigo Software
PO Box 53
Readfield, ME 04355

ds@dirigosoftware.com
www.dirigosoftware.com

HOUSING OR DELIVERY UNIT (SUCTION JET ASSEMBLY) DO NOT NEED TO BE REPLACED AS WEL

TSB Report for: 2005 BMW X5

Mfg Bulletin #: **SI-B61-15-09** Repl Bulletin #:
Bulletin Date: **20100401**
Component: **110000 ELECTRICAL SYSTEM**

BMW: VARIOUS ELECTRICAL PROBLEMS. ON THE VEHICLE, VARIOUS ELECTRICAL PROBLEMS ARE POSSIBLE. WARNING LAMPS ILLUMINATED IN THE INSTRUMENT CLUSTER; CHECK CONTROL MESSAGES; SYSTEMS INOPERATIVE; FUSE BLOWN; WIPERS IN DEFAULT MODE (PERMANENTLY O

TSB Report for: 2005 BMW X5

Mfg Bulletin #: **SI-B61-15-09** Repl Bulletin #:
Bulletin Date: **20100401**
Component: **114000 ELECTRICAL SYSTEM:WIRING**

BMW: VARIOUS ELECTRICAL PROBLEMS. ON THE VEHICLE, VARIOUS ELECTRICAL PROBLEMS ARE POSSIBLE. WARNING LAMPS ILLUMINATED IN THE INSTRUMENT CLUSTER; CHECK CONTROL MESSAGES; SYSTEMS INOPERATIVE; FUSE BLOWN; WIPERS IN DEFAULT MODE (PERMANENTLY O

TSB Report for: 2005 BMW X5

Mfg Bulletin #: **SIB-24-01-08** Repl Bulletin #:
Bulletin Date: **20101001**
Component: **103000 POWER TRAIN:AUTOMATIC TRANSMISSION**

BMW VEHICLE: TRANSMISSION WARNING LIGHT IS ILLUMINATED AND THE TRANSMISSION ENTERS FAILSAFE MODE. FAULT CODE 4F81 (RATIO MONITORING, CLUTCH A), IN SOME CASES COMBINED WITH THE SUBSEQUENT FAULTS 507B/507C (PARKING GEAR SENSOR IMPLAUSIBLE S

TSB Report for: 2005 BMW X5

Mfg Bulletin #: **SIB-32-04-07** Repl Bulletin #:
Bulletin Date: **20100601**
Component: **015000 STEERING:HYDRAULIC POWER ASSIST SYSTEM**

BMW: A NEW TECHNICAL PROCESS HAS BEEN CREATED FOR BMW TO IDENTIFY CAUSES OF STEERING COMPLAINTS WITH A WIDE RANGE OF MODELS. *RM



Kelly Young
Dirigo Software
PO Box 53
Readfield, ME 04355

ds@dirigosoftware.com
www.dirigosoftware.com

TSB Report for: 2005 BMW X5

Mfg Bulletin #: **SIB-32-04-07** Repl Bulletin #: Bulletin Date: **20100601**
Component: **016000 STEERING:ELECTRIC POWER ASSIST SYSTEM**

BMW: A NEW TECHNICAL PROCESS HAS BEEN CREATED FOR BMW TO IDENTIFY CAUSES OF STEERING COMPLAINTS WITH A WIDE RANGE OF MODELS. *RM

TSB Report for: 2005 BMW X5

Mfg Bulletin #: **SIB-16-03-10** Repl Bulletin #: Bulletin Date: **20100601**
Component: **061200 ENGINE AND ENGINE COOLING:ENGINE:DIESEL**

BMW: WARNING MESSAGE ON ABOUT LOW DIESEL EXHAUST FUEL LEVEL AND THAT THE ENGINE WILL NOT RESTART WITHIN 999 MILES. THE LIGHT COMES ON A FEW THOUSAND MILES EARLIER THAN A RECOMMENDED OIL CHANGE. *RM

TSB Report for: 2005 BMW X5

Mfg Bulletin #: **SIB-16-03-10** Repl Bulletin #: Bulletin Date: **20100601**
Component: **080000 FUEL SYSTEM, DIESEL**

BMW: WARNING MESSAGE ON ABOUT LOW DIESEL EXHAUST FUEL LEVEL AND THAT THE ENGINE WILL NOT RESTART WITHIN 999 MILES. THE LIGHT COMES ON A FEW THOUSAND MILES EARLIER THAN A RECOMMENDED OIL CHANGE. *RM

TSB Report for: 2005 BMW X5

Mfg Bulletin #: **SIB-13-07-10** Repl Bulletin #: Bulletin Date: **20100601**
Component: **061000 ENGINE AND ENGINE COOLING:ENGINE**

BMW: THERE IS A ROUGH ENGINE IDLE AND "SERVICE ENGINE SOON LIGHT" WHEN DRIVING DOWNHILL IN HIGH ALTITUDES DURING COLD WEATHER. THERE MAY BE SIX DIFFERENT FAULT CODES. *RM

TSB Report for: 2005 BMW X5

Mfg Bulletin #: **SIB-13-02-10** Repl Bulletin #: Bulletin Date: **20100601**
Component: **070000 FUEL SYSTEM, GASOLINE**

BMW: IT IS NOW POSSIBLE TO PERFORM A FUEL QUALITY DETECTION TEST ON VEHICLES WITH AN N54 ENGINE. *RM



Kelly Young
Dirigo Software
PO Box 53
Readfield, ME 04355

ds@dirigosoftware.com
www.dirigosoftware.com

TSB Report for: 2005 BMW X5

Mfg Bulletin #: **SIB-13-02-10** Repl Bulletin #:
Component: **080000 FUEL SYSTEM, DIESEL** Bulletin Date: **20100601**

BMW: IT IS NOW POSSIBLE TO PERFORM A FUEL QUALITY DETECTION TEST ON VEHICLES WITH AN N54 ENGINE. *RM

TSB Report for: 2005 BMW X5

Mfg Bulletin #: **SIB-13-06-10** Repl Bulletin #:
Component: **061000 ENGINE AND ENGINE COOLING:ENGINE** Bulletin Date: **20100601**

BMW: A SERVICE ENGINE SOON LIGHT COMES ON. THE ENGINE WILL ONLY OPERATE TO 1500 RPMS AND LACKS POWER. THERE IS A SOFTWARE APPLICATION ERROR. *RM

TSB Report for: 2005 BMW X5

Mfg Bulletin #: **SIB-13-06-10** Repl Bulletin #:
Component: **118000 ELECTRICAL SYSTEM: SOFTWARE** Bulletin Date: **20100601**

BMW: A SERVICE ENGINE SOON LIGHT COMES ON. THE ENGINE WILL ONLY OPERATE TO 1500 RPMS AND LACKS POWER. THERE IS A SOFTWARE APPLICATION ERROR. *RM

TSB Report for: 2005 BMW X5

Mfg Bulletin #: **SIB-11-08-03** Repl Bulletin #:
Component: **061000 ENGINE AND ENGINE COOLING:ENGINE** Bulletin Date: **20100701**

BMW: SIX DIFFERENT MODELS EQUIPPED WITH THE M54 ENGINE COULD HAVE VALVE COVERS BREAK IN COLD WEATHER AND RUIN THE ENGINE. THIS IS DUE TO MOISTURE ACCUMULATION. *RM

TSB Report for: 2005 BMW X5

Mfg Bulletin #: **SIB-63-02-01** Repl Bulletin #:
Component: **120000 EXTERIOR LIGHTING** Bulletin Date: **20100801**

BMW: PROCEDURE FOR DETERMINING AND REPLACING INCANDESCENT AND HALOGEN LIGHT BULBS UNDER WARRANTY. *RM

TSB Report for: 2005 BMW X5

Mfg Bulletin #: **SIB-61-08-10** Repl Bulletin #:
Component: **110000 ELECTRICAL SYSTEM** Bulletin Date: **20100801**

BMW: ELCTRONICALLY DISCONNECTING THE JUNCTION BOX WITHOUT DISCONNECTING THE



Kelly Young
Dirigo Software
PO Box 53
Readfield, ME 04355

ds@dirigosoftware.com
www.dirigosoftware.com

BATTERY WILL CAUSE DAMAGE TO THE REAR POWER DISTRIBUTION BOX. *RM

TSB Report for: 2005 BMW X5

Mfg Bulletin #: **SIB-61-08-10** Repl Bulletin #:
Bulletin Date: **20100801**
Component: **111000 ELECTRICAL SYSTEM:BATTERY**

BMW: ELCTRONICALLY DISCONNECTING THE JUNCTION BOX WITHOUT DISCONNECTING THE BATTERY WILL CAUSE DAMAGE TO THE REAR POWER DISTRIBUTION BOX. *RM

TSB Report for: 2005 BMW X5

Mfg Bulletin #: **SIB-61-08-10** Repl Bulletin #:
Bulletin Date: **20100801**
Component: **353000 EQUIPMENT:ELECTRICAL**

BMW: ELCTRONICALLY DISCONNECTING THE JUNCTION BOX WITHOUT DISCONNECTING THE BATTERY WILL CAUSE DAMAGE TO THE REAR POWER DISTRIBUTION BOX. *RM

TSB Report for: 2005 BMW X5

Mfg Bulletin #: **SIB-51-26-10** Repl Bulletin #:
Bulletin Date: **20100801**
Component: **114000 ELECTRICAL SYSTEM:WIRING**

BMW: MODEL E70 EQUIPPED WITH AN AUTOMATIC TAILGATE. THE REAR TAILGATE MAY NOT OPERATE IN EITHER DIRECTION DUE TO WIRING DAMAGE. *RM

TSB Report for: 2005 BMW X5

Mfg Bulletin #: **SIB-51-26-10** Repl Bulletin #:
Bulletin Date: **20100801**
Component: **162500 STRUCTURE:BODY:TAILGATE**

BMW: MODEL E70 EQUIPPED WITH AN AUTOMATIC TAILGATE. THE REAR TAILGATE MAY NOT OPERATE IN EITHER DIRECTION DUE TO WIRING DAMAGE. *RM

TSB Report for: 2005 BMW X5

Mfg Bulletin #: **SIB-65-36-09** Repl Bulletin #:
Bulletin Date: **20100901**
Component: **114000 ELECTRICAL SYSTEM:WIRING**

BMW: THE AIRBAG WARNING LAMP IS ILLUMINATED DUE TO A SOFTWARE ERROR. *RM



Kelly Young
Dirigo Software
PO Box 53
Readfield, ME 04355

ds@dirigosoftware.com
www.dirigosoftware.com

TSB Report for: 2005 BMW X5

Mfg Bulletin #: **SIB-65-36-09** Repl Bulletin #: Bulletin Date: **20100901**
Component: **140000 AIR BAGS**

BMW: THE AIRBAG WARNING LAMP IS ILLUMINATED DUE TO A SOFTWARE ERROR. *RM

TSB Report for: 2005 BMW X5

Mfg Bulletin #: **SIB-65-36-09** Repl Bulletin #: Bulletin Date: **20100901**
Component: **118000 ELECTRICAL SYSTEM: SOFTWARE**

BMW: THE AIRBAG WARNING LAMP IS ILLUMINATED DUE TO A SOFTWARE ERROR. *RM

TSB Report for: 2005 BMW X5

Mfg Bulletin #: **SIB-52-08-09** Repl Bulletin #: Bulletin Date: **20101001**
Component: **221600 SEATS:FRONT ASSEMBLY:POWER ADJUST**

BMW: THERE ARE NOISES WHEN ADJUSTING THE FRONT DRIVER OR PASSENGER SEATES. *RM

TSB Report for: 2005 BMW X5

Mfg Bulletin #: **SIB-63-10-09** Repl Bulletin #: Bulletin Date: **20110301**
Component: **125000 EXTERIOR LIGHTING:BRAKE LIGHTS**

BMW: THE BRAKE LIGHT FAILS AND THE BULB HOLDER IS DEFORMED DUE TO HIGH TEMPERATURES AND THE COMPOSITION OF THE HOLDER. *RM

TSB Report for: 2005 BMW X5

Mfg Bulletin #: **SIB-12-15-11** Repl Bulletin #: Bulletin Date: **20110701**
Component: **061000 ENGINE AND ENGINE COOLING:ENGINE**

BMW: THE SERVICE ENGINE SOON LIGHT IS ON. THERE ARE TROUBLE CODES STORED FOR THE CRANKSHAFT SENSOR. NO DRIVEABILITY ISSUES. *RM

TSB Report for: 2005 BMW X5

Mfg Bulletin #: **SIB-63-04-10** Repl Bulletin #: Bulletin Date: **20100301**
Component: **120000 EXTERIOR LIGHTING**

BMW: THE BULB HAS FAILED ON THE DAYTIME RUNNING LAMP. *PE



Kelly Young
Dirigo Software
PO Box 53
Readfield, ME 04355

ds@dirigosoftware.com
www.dirigosoftware.com

TSB Report for: 2005 BMW X5

Mfg Bulletin #: **SIB-63-04-10** Repl Bulletin #:
Component: **121000 EXTERIOR LIGHTING:HEADLIGHTS** Bulletin Date: **20100301**

BMW: THE BULB HAS FAILED ON THE DAYTIME RUNNING LAMP. *PE

TSB Report for: 2005 BMW X5

Mfg Bulletin #: **SIB-61-06-11** Repl Bulletin #:
Component: **118000 ELECTRICAL SYSTEM: SOFTWARE** Bulletin Date: **20110901**

BMW: ON CERTAIN VEHICLES, THE JBE (JUNCTION BOX ELECTRONICS) MODULE FAILS PROGRAMMING DURING A SOFTWARE UPDATE OF THE VEHICLE. *PE

TSB Report for: 2005 BMW X5

Mfg Bulletin #: **SIB-63-05-11** Repl Bulletin #:
Component: **121000 EXTERIOR LIGHTING:HEADLIGHTS** Bulletin Date: **20110901**

BMW: ON CERTAIN VEHICLES, THE XENON HEADLAMP OFTEN HAVE NO TROUBLE FOUND WHEN RETURNED AND TESTED THRU WARRANTY PARTS SYSTEM. THE ROOT CAUSE IS NOT POSSIBLE TO BE IDENTIFY. *PE

TSB Report for: 2006 BMW X5

Mfg Bulletin #: **360406** Repl Bulletin #:
Component: **190000 TIRES** Bulletin Date: **20060401**

NITROGEN INFLATED TIRES. *TT

TSB Report for: 2006 BMW X5

Mfg Bulletin #: **130206** Repl Bulletin #:
Component: **070000 FUEL SYSTEM, GASOLINE** Bulletin Date: **20060401**

TOP TIER DETERGENT GASOLINE IN BMW VEHICLES. *TT

TSB Report for: 2006 BMW X5

Mfg Bulletin #: **360106** Repl Bulletin #:
Component: **190000 TIRES** Bulletin Date: **20060301**

ERRONEOUS FLAT TIRE WARNING. *TT



Kelly Young
Dirigo Software
PO Box 53
Readfield, ME 04355

ds@dirigosoftware.com
www.dirigosoftware.com

TSB Report for: 2006 BMW X5

Mfg Bulletin #: **515001** Repl Bulletin #: **510206** Bulletin Date: **20060301**
Component: **162700 STRUCTURE:BODY:TRUNK LID**

TRUNK LID GRIP WATER INGRESS - INTERMITTENT TRUNK LID (LIFT GATE OR REAR HATCH) UNLOCKING OPERATIONS. *TT

TSB Report for: 2006 BMW X5

Mfg Bulletin #: **130306** Repl Bulletin #: Bulletin Date: **20060501**
Component: **090000 FUEL SYSTEM, OTHER**

FUEL PUMP FAILURE AFTER REFUELING WITH ETHANOL FUEL BLEND. *TT

TSB Report for: 2006 BMW X5

Mfg Bulletin #: **510307** Repl Bulletin #: Bulletin Date: **20070201**
Component: **176100 LATCHES/LOCKS/LINKAGES:HOOD:LATCH**

INSTALL HOOD LATCH CORROSION RESISTANT CLIP. *KB

TSB Report for: 2006 BMW X5

Mfg Bulletin #: **SI B61 11 07** Repl Bulletin #: Bulletin Date: **20071101**
Component: **110000 ELECTRICAL SYSTEM**

MISSING CLIP ON POWER CABLE CAUSES VARIOUS ELECTRICAL COMPLAINTS. *NJ

TSB Report for: 2006 BMW X5

Mfg Bulletin #: **SI B31 01 07** Repl Bulletin #: Bulletin Date: **20080101**
Component: **021000 SUSPENSION:FRONT**

KNOCKING NOISE FROM FRONT SUSPENSION. *NJ

TSB Report for: 2006 BMW X5

Mfg Bulletin #: **SI B 340307** Repl Bulletin #: **SI B34-03-07** Bulletin Date: **20080601**
Component: **114000 ELECTRICAL SYSTEM:WIRING**

DSC WARNING LAMP ILLUMINATED. E70 (X5) VEHICLES PRODUCED UP TO JANUARY 28, 2007. *PE
UPDATED 9/10/08. *PE



Kelly Young
Dirigo Software
PO Box 53
Readfield, ME 04355

ds@dirigosoftware.com
www.dirigosoftware.com

TSB Report for: 2006 BMW X5

Mfg Bulletin #: **SI B12 08 08** Repl Bulletin #: Bulletin Date: **20080401**
Component: **061000 ENGINE AND ENGINE COOLING:ENGINE**

SERVICE ACTION ON MY 2005 AND 2006 E53 (X5) WITH M54 ENGINE AND GM5 TRANSMISSION PRODUCED 09/2004-10/2006 - REPROGRAM DME. *PE

TSB Report for: 2006 BMW X5

Mfg Bulletin #: **SI B12 08 08** Repl Bulletin #: Bulletin Date: **20080401**
Component: **103000 POWER TRAIN:AUTOMATIC TRANSMISSION**

SERVICE ACTION ON MY 2005 AND 2006 E53 (X5) WITH M54 ENGINE AND GM5 TRANSMISSION PRODUCED 09/2004-10/2006 - REPROGRAM DME. *PE

TSB Report for: 2006 BMW X5

Mfg Bulletin #: **SI B34 01 08** Repl Bulletin #: Bulletin Date: **20080401**
Component: **053000 PARKING BRAKE:INDICATOR LIGHT**

THE PARKING BRAKE WARNING IS ILLUMINATED AND FAULT CODE 6032 IS STORED. FOR MODEL E70 (X5). *PE

TSB Report for: 2006 BMW X5

Mfg Bulletin #: **SI B37-03-07** Repl Bulletin #: Bulletin Date: **20080101**
Component: **020000 SUSPENSION**

BMW: DYNAMIC DRIVE (ARS) FRONT SWAY BAR REPAIRS. E70 (X5) WITH SPORT PACKAGE OPTION CODE ZSP. *PE

TSB Report for: 2006 BMW X5

Mfg Bulletin #: **SI B63-04-08** Repl Bulletin #: Bulletin Date: **20080601**
Component: **121000 EXTERIOR LIGHTING:HEADLIGHTS**

BMW: HEADLAMP MOISTURE: FAULT DIAGNOSTICS. WATER OR CONDENSATION IN ONE OR BOTH HEADLAMPS. MODELS 5 SERIES, 6 SERIES, 7 SERIES, X5, X6, 1 SERIES, AND 3 SERIES. MODEL YEARS 2000-20008. *PE



Kelly Young
Dirigo Software
PO Box 53
Readfield, ME 04355

ds@dirigosoftware.com
www.dirigosoftware.com

TSB Report for: 2006 BMW X5

Mfg Bulletin #: **SI-B11-01-08** Repl Bulletin #: Bulletin Date: **20080401**
Component: **355200 EQUIPMENT:OTHER:OWNERS/SERVICE/OTHER MANUAL**

BMW: REPLACE THE CHAIN TENSIONING RAIL BEARING BOLT THAT COULD COME LOOSE AND CAUSE DAMAGE TO THE ENGINE. MODELS E60 (5 SERIES), E70 (X5 SERIES), E83 (X3 SERIES), E9X (3 SERIES). *PE

TSB Report for: 2006 BMW X5

Mfg Bulletin #: **TSB-24-04-08** Repl Bulletin #: **SIB-24-04-08** Bulletin Date: **20101201**
Component: **103000 POWER TRAIN:AUTOMATIC TRANSMISSION**

BMW: DELAYED ENGAGEMENT AND HARSH JOLT WHEN ACCELERATING FROM A STOP. HARSH 1-2 UPSHIFT OR JOLT FELT DURING THE 3-2 DOWNSHIFT OWN DECELERATION. MODEL E70 (X5 3.0I) *PE UPDATED 06/08/11. *PE

TSB Report for: 2006 BMW X5

Mfg Bulletin #: **SI-B-12-04-0** Repl Bulletin #: Bulletin Date: **20101101**
Component: **061000 ENGINE AND ENGINE COOLING:ENGINE**

BMW: CHECK ENGINE LAMP ILLUMINATED AND/OR VEHICLE OVERHEATS. MODELS E83, E85, E86, E70, E90, E91, E92, E93, E60 AND E61. *PE UPDATED 5/24/11. *PE

TSB Report for: 2006 BMW X5

Mfg Bulletin #: **SI-B-12-04-0** Repl Bulletin #: Bulletin Date: **20101101**
Component: **110000 ELECTRICAL SYSTEM**

BMW: CHECK ENGINE LAMP ILLUMINATED AND/OR VEHICLE OVERHEATS. MODELS E83, E85, E86, E70, E90, E91, E92, E93, E60 AND E61. *PE UPDATED 5/24/11. *PE

TSB Report for: 2006 BMW X5

Mfg Bulletin #: **SI-B-12-04-0** Repl Bulletin #: Bulletin Date: **20101101**
Component: **117000 DIGITAL INSTRUMENT PANEL**

BMW: CHECK ENGINE LAMP ILLUMINATED AND/OR VEHICLE OVERHEATS. MODELS E83, E85, E86, E70, E90, E91, E92, E93, E60 AND E61. *PE UPDATED 5/24/11. *PE



Kelly Young
Dirigo Software
PO Box 53
Readfield, ME 04355

ds@dirigosoftware.com
www.dirigosoftware.com

TSB Report for: 2006 BMW X5

Mfg Bulletin #: **SI-B-84-05-0** Repl Bulletin #: Bulletin Date: **20080901**
Component: **110000 ELECTRICAL SYSTEM**

BMW: THE TELEMATICS CONTROL UNIT (TCU) IN VEHICLES MAY NOT HAVE BEEN PROPERLY ACTIVATED. THIS CAUSES THE MANUAL AND AUTOMATIC EMERGENCY CALL AND ROADSIDE CALL (BMW ASSIST) NOT TO FUNCTION. MODELS E53, E60, E90, E83 ARE AFFECTED.

TSB Report for: 2006 BMW X5

Mfg Bulletin #: **SI-B-84-05-0** Repl Bulletin #: Bulletin Date: **20080901**
Component: **353000 EQUIPMENT:ELECTRICAL**

BMW: THE TELEMATICS CONTROL UNIT (TCU) IN VEHICLES MAY NOT HAVE BEEN PROPERLY ACTIVATED. THIS CAUSES THE MANUAL AND AUTOMATIC EMERGENCY CALL AND ROADSIDE CALL (BMW ASSIST) NOT TO FUNCTION. MODELS E53, E60, E90, E83 ARE AFFECTED.

TSB Report for: 2006 BMW X5

Mfg Bulletin #: **SI-B-84-05-0** Repl Bulletin #: Bulletin Date: **20080901**
Component: **353500 EQUIPMENT:ELECTRICAL:NAVIGATIONAL SYSTEM(GLOBAL POSITIONING SYSTEM)**

BMW: THE TELEMATICS CONTROL UNIT (TCU) IN VEHICLES MAY NOT HAVE BEEN PROPERLY ACTIVATED. THIS CAUSES THE MANUAL AND AUTOMATIC EMERGENCY CALL AND ROADSIDE CALL (BMW ASSIST) NOT TO FUNCTION. MODELS E53, E60, E90, E83 ARE AFFECTED.

TSB Report for: 2006 BMW X5

Mfg Bulletin #: **SI-B51-30-08** Repl Bulletin #: Bulletin Date: **20081101**
Component: **160000 STRUCTURE**

BMW: WATER LEAK IN THE FRONT RIGHT FOOTWELL AREA CAUSING THE CARPET TO BECOME WET. *PE

TSB Report for: 2006 BMW X5

Mfg Bulletin #: **SI-B51-30-08** Repl Bulletin #: Bulletin Date: **20081101**
Component: **161000 STRUCTURE:FRAME AND MEMBERS**

BMW: WATER LEAK IN THE FRONT RIGHT FOOTWELL AREA CAUSING THE CARPET TO BECOME WET. *PE



TSB Report for: 2006 BMW X5

Mfg Bulletin #: **SI-B51-30-08** Repl Bulletin #:
Component: **162000 STRUCTURE:BODY** Bulletin Date: **20081101**

BMW: WATER LEAK IN THE FRONT RIGHT FOOTWELL AREA CAUSING THE CARPET TO BECOME WET. *PE

TSB Report for: 2006 BMW X5

Mfg Bulletin #: **SI-B51-30-08** Repl Bulletin #:
Component: **162800 STRUCTURE:BODY:HOOD** Bulletin Date: **20081101**

BMW: WATER LEAK IN THE FRONT RIGHT FOOTWELL AREA CAUSING THE CARPET TO BECOME WET. *PE

TSB Report for: 2006 BMW X5

Mfg Bulletin #: **SI-B-11-01-0** Repl Bulletin #:
Component: **061000 ENGINE AND ENGINE COOLING:ENGINE** Bulletin Date: **20090301**

BMW: SMALL NUMBER OF VEHICLES EXPERIENCE PROBLEMS RANGING FROM LEAKING OIL FILLER CAPS, LEAKING OR BROKEN VALVE COVERS, TO COMPLETE ENGINE FAILURE IN EXTREMELY COLD CLIMATE CONDITIONS. MOISTURE ACCUMULATING IN ENGINE CRANKCASE VENTILATION V

TSB Report for: 2006 BMW X5

Mfg Bulletin #: **SI-B-11-01-0** Repl Bulletin #:
Component: **061200 ENGINE AND ENGINE COOLING:ENGINE:DIESEL** Bulletin Date: **20090301**

BMW: SMALL NUMBER OF VEHICLES EXPERIENCE PROBLEMS RANGING FROM LEAKING OIL FILLER CAPS, LEAKING OR BROKEN VALVE COVERS, TO COMPLETE ENGINE FAILURE IN EXTREMELY COLD CLIMATE CONDITIONS. MOISTURE ACCUMULATING IN ENGINE CRANKCASE VENTILATION V

TSB Report for: 2006 BMW X5

Mfg Bulletin #: **SI-B-11-01-0** Repl Bulletin #:
Component: **063110 ENGINE AND ENGINE COOLING:EXHAUST SYSTEM:EMISSION CONTROL:CRANKCASE (PCV)** Bulletin Date: **20090301**

BMW: SMALL NUMBER OF VEHICLES EXPERIENCE PROBLEMS RANGING FROM LEAKING OIL FILLER CAPS, LEAKING OR BROKEN VALVE COVERS, TO COMPLETE ENGINE FAILURE IN EXTREMELY COLD CLIMATE CONDITIONS. MOISTURE ACCUMULATING IN ENGINE CRANKCASE VENTILATION V



Kelly Young
Dirigo Software
PO Box 53
Readfield, ME 04355

ds@dirigosoftware.com
www.dirigosoftware.com

TSB Report for: 2006 BMW X5

Mfg Bulletin #: **SI-B130209** Repl Bulletin #: Bulletin Date: **20090301**
Component: **080000 FUEL SYSTEM, DIESEL**

BMW: DIESEL: DIAGNOSIS FOR LOW PRESSURE FUEL SUPPLY FAULTS. SERVICE ENGINE SOON LAMP IS ILLUMINATED (A FUEL PUMP MALFUNCTION MESSAGE IS DISPLAYED IN THE CC) AND A COMBINATION OF THE FOLLOWING FAULT CODES MAY BE STORED IN THE DDE CONTROL MOD

TSB Report for: 2006 BMW X5

Mfg Bulletin #: **SI-B12-02-09** Repl Bulletin #: **SIB-12-02-09** Bulletin Date: **20090501**
Component: **071110 FUEL SYSTEM, GASOLINE:STORAGE:TANK ASSEMBLY:FILLER PIPE AND CAP**

BMW: SERVICE ENGINE SOON LAMP OR THE CHECK GAS CAP WARNINGS ARE ILLUMINATED WHILE DRIVING. WHEN DIAGNOSED, THE DME HAS STORED FAULTS FOR SMALL LEAK, MICRO LEAK, SUPER FINE LEAK, OR LARGE LEAK IN RELATION TO THE TANK VENTILATION OR EVAPORATI

TSB Report for: 2006 BMW X5

Mfg Bulletin #: **SI-B12-02-09** Repl Bulletin #: **SIB-12-02-09** Bulletin Date: **20090501**
Component: **091100 FUEL SYSTEM, OTHER:STORAGE:TANK ASSEMBLY**

BMW: SERVICE ENGINE SOON LAMP OR THE CHECK GAS CAP WARNINGS ARE ILLUMINATED WHILE DRIVING. WHEN DIAGNOSED, THE DME HAS STORED FAULTS FOR SMALL LEAK, MICRO LEAK, SUPER FINE LEAK, OR LARGE LEAK IN RELATION TO THE TANK VENTILATION OR EVAPORATI

TSB Report for: 2006 BMW X5

Mfg Bulletin #: **SB-12-01-09** Repl Bulletin #: Bulletin Date: **20090501**
Component: **061000 ENGINE AND ENGINE COOLING:ENGINE**

BMW VEHICLES: SERVICE ENGINE SOON LAMP OR CHECK GAS CAP WARNING ILLUMINATED WHILE DRIVING. SOFTWARE ERROR IN THE DME FOR THE TANK LEAK DIAGNOSTIC SYSTEM. MODELS E60, E61 (5 SERIES); E70 (X5); E71 (X6); E82, E88 (1 SERIES); E83 (X3); E90,

TSB Report for: 2006 BMW X5

Mfg Bulletin #: **SB-12-01-09** Repl Bulletin #: Bulletin Date: **20090501**
Component: **071110 FUEL SYSTEM, GASOLINE:STORAGE:TANK ASSEMBLY:FILLER PIPE AND CAP**

BMW VEHICLES: SERVICE ENGINE SOON LAMP OR CHECK GAS CAP WARNING ILLUMINATED WHILE DRIVING. SOFTWARE ERROR IN THE DME FOR THE TANK LEAK DIAGNOSTIC SYSTEM. MODELS E60, E61 (5 SERIES); E70 (X5); E71 (X6); E82, E88 (1 SERIES); E83 (X3); E90,



Kelly Young
Dirigo Software
PO Box 53
Readfield, ME 04355

ds@dirigosoftware.com
www.dirigosoftware.com

TSB Report for: 2006 BMW X5

Mfg Bulletin #: **SB-12-18-09** Repl Bulletin #: Bulletin Date: **20090501**
Component: **061000 ENGINE AND ENGINE COOLING:ENGINE**

BMW VEHICLES: PROGRAM CONTROL UNITS (DME-DMTL DIAGNOSIS). AN INCORRECT TANK LEAKAGE DIAGNOSIS MAY OCCUR DUE TO A SOFTWARE ERROR. THE SERVICE ENGINE SOON (MIL) LAMP MAY BE ILLUMINATED WITH THE DMTL LEAKAGE FAULT STORED, EVEN THOUGH THERE

TSB Report for: 2006 BMW X5

Mfg Bulletin #: **SB-12-18-09** Repl Bulletin #: Bulletin Date: **20090501**
Component: **091100 FUEL SYSTEM, OTHER:STORAGE:TANK ASSEMBLY**

BMW VEHICLES: PROGRAM CONTROL UNITS (DME-DMTL DIAGNOSIS). AN INCORRECT TANK LEAKAGE DIAGNOSIS MAY OCCUR DUE TO A SOFTWARE ERROR. THE SERVICE ENGINE SOON (MIL) LAMP MAY BE ILLUMINATED WITH THE DMTL LEAKAGE FAULT STORED, EVEN THOUGH THERE

TSB Report for: 2006 BMW X5

Mfg Bulletin #: **SIB-12-17-09** Repl Bulletin #: **SIB-12-17-09** Bulletin Date: **20110501**
Component: **061000 ENGINE AND ENGINE COOLING:ENGINE**

BMW VEHICLE: WATER HAS ENTERED ELECTRONICS BOX BECAUSE THE LID IS NOT PROPERLY FITTED. ONCE IT IS VERIFIED THAT WATER HAS INDEED ENTERED THE ELECTRONICS BOX, IT WILL BE NECESSARY TO REPLACE BOTH THE LOWER PART OF THE ELECTRONICS BOX AND T

TSB Report for: 2006 BMW X5

Mfg Bulletin #: **SIB-12-17-09** Repl Bulletin #: **SIB-12-17-09** Bulletin Date: **20110501**
Component: **061200 ENGINE AND ENGINE COOLING:ENGINE:DIESEL**

BMW VEHICLE: WATER HAS ENTERED ELECTRONICS BOX BECAUSE THE LID IS NOT PROPERLY FITTED. ONCE IT IS VERIFIED THAT WATER HAS INDEED ENTERED THE ELECTRONICS BOX, IT WILL BE NECESSARY TO REPLACE BOTH THE LOWER PART OF THE ELECTRONICS BOX AND T

TSB Report for: 2006 BMW X5

Mfg Bulletin #: **SIB-12-17-09** Repl Bulletin #: **SIB-12-17-09** Bulletin Date: **20110501**
Component: **111000 ELECTRICAL SYSTEM:BATTERY**

BMW VEHICLE: WATER HAS ENTERED ELECTRONICS BOX BECAUSE THE LID IS NOT PROPERLY FITTED. ONCE IT IS VERIFIED THAT WATER HAS INDEED ENTERED THE ELECTRONICS BOX, IT WILL BE NECESSARY TO REPLACE BOTH THE LOWER PART OF THE ELECTRONICS BOX AND T



Kelly Young
Dirigo Software
PO Box 53
Readfield, ME 04355

ds@dirigosoftware.com
www.dirigosoftware.com

TSB Report for: 2006 BMW X5

Mfg Bulletin #: **SI-B66-09-09** Repl Bulletin #:
Component: **114000 ELECTRICAL SYSTEM:WIRING** Bulletin Date: **20090901**

BMW: FAILURE OF REMOTE CONTROL LOCKING. INTERMITTENTLY OR PERMANENTLY, THE REMOTE CONTROL LOCKING IS INOPERATIVE. BOTH REMOTE KEYS ARE AFFECTED. IN SOME CASES, THE PARKING BRAKE WARNING IS ILLUMINATED IN THE INSTRUMENT CLUSTER AND FUSE

TSB Report for: 2006 BMW X5

Mfg Bulletin #: **SI-B31-01-08** Repl Bulletin #:
Component: **105200 POWER TRAIN:DRIVELINE:CONSTANT VELOCITY JOINT** Bulletin Date: **20090901**

BMW: REPLACEMENT OF FRONT OUTER CV JOINT. COMPLAINTS OF CLICKING OR GRINDING NOISES COMING FROM THE FRONT AXLE AREA WHEN MAKING A TURN. THE FRONT OUTER CONSTANT VELOCITY JOINT BOOT IS SPLIT OPEN AND THE JOINT IS ALREADY DAMAGED.

TSB Report for: 2006 BMW X5

Mfg Bulletin #: **SIB-61-15-09** Repl Bulletin #:
Component: **110000 ELECTRICAL SYSTEM** Bulletin Date: **20100401**

BMW VEHICLES: VARIOUS ELECTRICAL PROBLEMS ARE POSSIBLE ON THE VEHICLE: WARNING LAMPS ILLUMINATED IN THE INSTRUMENT CLUSTER; CHECK CONTROL MESSAGES; SYSTEMS INOPERATIVE; FUSE BLOWN; WIPERS IN DEFAULT MODE (PERMANENTLY ON); AND FAULT CODES F

TSB Report for: 2006 BMW X5

Mfg Bulletin #: **SIB-61-15-09** Repl Bulletin #:
Component: **117000 DIGITAL INSTRUMENT PANEL** Bulletin Date: **20100401**

BMW VEHICLES: VARIOUS ELECTRICAL PROBLEMS ARE POSSIBLE ON THE VEHICLE: WARNING LAMPS ILLUMINATED IN THE INSTRUMENT CLUSTER; CHECK CONTROL MESSAGES; SYSTEMS INOPERATIVE; FUSE BLOWN; WIPERS IN DEFAULT MODE (PERMANENTLY ON); AND FAULT CODES F

TSB Report for: 2006 BMW X5

Mfg Bulletin #: **SIB-34-03-07** Repl Bulletin #:
Component: **110000 ELECTRICAL SYSTEM** Bulletin Date: **20091001**

BMW VEHICLES: DSC WARNING LAMP ILLUMINATED. THE DSC (DYNAMIC STABILITY CONTROL) WARNING LAMP IS ILLUMINATED AND SOME OR ALL OF THE FOLLOWING FAULT CODES ARE STORED: 6E58; 6E04; 53BA; D36F; 55C3; 6ECA; AND THE WIPERS MAY ALSO BE OPERATING



Kelly Young
Dirigo Software
PO Box 53
Readfield, ME 04355

ds@dirigosoftware.com
www.dirigosoftware.com

TSB Report for: 2006 BMW X5

Mfg Bulletin #: **SIB-34-03-07** Repl Bulletin #:
Component: **114000 ELECTRICAL SYSTEM:WIRING** Bulletin Date: **20091001**

BMW VEHICLES: DSC WARNING LAMP ILLUMINATED. THE DSC (DYNAMIC STABILITY CONTROL) WARNING LAMP IS ILLUMINATED AND SOME OR ALL OF THE FOLLOWING FAULT CODES ARE STORED: 6E58; 6E04; 53BA; D36F; 55C3; 6ECA; AND THE WIPERS MAY ALSO BE OPERATING

TSB Report for: 2006 BMW X5

Mfg Bulletin #: **SIB-34-03-07** Repl Bulletin #:
Component: **136000 VISIBILITY:WINDSHIELD WIPER/WASHER** Bulletin Date: **20091001**

BMW VEHICLES: DSC WARNING LAMP ILLUMINATED. THE DSC (DYNAMIC STABILITY CONTROL) WARNING LAMP IS ILLUMINATED AND SOME OR ALL OF THE FOLLOWING FAULT CODES ARE STORED: 6E58; 6E04; 53BA; D36F; 55C3; 6ECA; AND THE WIPERS MAY ALSO BE OPERATING

TSB Report for: 2006 BMW X5

Mfg Bulletin #: **SIB-34-03-07** Repl Bulletin #:
Component: **025000 ELECTRONIC STABILITY CONTROL** Bulletin Date: **20091001**

BMW VEHICLES: DSC WARNING LAMP ILLUMINATED. THE DSC (DYNAMIC STABILITY CONTROL) WARNING LAMP IS ILLUMINATED AND SOME OR ALL OF THE FOLLOWING FAULT CODES ARE STORED: 6E58; 6E04; 53BA; D36F; 55C3; 6ECA; AND THE WIPERS MAY ALSO BE OPERATING

TSB Report for: 2006 BMW X5

Mfg Bulletin #: **SIB-13-02-09** Repl Bulletin #:
Component: **061200 ENGINE AND ENGINE COOLING:ENGINE:DIESEL** Bulletin Date: **20091001**

BMW VEHICLES: DIAGNOSIS FOR LOW PRESSURE FUEL SUPPLY FAULTS. THE SERVICE ENGINE SOON LAMP IS ILLUMINATED (A FUEL PUMP MALFUCTION MESSAGE IS DISPLAYED IN THE CC), AND A COMBINATION OF THE FOLLOWING FAULT CODES MAY BE STORED IN THE DDE CONT

TSB Report for: 2006 BMW X5

Mfg Bulletin #: **SIB-12-26-09** Repl Bulletin #:
Component: **061000 ENGINE AND ENGINE COOLING:ENGINE** Bulletin Date: **20091001**

BMW VEHICLES: EDK THROTTLE POTENTIOMETER FAULTS-DIAGNOSIS. MODELS E60, E63, E64, E65, E66, AND E70. THE SERVICE ENGINE SOON AND DSC/DTC WARNING LAMPS ARE ILLUMINATED. THE ENGINE ENTERS THE POWER REDUCTION (FAIL SAFE) MODE. *PE



Kelly Young
Dirigo Software
PO Box 53
Readfield, ME 04355

ds@dirigosoftware.com
www.dirigosoftware.com

TSB Report for: 2006 BMW X5

Mfg Bulletin #: **SIB-12-26-09** Repl Bulletin #: Bulletin Date: **20091001**
Component: **061200 ENGINE AND ENGINE COOLING:ENGINE:DIESEL**

BMW VEHICLES: EDK THROTTLE POTENTIOMETER FAULTS-DIAGNOSIS. MODELS E60, E63, E64, E65, E66, AND E70. THE SERVICE ENGINE SOON AND DSC/DTC WARNING LAMPS ARE ILLUMINATED. THE ENGINE ENTERS THE POWER REDUCTION (FAIL SAFE) MODE. *PE

TSB Report for: 2006 BMW X5

Mfg Bulletin #: **SIB-11-02-08** Repl Bulletin #: **SI-B11-02-08** Bulletin Date: **20110601**
Component: **061000 ENGINE AND ENGINE COOLING:ENGINE**

BMW VEHICLE: THE SERVICE ENGINE SOON (MIL) LAMP IS ILLUMINATED AND A POWER REDUCTION IS CLEARLY PERCEPTIBLE. THIS SITUATION MAY OCCUR AFTER DRIVING FOR SOME TIME WITH THE ENGINE ALREADY AT FULL OPERATING TEMPERATURE. IF THE IGNITION IS C

TSB Report for: 2006 BMW X5

Mfg Bulletin #: **SIB-11-02-08** Repl Bulletin #: **SI-B11-02-08** Bulletin Date: **20110601**
Component: **061200 ENGINE AND ENGINE COOLING:ENGINE:DIESEL**

BMW VEHICLE: THE SERVICE ENGINE SOON (MIL) LAMP IS ILLUMINATED AND A POWER REDUCTION IS CLEARLY PERCEPTIBLE. THIS SITUATION MAY OCCUR AFTER DRIVING FOR SOME TIME WITH THE ENGINE ALREADY AT FULL OPERATING TEMPERATURE. IF THE IGNITION IS C

TSB Report for: 2006 BMW X5

Mfg Bulletin #: **SIB-12-09-08** Repl Bulletin #: Bulletin Date: **20080201**
Component: **062200 ENGINE AND ENGINE COOLING:COOLING SYSTEM:FAN**

BMW VEHICLE: DRIVEABILITY COMPLAINTS DUE TO COOLING FAN RELAY FAILURE. THE CUSTOMER MAY COMPLAIN OF INTERMITTENT DRIVEABILITY PROBLEMS, DESCRIBED AS-ENGINE IS LACKING POWER WHEN ACCELERATING UPHILL; TRANSMISSION WILL NOT UPSHIFT UNDER HEA

TSB Report for: 2006 BMW X5

Mfg Bulletin #: **SIB-12-09-08** Repl Bulletin #: Bulletin Date: **20080201**
Component: **110000 ELECTRICAL SYSTEM**

BMW VEHICLE: DRIVEABILITY COMPLAINTS DUE TO COOLING FAN RELAY FAILURE. THE CUSTOMER MAY COMPLAIN OF INTERMITTENT DRIVEABILITY PROBLEMS, DESCRIBED AS-ENGINE IS LACKING POWER WHEN ACCELERATING UPHILL; TRANSMISSION WILL NOT UPSHIFT UNDER HEA



Kelly Young
Dirigo Software
PO Box 53
Readfield, ME 04355

ds@dirigosoftware.com
www.dirigosoftware.com

TSB Report for: 2006 BMW X5

Mfg Bulletin #: **SIB-12-23-07** Repl Bulletin #:
Component: **061000 ENGINE AND ENGINE COOLING:ENGINE** Bulletin Date: **20071101**

BMW VEHICLE: FC 2EF4 CHARACTERISTIC MAP THERMOSTAT. COMPLAINTS THAT THE SERVICE ENGINE SOON LAMP IS ILLUMINATED. FAULT CODE 2EF4 CHARACTERISTIC MAP THERMOSTAT IS STORED IN DME FAULT MEMORY. DME SOFTWARE CALIBRATION RELATED TO HIGH HEATIN

TSB Report for: 2006 BMW X5

Mfg Bulletin #: **SIB-12-23-07** Repl Bulletin #:
Component: **353000 EQUIPMENT:ELECTRICAL** Bulletin Date: **20071101**

BMW VEHICLE: FC 2EF4 CHARACTERISTIC MAP THERMOSTAT. COMPLAINTS THAT THE SERVICE ENGINE SOON LAMP IS ILLUMINATED. FAULT CODE 2EF4 CHARACTERISTIC MAP THERMOSTAT IS STORED IN DME FAULT MEMORY. DME SOFTWARE CALIBRATION RELATED TO HIGH HEATIN

TSB Report for: 2006 BMW X5

Mfg Bulletin #: **SIB-12-23-07** Repl Bulletin #:
Component: **118000 ELECTRICAL SYSTEM: SOFTWARE** Bulletin Date: **20071101**

BMW VEHICLE: FC 2EF4 CHARACTERISTIC MAP THERMOSTAT. COMPLAINTS THAT THE SERVICE ENGINE SOON LAMP IS ILLUMINATED. FAULT CODE 2EF4 CHARACTERISTIC MAP THERMOSTAT IS STORED IN DME FAULT MEMORY. DME SOFTWARE CALIBRATION RELATED TO HIGH HEATIN

TSB Report for: 2006 BMW X5

Mfg Bulletin #: **SIB-61-11-07** Repl Bulletin #:
Component: **110000 ELECTRICAL SYSTEM** Bulletin Date: **20071101**

BMW VEHICLE: MISSING CLIP ON POWER CABLE CAUSES VARIOUS ELECTRICAL COMPLAINTS. VEHICLE WILL NOT START. INSTRUMENT CLUSTER OR DISPLAYS ARE FLICKERING. REMOTE CONTROL WILL NOT UNLOCK VEHICLE. VARIOUS CONTROL MODULES CANNOT BE ACCESSED USIN

TSB Report for: 2006 BMW X5

Mfg Bulletin #: **SIB-61-13-07** Repl Bulletin #:
Component: **110000 ELECTRICAL SYSTEM** Bulletin Date: **20071101**

BMW VEHICLE: ELECTRONIC MALFUNCTION CC MESSAGE CAUSED BY SHORTED WIRING. THE ELECTRONIC MALFUNCTION CHECK CONTROL MESSAGE MAY BE DISPLAYED; THE SOUNDS SYSTEM EMITS A STATIC NOISE FROM THE SPEAKERS; THE RFK (REAR VIEW CAMERA) DOES NOT PAN;



Kelly Young
Dirigo Software
PO Box 53
Readfield, ME 04355

ds@dirigosoftware.com
www.dirigosoftware.com

TSB Report for: 2006 BMW X5

Mfg Bulletin #: **SIB-61-13-07** Repl Bulletin #: Bulletin Date: **20071101**
Component: **114000 ELECTRICAL SYSTEM:WIRING**

BMW VEHICLE: ELECTRONIC MALFUNCTION CC MESSAGE CAUSED BY SHORTED WIRING. THE ELECTRONIC MALFUNCTION CHECK CONTROL MESSAGE MAY BE DISPLAYED; THE SOUNDS SYSTEM EMITS A STATIC NOISE FROM THE SPEAKERS; THE RFK (REAR VIEW CAMERA) DOES NOT PAN;

TSB Report for: 2006 BMW X5

Mfg Bulletin #: **SIB-61-13-07** Repl Bulletin #: Bulletin Date: **20071101**
Component: **353000 EQUIPMENT:ELECTRICAL**

BMW VEHICLE: ELECTRONIC MALFUNCTION CC MESSAGE CAUSED BY SHORTED WIRING. THE ELECTRONIC MALFUNCTION CHECK CONTROL MESSAGE MAY BE DISPLAYED; THE SOUNDS SYSTEM EMITS A STATIC NOISE FROM THE SPEAKERS; THE RFK (REAR VIEW CAMERA) DOES NOT PAN;

TSB Report for: 2006 BMW X5

Mfg Bulletin #: **SIB-61-13-07** Repl Bulletin #: Bulletin Date: **20071101**
Component: **118000 ELECTRICAL SYSTEM: SOFTWARE**

BMW VEHICLE: ELECTRONIC MALFUNCTION CC MESSAGE CAUSED BY SHORTED WIRING. THE ELECTRONIC MALFUNCTION CHECK CONTROL MESSAGE MAY BE DISPLAYED; THE SOUNDS SYSTEM EMITS A STATIC NOISE FROM THE SPEAKERS; THE RFK (REAR VIEW CAMERA) DOES NOT PAN;

TSB Report for: 2006 BMW X5

Mfg Bulletin #: **SIB-65-33-07** Repl Bulletin #: Bulletin Date: **20071101**
Component: **140000 AIR BAGS**

BMW VEHICLE: AIRBAG WARNING ILLUMINATED, FC 93D2. THE AIRBAG WARNING LAMP IS ILLUMINATED (PERMANENTLY OR INTERMITTENTLY) AND FAULT CODE 93D2 (PASSENGER AIRBAG OFF LIGHT [POL]) IS STORED IN THE ACSM (ADVANCED CRASH SAFETY MODULE). FAULTY

TSB Report for: 2006 BMW X5

Mfg Bulletin #: **SIB-36-05-07** Repl Bulletin #: Bulletin Date: **20071201**
Component: **199000 TIRES:PRESSURE MONITORING AND REGULATING SYSTEMS**

BMW: TIRE WARNING LIGHT ILLUMINATED DUE TO LOW AMBIENT TEMPERATURE. MODEL E90, E91(3 SERIES);E92, E92 (3 SERIES); E60 (5 SERIES); E60 (M5); E63, E64 (6 SERIES); E63, E64 (M6); E65, E66



Kelly Young
Dirigo Software
PO Box 53
Readfield, ME 04355

ds@dirigosoftware.com
www.dirigosoftware.com

(7 SERIES); E70 (X5); E83 (X3); AND E85, E86 (Z4).

TSB Report for: 2006 BMW X5

Mfg Bulletin #: **SIB-16-02-09** Repl Bulletin #: Bulletin Date: **20091201**

Component: **072100 FUEL SYSTEM, GASOLINE:DELIVERY:FUEL PUMP**

BMW VEHICLES: FUEL LEVEL SENSOR REPAIRS. WHERE IT IS NECESSARY TO REPLACE THE RIGHT OR THE LEFT SIDE FUEL LEVEL SENSOR DUE TO A FAILURE, THE ENTIRE PUMP AND HOUSING OR DELIVERY UNIT (SUCTION JET ASSEMBLY) DO NOT NEED TO BE REPLACED AS WEL

TSB Report for: 2006 BMW X5

Mfg Bulletin #: **SIB-17-03-09** Repl Bulletin #: Bulletin Date: **20101001**

Component: **061120 ENGINE AND ENGINE COOLING:ENGINE:GASOLINE:TURBO-CHARGER**

BMW VEHICLES: N63 TURBOCHARGER AUXILIARY WATER PUMP FAULTS. THE SERVICE ENGINE SOON LAMP IS ILLUMINATED WITH THE FOLLOWING FAULT CODES STORED IN THE DME CONTROL MODULE. TURBOCHARGER COOLANT PUMP, CONTROL LINE, ELECTRIC, 0X1016-LINE INTER

TSB Report for: 2006 BMW X5

Mfg Bulletin #: **SIB-17-03-09** Repl Bulletin #: Bulletin Date: **20101001**

Component: **061320 ENGINE AND ENGINE COOLING:ENGINE:OTHER FUEL TYPES:TURBO-CHARGER**

BMW VEHICLES: N63 TURBOCHARGER AUXILIARY WATER PUMP FAULTS. THE SERVICE ENGINE SOON LAMP IS ILLUMINATED WITH THE FOLLOWING FAULT CODES STORED IN THE DME CONTROL MODULE. TURBOCHARGER COOLANT PUMP, CONTROL LINE, ELECTRIC, 0X1016-LINE INTER

TSB Report for: 2006 BMW X5

Mfg Bulletin #: **SIB-17-03-09** Repl Bulletin #: Bulletin Date: **20101001**

Component: **110000 ELECTRICAL SYSTEM**

BMW VEHICLES: N63 TURBOCHARGER AUXILIARY WATER PUMP FAULTS. THE SERVICE ENGINE SOON LAMP IS ILLUMINATED WITH THE FOLLOWING FAULT CODES STORED IN THE DME CONTROL MODULE. TURBOCHARGER COOLANT PUMP, CONTROL LINE, ELECTRIC, 0X1016-LINE INTER



Kelly Young
Dirigo Software
PO Box 53
Readfield, ME 04355

ds@dirigosoftware.com
www.dirigosoftware.com

TSB Report for: 2006 BMW X5

Mfg Bulletin #: **SIB-17-03-09** Repl Bulletin #:
Bulletin Date: **20101001**
Component: **355200 EQUIPMENT:OTHER:OWNERS/SERVICE/OTHER MANUAL**

BMW VEHICLES: N63 TURBOCHARGER AUXILIARY WATER PUMP FAULTS. THE SERVICE ENGINE SOON LAMP IS ILLUMINATED WITH THE FOLLOWING FAULT CODES STORED IN THE DME CONTROL MODULE. TURBOCHARGER COOLANT PUMP, CONTROL LINE, ELECTRIC, 0X1016-LINE INTER

TSB Report for: 2006 BMW X5

Mfg Bulletin #: **SI-B61-15-09** Repl Bulletin #:
Bulletin Date: **20100401**
Component: **110000 ELECTRICAL SYSTEM**

BMW: VARIOUS ELECTRICAL PROBLEMS. ON THE VEHICLE, VARIOUS ELECTRICAL PROBLEMS ARE POSSIBLE. WARNING LAMPS ILLUMINATED IN THE INSTRUMENT CLUSTER; CHECK CONTROL MESSAGES; SYSTEMS INOPERATIVE; FUSE BLOWN; WIPERS IN DEFAULT MODE (PERMANENTLY O

TSB Report for: 2006 BMW X5

Mfg Bulletin #: **SI-B61-15-09** Repl Bulletin #:
Bulletin Date: **20100401**
Component: **114000 ELECTRICAL SYSTEM:WIRING**

BMW: VARIOUS ELECTRICAL PROBLEMS. ON THE VEHICLE, VARIOUS ELECTRICAL PROBLEMS ARE POSSIBLE. WARNING LAMPS ILLUMINATED IN THE INSTRUMENT CLUSTER; CHECK CONTROL MESSAGES; SYSTEMS INOPERATIVE; FUSE BLOWN; WIPERS IN DEFAULT MODE (PERMANENTLY O

TSB Report for: 2006 BMW X5

Mfg Bulletin #: **SIB-24-01-08** Repl Bulletin #:
Bulletin Date: **20101001**
Component: **103000 POWER TRAIN:AUTOMATIC TRANSMISSION**

BMW VEHICLE: TRANSMISSION WARNING LIGHT IS ILLUMINATED AND THE TRANSMISSION ENTERS FAILSAFE MODE. FAULT CODE 4F81 (RATIO MONITORING, CLUTCH A), IN SOME CASES COMBINED WITH THE SUBSEQUENT FAULTS 507B/507C (PARKING GEAR SENSOR IMPLAUSIBLE S

TSB Report for: 2006 BMW X5

Mfg Bulletin #: **SIB-32-04-07** Repl Bulletin #:
Bulletin Date: **20100601**
Component: **015000 STEERING:HYDRAULIC POWER ASSIST SYSTEM**

BMW: A NEW TECHNICAL PROCESS HAS BEEN CREATED FOR BMW TO IDENTIFY CAUSES OF STEERING COMPLAINTS WITH A WIDE RANGE OF MODELS. *RM



Kelly Young
Dirigo Software
PO Box 53
Readfield, ME 04355

ds@dirigosoftware.com
www.dirigosoftware.com

TSB Report for: 2006 BMW X5

Mfg Bulletin #: **SIB-32-04-07** Repl Bulletin #: Bulletin Date: **20100601**
Component: **016000 STEERING:ELECTRIC POWER ASSIST SYSTEM**

BMW: A NEW TECHNICAL PROCESS HAS BEEN CREATED FOR BMW TO IDENTIFY CAUSES OF STEERING COMPLAINTS WITH A WIDE RANGE OF MODELS. *RM

TSB Report for: 2006 BMW X5

Mfg Bulletin #: **SIB-16-03-10** Repl Bulletin #: Bulletin Date: **20100601**
Component: **061200 ENGINE AND ENGINE COOLING:ENGINE:DIESEL**

BMW: WARNING MESSAGE ON ABOUT LOW DIESEL EXHAUST FUEL LEVEL AND THAT THE ENGINE WILL NOT RESTART WITHIN 999 MILES. THE LIGHT COMES ON A FEW THOUSAND MILES EARLIER THAN A RECOMMENDED OIL CHANGE. *RM

TSB Report for: 2006 BMW X5

Mfg Bulletin #: **SIB-16-03-10** Repl Bulletin #: Bulletin Date: **20100601**
Component: **080000 FUEL SYSTEM, DIESEL**

BMW: WARNING MESSAGE ON ABOUT LOW DIESEL EXHAUST FUEL LEVEL AND THAT THE ENGINE WILL NOT RESTART WITHIN 999 MILES. THE LIGHT COMES ON A FEW THOUSAND MILES EARLIER THAN A RECOMMENDED OIL CHANGE. *RM

TSB Report for: 2006 BMW X5

Mfg Bulletin #: **SIB-13-07-10** Repl Bulletin #: Bulletin Date: **20100601**
Component: **061000 ENGINE AND ENGINE COOLING:ENGINE**

BMW: THERE IS A ROUGH ENGINE IDLE AND "SERVICE ENGINE SOON LIGHT" WHEN DRIVING DOWNHILL IN HIGH ALTITUDES DURING COLD WEATHER. THERE MAY BE SIX DIFFERENT FAULT CODES. *RM

TSB Report for: 2006 BMW X5

Mfg Bulletin #: **SIB-13-02-10** Repl Bulletin #: Bulletin Date: **20100601**
Component: **070000 FUEL SYSTEM, GASOLINE**

BMW: IT IS NOW POSSIBLE TO PERFORM A FUEL QUALITY DETECTION TEST ON VEHICLES WITH AN N54 ENGINE. *RM



Kelly Young
Dirigo Software
PO Box 53
Readfield, ME 04355

ds@dirigosoftware.com
www.dirigosoftware.com

TSB Report for: 2006 BMW X5

Mfg Bulletin #: **SIB-13-02-10** Repl Bulletin #:
Component: **080000 FUEL SYSTEM, DIESEL** Bulletin Date: **20100601**

BMW: IT IS NOW POSSIBLE TO PERFORM A FUEL QUALITY DETECTION TEST ON VEHICLES WITH AN N54 ENGINE. *RM

TSB Report for: 2006 BMW X5

Mfg Bulletin #: **SIB-13-06-10** Repl Bulletin #:
Component: **061000 ENGINE AND ENGINE COOLING:ENGINE** Bulletin Date: **20100601**

BMW: A SERVICE ENGINE SOON LIGHT COMES ON. THE ENGINE WILL ONLY OPERATE TO 1500 RPMS AND LACKS POWER. THERE IS A SOFTWARE APPLICATION ERROR. *RM

TSB Report for: 2006 BMW X5

Mfg Bulletin #: **SIB-13-06-10** Repl Bulletin #:
Component: **118000 ELECTRICAL SYSTEM: SOFTWARE** Bulletin Date: **20100601**

BMW: A SERVICE ENGINE SOON LIGHT COMES ON. THE ENGINE WILL ONLY OPERATE TO 1500 RPMS AND LACKS POWER. THERE IS A SOFTWARE APPLICATION ERROR. *RM

TSB Report for: 2006 BMW X5

Mfg Bulletin #: **SIB-11-08-03** Repl Bulletin #:
Component: **061000 ENGINE AND ENGINE COOLING:ENGINE** Bulletin Date: **20100701**

BMW: SIX DIFFERENT MODELS EQUIPPED WITH THE M54 ENGINE COULD HAVE VALVE COVERS BREAK IN COLD WEATHER AND RUIN THE ENGINE. THIS IS DUE TO MOISTURE ACCUMULATION. *RM

TSB Report for: 2006 BMW X5

Mfg Bulletin #: **SIB-63-02-01** Repl Bulletin #:
Component: **120000 EXTERIOR LIGHTING** Bulletin Date: **20100801**

BMW: PROCEDURE FOR DETERMINING AND REPLACING INCANDESCENT AND HALOGEN LIGHT BULBS UNDER WARRANTY. *RM

TSB Report for: 2006 BMW X5

Mfg Bulletin #: **SIB-61-08-10** Repl Bulletin #:
Component: **110000 ELECTRICAL SYSTEM** Bulletin Date: **20100801**

BMW: ELCTRONICALLY DISCONNECTING THE JUNCTION BOX WITHOUT DISCONNECTING THE



Kelly Young
Dirigo Software
PO Box 53
Readfield, ME 04355

ds@dirigosoftware.com
www.dirigosoftware.com

BATTERY WILL CAUSE DAMAGE TO THE REAR POWER DISTRIBUTION BOX. *RM

TSB Report for: 2006 BMW X5

Mfg Bulletin #: **SIB-61-08-10** Repl Bulletin #:
Bulletin Date: **20100801**
Component: **111000 ELECTRICAL SYSTEM:BATTERY**

BMW: ELCTRONICALLY DISCONNECTING THE JUNCTION BOX WITHOUT DISCONNECTING THE BATTERY WILL CAUSE DAMAGE TO THE REAR POWER DISTRIBUTION BOX. *RM

TSB Report for: 2006 BMW X5

Mfg Bulletin #: **SIB-61-08-10** Repl Bulletin #:
Bulletin Date: **20100801**
Component: **353000 EQUIPMENT:ELECTRICAL**

BMW: ELCTRONICALLY DISCONNECTING THE JUNCTION BOX WITHOUT DISCONNECTING THE BATTERY WILL CAUSE DAMAGE TO THE REAR POWER DISTRIBUTION BOX. *RM

TSB Report for: 2006 BMW X5

Mfg Bulletin #: **SIB-51-26-10** Repl Bulletin #:
Bulletin Date: **20100801**
Component: **114000 ELECTRICAL SYSTEM:WIRING**

BMW: MODEL E70 EQUIPPED WITH AN AUTOMATIC TAILGATE. THE REAR TAILGATE MAY NOT OPERATE IN EITHER DIRECTION DUE TO WIRING DAMAGE. *RM

TSB Report for: 2006 BMW X5

Mfg Bulletin #: **SIB-51-26-10** Repl Bulletin #:
Bulletin Date: **20100801**
Component: **162500 STRUCTURE:BODY:TAILGATE**

BMW: MODEL E70 EQUIPPED WITH AN AUTOMATIC TAILGATE. THE REAR TAILGATE MAY NOT OPERATE IN EITHER DIRECTION DUE TO WIRING DAMAGE. *RM

TSB Report for: 2006 BMW X5

Mfg Bulletin #: **SIB-65-36-09** Repl Bulletin #:
Bulletin Date: **20100901**
Component: **114000 ELECTRICAL SYSTEM:WIRING**

BMW: THE AIRBAG WARNING LAMP IS ILLUMINATED DUE TO A SOFTWARE ERROR. *RM



Kelly Young
Dirigo Software
PO Box 53
Readfield, ME 04355

ds@dirigosoftware.com
www.dirigosoftware.com

TSB Report for: 2006 BMW X5

Mfg Bulletin #: **SIB-65-36-09** Repl Bulletin #: Bulletin Date: **20100901**
Component: **140000 AIR BAGS**

BMW: THE AIRBAG WARNING LAMP IS ILLUMINATED DUE TO A SOFTWARE ERROR. *RM

TSB Report for: 2006 BMW X5

Mfg Bulletin #: **SIB-65-36-09** Repl Bulletin #: Bulletin Date: **20100901**
Component: **118000 ELECTRICAL SYSTEM: SOFTWARE**

BMW: THE AIRBAG WARNING LAMP IS ILLUMINATED DUE TO A SOFTWARE ERROR. *RM

TSB Report for: 2006 BMW X5

Mfg Bulletin #: **SIB-52-08-09** Repl Bulletin #: Bulletin Date: **20101001**
Component: **221600 SEATS:FRONT ASSEMBLY:POWER ADJUST**

BMW: THERE ARE NOISES WHEN ADJUSTING THE FRONT DRIVER OR PASSENGER SEATES. *RM

TSB Report for: 2006 BMW X5

Mfg Bulletin #: **SIB-24-01-10** Repl Bulletin #: **SI-B24-01-10** Bulletin Date: **20110201**
Component: **103000 POWER TRAIN:AUTOMATIC TRANSMISSION**

BMW: THE EMERGENCY PARK RELEASE CABLE HAS BEEN REMOVED IN THESE MODELS AND THERE IS A PROCEDURE TO DISENGAGE THE PARK LOCK. 2011 E70/E71. UPDATED ON 06/08/2011. *KB UPDATED ON 06/21/2011. *RM

TSB Report for: 2006 BMW X5

Mfg Bulletin #: **SIB-12-01-11** Repl Bulletin #: **SIB-12-01-11** Bulletin Date: **20110901**
Component: **091100 FUEL SYSTEM, OTHER:STORAGE:TANK ASSEMBLY**

BMW: THE SERVICE ENGINE SOON LIGHT IS ON WHILE DRIVING. THIS IS A PROGRAMMING ISSUE. *RM
UPDATED 1/4/12. *PE

TSB Report for: 2006 BMW X5

Mfg Bulletin #: **SIB-12-01-11** Repl Bulletin #: **SIB-12-01-11** Bulletin Date: **20110901**
Component: **118000 ELECTRICAL SYSTEM: SOFTWARE**

BMW: THE SERVICE ENGINE SOON LIGHT IS ON WHILE DRIVING. THIS IS A PROGRAMMING ISSUE. *RM
UPDATED 1/4/12. *PE



Kelly Young
Dirigo Software
PO Box 53
Readfield, ME 04355

ds@dirigosoftware.com
www.dirigosoftware.com

TSB Report for: 2006 BMW X5

Mfg Bulletin #: **SIB-63-10-09** Repl Bulletin #: Bulletin Date: **20110301**
Component: **125000 EXTERIOR LIGHTING: BRAKE LIGHTS**

BMW: THE BRAKE LIGHT FAILS AND THE BULB HOLDER IS DEFORMED DUE TO HIGH TEMPERATURES AND THE COMPOSITION OF THE HOLDER. *RM

TSB Report for: 2006 BMW X5

Mfg Bulletin #: **SIB-12-15-11** Repl Bulletin #: Bulletin Date: **20110701**
Component: **061000 ENGINE AND ENGINE COOLING: ENGINE**

BMW: THE SERVICE ENGINE SOON LIGHT IS ON. THERE ARE TROUBLE CODES STORED FOR THE CRANKSHAFT SENSOR. NO DRIVEABILITY ISSUES. *RM

TSB Report for: 2006 BMW X5

Mfg Bulletin #: **SIB-63-04-10** Repl Bulletin #: Bulletin Date: **20100301**
Component: **120000 EXTERIOR LIGHTING**

BMW: THE BULB HAS FAILED ON THE DAYTIME RUNNING LAMP. *PE

TSB Report for: 2006 BMW X5

Mfg Bulletin #: **SIB-63-04-10** Repl Bulletin #: Bulletin Date: **20100301**
Component: **121000 EXTERIOR LIGHTING: HEADLIGHTS**

BMW: THE BULB HAS FAILED ON THE DAYTIME RUNNING LAMP. *PE

TSB Report for: 2006 BMW X5

Mfg Bulletin #: **SIB-61-06-11** Repl Bulletin #: Bulletin Date: **20110901**
Component: **118000 ELECTRICAL SYSTEM: SOFTWARE**

BMW: ON CERTAIN VEHICLES, THE JBE (JUNCTION BOX ELECTRONICS) MODULE FAILS PROGRAMMING DURING A SOFTWARE UPDATE OF THE VEHICLE. *PE

TSB Report for: 2006 BMW X5

Mfg Bulletin #: **SIB-63-05-11** Repl Bulletin #: Bulletin Date: **20110901**
Component: **121000 EXTERIOR LIGHTING: HEADLIGHTS**

BMW: ON CERTAIN VEHICLES, THE XENON HEADLAMP OFTEN HAVE NO TROUBLE FOUND WHEN RETURNED AND TESTED THRU WARRANTY PARTS SYSTEM. THE ROOT CAUSE IS NOT POSSIBLE TO BE IDENTIFY. *PE



Kelly Young
Dirigo Software
PO Box 53
Readfield, ME 04355

ds@dirigosoftware.com
www.dirigosoftware.com

***** END OF REPORT *****