



SI B 63 11 06
Lights

October 2006
Technical Service

This Service Information bulletin supersedes S.M. B63 204 04 **dated March 2004**

SUBJECT

Rear Brake Light/Parking Light is Out

MODEL

E53 (X5) vehicles up to 09/03

SITUATION

Rear brake light/parking light is out. Bulb-out warning shows in Check Control.

CAUSE

Poor connection at bulb holder.

PROCEDURE

Install improved rear lamp. P/N as follows:

63 21 8 409 009	Left (amber T/S)
63 21 8 409 010	Right (amber T/S)
63 21 8 386 809	Left (white T/S)
63 21 8 386 810	Right (white T/S)