



IMPORTANT SAFETY RECALL

This notice applies to your vehicle, 5UXFB53546LV28834 [T15 11244]

January 2014

Recall Campaign No. 13V-564: Front Passenger Air Bag Seat Occupancy Sensor Mat

Dear BMW Owner/Lessee:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

BMW AG has decided that a defect, which relates to motor vehicle safety, exists in certain model year 2006-07 BMW 3 Series Sedans and Sports Wagons, 5 Series Sedans and Sports Wagons and 7 Series, and also model year 2006 X5 SAVs. Our records indicate that you are the owner of a potentially affected vehicle.

IMPORTANT NOTICE

Please note that at the present time, we do not yet have sufficient parts to conduct this Recall; however, we will notify you as soon as parts become available. At that time, you should make an appointment with your authorized BMW center in order to have this Recall performed on your vehicle.

DESCRIPTION OF PROBLEM

This Recall involves the front passenger air bag seat occupancy sensor mat. Over time, due to the frequency of front passenger seat usage, the sensor can become damaged. If this were to occur, deactivation of the front passenger air bag could result, increasing the risk of injury in the event of a crash. If the front passenger air bag became deactivated, the air bag warning lamp on the instrument cluster and the front "passenger air bag off" lamp in the overhead console are illuminated at the same time.

DESCRIPTION OF REPAIR

The air bag seat occupancy sensor mat will be repaired so that forces applied to the seat cushion do not damage the sensor.

The actual repair will require approximately three hours; however, additional time may be required depending on the BMW center's schedule. This work will be performed free of charge by your authorized BMW center.

PRECAUTIONS FOR YOUR SAFETY

1. Please make sure all vehicle occupants always wear their safety belts.
2. If the air bag warning lamp on the instrument cluster and the front "passenger air bag off" lamp in the overhead console are illuminated at the same time, the vehicle may be experiencing this condition.

Company

BMW of North America, LLC

BMW Group Company

Mailing address

PO Box 1227
Westwood, NJ
07675-1227

Telephone

(800) 525-7417

Fax

(201) 930-8362

E-mail

customer.relations@
bmwusa.com

Website

bmwusa.com

