



SUBJECT

Ultrasonic Passenger Compartment Motion Detector Triggers False Alarm

MODEL

E70 (X5)

E71 (X6)

Vehicles produced up to March 30, 2009

SITUATION

The ultrasonic passenger compartment motion detector (USIS), which is fully integrated in the Roof Control Panel (FZD), triggers a false alarm. No faults are stored.

CAUSE

Ultrasonic passenger compartment motion detector

CORRECTION

Program the vehicle using ISTA/P 2.33.0 or later.

Note that ISTA/P will automatically reprogram and code all programmable control modules that do not have the latest software.

For information on programming and coding with ISTA/P, refer to Centernet / Aftersales Portal / Service / Workshop Technology / Vehicle Programming.

WARRANTY INFORMATION

Covered under the terms of the BMW New Vehicle Limited Warranty or the BMW Certified Pre-Owned program.

Defect Code: **65 75 24 14 00**

Labor Operation:	Labor Allowance:	Description:
Refer to KSD	Refer to KSD	Program control modules

In cases where ISTA requires the replacement of control modules or additional programming because certain control modules failed to program correctly, print out the Measures Plan and Final Report and attach these reports to the RO in the vehicle file. This additional work should be claimed under the defect code listed in this bulletin, using the labor operation and labor allowance from the KSD.