

**Defect Code:****NEW 27 10 00 77 MP****E53 and E83 only****Labor Operation:****Labor Allowance:****Description:**

00 11 570

Refer to KSD

Replace transfer case fluid

**All remaining xDrive models****Labor Operation:****Labor Allowance:****Description:**

27 99 000\*

2 FRU

Replace transfer case fluid (WT)

[ Copyright © 2010 BMW of North America, LLC ]