SI B 65 09 08
Audio, Navigation, Monitors, Alarms, SRS

March 2009
Technical Service

This Service Information bulletin supersedes SI B65 09 08 **dated November 2008.**

NEW designates changes to this revision

SUBJECT
Anti-theft Alarm System Triggers a False Alarm

MODEL
E70 (X5)

E71 (X6)

SITUATION
The anti-theft alarm system (DWA) triggers a false alarm. Fault code 9D47 (Alarm memory: siren disconnected) and/or 9D45 (Alarm: bus connected to positive or overvoltage) is stored in the SINE_65 (Siren with tilt sensor) control module. The situation occurs very intermittently.

CAUSE
Software error

CORRECTION
NEW This problem has been integrated into ISTA diagnostics. Follow diagnostics and the relevant test plan, using the latest ISTA version.

WARRANTY INFORMATION
Information only