

16858	Ralum Pipe	1
17766	Expansion Tank Hose	1
15549	Radiator Hose	1
21850	Radiator Hose	1
19114	Water Hose	1
21854	Cooling Hose	1
21651	Cooling Hose	1
19115	Water Hose	1
372	Rivat	1
18661	Heater Hose	1
21652	Heater Hose	1
21653	Heater Hose	1
21297	Heater Hose	1
8937	Antifreeze (Phosphate Fr	1.5

Water Pump and Thermostat Service:

Line Total 545.

Replace water pump with new unit (metal impeller).
 Install new coolant and bleed system.
 Install new thermostat.
 Replace auxiliary water pump.

11443	Water Pump	1
11016	Water Pump Gasket	1
2567	Thermostat	1
12420	Coolant Temp Sensor	1
22316	Auxiliary Water Pump	1

Valve Cover Gasket Service:

Line Total 740.

Install new valve cover gaskets
 Install new vanos solenoid seals

15094	Valve Cover Gasket Set	1
15095	Valve Cover Gasket Set	1
12785	WC Bolt Grommet	5
16214	Valve Cover Seal Washer	16
17661	Solenoid Gasket	2

Fuel Filter Service

Line Total 117.

Install new fuel filter

18632	Fuel Filter	1
-------	-------------	---

Check

Estimated Hours: 0.00

Oil separator failed?

Blowing oil on top of oil filter

MANOMETER = 6

All vacuum hoses and oil delivery hoses replace

Check Valve cover gaskets

— LEAKY

Check for burning smell (possible coolant residue on belly pan)

Leaky

Valley pan? seep

Coolant flush

Possible water pump thermostat and coolant hose

Oil change and filter just done.

Check for brake shutter at highway speed through

Mic rotors

MIN 34mm MEAS 35.7

Estimated Hours: 0.00

Check lower control arm bushings — NOT too old —

hood shocks weak

COOLANT seepage in valley pan leak

FT SEAL ON TRANSFORMER CASE LEAK

Check
 Oil seperator failed?
 Blowing oil on top of oil filter
 All vacuum hoses and oil delivery hoses replace
 Check Valve cover gaskets
 Check for burning smell (possible coolant residue on belly pan)
 Valley pan?
 Coolant flush
 Possible water pump thermostat and coolant hose
 Oil change and filter just done.

Check for brake shutter at highway speed through
 Mic rotors
 Check lower control arm bushings
 Remove and install rotors
 Turn Rotors

Line Total 125

Coolant Pipe Service:

Replace intake manifold gaskets.
 Install front and rear intake manifold gaskets.
 Install new bottom intake gaskets.
 Re-seal valley cover gasket.
 Install new Water pump, Thermostat, and o rings for water tubes.
 Re-seal vanos solenoids

Line Total 1424.

2458	Valve Cover Cap	1
2569	O-Ring	2
2570	O-Ring	2
2579	Gasket	2
2593	Intake Manifold Gasket	4
249	Intake Cover Gasket	1
250	Intake Manifold Gasket	1
2600	Spacer, Intake Manifold	10
14519	Intake Manifold Cover	1
18074	Sealing Sleeve	1

Replace All Hoses

Install new upper and lower radiator hoses
 Install new hose from reservoir to radiator
 Replace all heater hoses

Line Total 906.81