

ERROR MEMORY REPORT

Date: 12/20/20 16:11:37
ECU: DDE40KW0
JobStatus: OKAY
Variant: DDE40KW0

RESULT: 6 errors in error memory !

13573 glow device

Error frequency : 6
Logistic counter: 40

Error occurred 1. times at:

Engine speed	724.28 1/min
Coolant temperature	12.22 Grad C
Einspritzmenge	28.67 mm ³
RPC rail pressure	337.35 bar
Fehler aufgetreten bei	270400.00 km

Error occurred 2. times at:

Engine speed	749.25 1/min
Coolant temperature	10.86 Grad C
Einspritzmenge	15.36 mm ³
RPC rail pressure	307.23 bar
Fehler aufgetreten bei	270480.00 km

Error occurred 3. times at:

Engine speed	749.25 1/min
Coolant temperature	10.86 Grad C
Einspritzmenge	15.36 mm ³
RPC rail pressure	307.23 bar
Fehler aufgetreten bei	270480.00 km

Error present
Sporadic error
Glow system - Glow-plug or Glow-plug relay

Errorcode: 35 05 28 06 DC 80 1D 4E 38 38 69 A0 80 1E 4C 1E
33 69 A8 80 1E 4C 1E 33 69

5651 Rough idle speed controller

Error frequency : 8
Logistic counter: 40

Error occurred 1. times at:

Engine speed	674.33 1/min
Coolant temperature	19.05 Grad C
Einspritzmenge	12.29 mm ³
Supply voltage	13.89 V
Fehler aufgetreten bei	270400.00 km

Error occurred 2. times at:

Engine speed	674.33 1/min
Coolant temperature	17.68 Grad C
Einspritzmenge	12.80 mm ³
Supply voltage	13.77 V

Fehler aufgetreten bei 270480.00 km

Error occured 3. times at:

Engine speed 674.33 1/min
Coolant temperature 17.68 Grad C
Einspritzmenge 12.80 mm³
Supply voltage 13.77 V
Fehler aufgetreten bei 270480.00 km

Error not present
Sporadic error
correction amount to big

Errorcode: 16 13 28 08 D8 01 1B 58 18 78 69 A0 01 1B 56 19
77 69 A8 01 1B 56 19 77 69

4496 Rail-pressure plausibility

Error frequency : 1
Logistic counter: 38

Engine speed 3121.88 1/min
fuel pre-supply pressure 3.76 bar
Einspritzmenge 63.49 mm³
RPC rail pressure 1048.19 bar
Fehler aufgetreten bei 270480.00 km

Error not present
Control deviation over engine speed too great

Errorcode: 11 90 26 01 10 20 7D EB 7C AE 69 A8 00 00 00 00
00 00 00 00 00 00 00 00 00

13589 air condition output

Error frequency : 1
Logistic counter: 40

Engine speed 0.00 1/min
Coolant temperature 9.49 Grad C
Einspritzmenge 34.82 mm³
RPC rail pressure 60.24 bar
Fehler aufgetreten bei 270480.00 km

Error not present
Open circuit or short circuit to B-

Errorcode: 35 15 28 01 10 08 00 4A 44 0A 69 A8 00 00 00 00
00 00 00 00 00 00 00 00 00

1152 Electric fan

Error frequency : 1
Logistic counter: 40

Engine speed 0.00 1/min
Coolant temperature 9.49 Grad C
Supply voltage 10.30 V
duty factor 4.73 %
Fehler aufgetreten bei 0.00 km

Error not present
Controll circuit or short circuit to positive B-

Errorcode: 04 80 28 01 10 08 00 4A 59 0C 00 00 00 00 00
00 00 00 00 00 00 00 00 00

7685 cruise control operating unit

Error frequency : 1
Logistic counter: 40

Engine speed	0.00 1/min
Coolant temperature	10.18 Grad C
Einspritzmenge	34.31 mm ³
RPC rail pressure	96.39 bar
Fehler aufgetreten bei	0.00 km

Error not present
no signal from the multi-function steering wheel

Errorcode: 1E 05 28 01 10 20 00 4B 43 10 00 00 00 00 00
00 00 00 00 00 00 00 00 00
