



SUBJECT

The Engine Oil Level Is Displayed as Overfilled

MODEL

E70 X5 3.0 with the N52K engine produced from 9/08 up to 3/09

SITUATION

When the engine oil level is checked in the Central Information Display (CID), it is shown as overfilled, even though the engine does contain the correct fill quantity of oil (6.5 liters / 6.9 quarts).

Also affected are those E70 with N52K produced prior to 9/08, which have been programmed using Progman version V30.0 through V32.1 or ISTA/P 2.32.1. These vehicles can be identified as having a current vehicle integration level of E070-08-09-500-530.

CAUSE

DME software calibration error

CORRECTION

Program the vehicle using ISTA/P 2.33.0 or later.

Note that ISTA/P will automatically reprogram and code all programmable control modules that do not have the latest software.

For information on programming and coding with ISTA/P, refer to CenterNet / Aftersales Portal / Service / Workshop Technology / Vehicle Programming.

WARRANTY INFORMATION

Covered under the terms of the BMW New Vehicle Limited Warranty or the Certified Pre Owned program.

Defect Code: **12 61 00 14 00**

Labor Operation:	Labor Allowance:	Description:
61 00 801*	Refer to KSD	Programming / encoding control unit(s) without CAS
61 00 802*	Refer to KSD	Programming / encoding control unit(s) with CAS

*Main Work - use this labor operation number when this is the only repair being performed, or if this is the main repair when performed along with other repairs at the same time. If this is not the main repair, refer to KSD for the associated (+) labor operation code.