

CHASSIS: E70 (E70)

Nrcd-No.: 093821dz

FG 5UXFF08579L1951051

Error

⚠ Error in CABD! Look at CABLERR and ERROR.LOG!

COAPI-2021: Datatransmission to ECU disturbed IFH-0010:
Datatransmission to controlunit disturbed AHM_E65

COAPI-2021: Datatransmission to ECU disturbed
CODIERINDEX_LESEN

COAPI-2021: Datatransmission to ECU disturbed
CODIERINDEX_LESEN: A_E65

COAPI-2041: Wrong ECU coding index A_E65: CODIERINDEX = 11h
AHM_E60.C04: CODIERINDEX = 04

COAPI-2041: Wrong ECU coding index CODIERDATEN_LESEN

OK

F1

Change SG/SGET

F2

Change Job

F3

Execute Job

F4

Reading ECU

F5

Basic functions

F6

Back