

Identification	Vehicle test	Activities	Service plan		
Information search	Guided troubleshooting	Programming / encoding	Service function	Workshop / Operating fluids	Measuring devices
Fault memory	Fault pattern	Input fault code			

Code	Description	Mileage r... ▲	Class
6E58	DSC: F-CAN DSC sensor		
9414	No message from DSC control unit, ACSM receiver / MRS5, DSC transmitter	28032	
D372	DSC: F-CAN No message (DSC sensor, 165)	28032	
CE91	Message (sensor cluster) from F-CAN faulty, receiver AFS, transmitter DSC s...	28040	
6E04	DSC: DSC sensor: variant	28048	
E59A	No message (yaw rate), receiver FRM, transmitter DSC	28112	
55C3	VTG: AWD limp-home control activated. No DSC specified nominal torque.	28136	
D712	Message error (speed, 0x1A0), receiver EHC	28136	
2DD9	No message, receiver DME, transmitter ARS	28136	

Number of fault memories: 9

No. fault patterns: 0

Fault memory filter: Default

Display
fault code

Delete fault
memory

Filter fault
memory

Delete filter

Display all

Calculate
test plan