

transmission.

The manufacturing period of the affected vehicles (February 2003 until November 2003) applies for the purposes of reimbursement.

**Reimbursement:**

Material and labour costs incurred can be claimed through the usual warranty channels subject to current warranty terms.

<b>Defect code</b>	<b>24 00 90 63 00</b> This defect code is not contained in the official Defect Code Catalogue but has been included in the system, thus enabling warranty claims to be processed. Within the framework of a visit to the workshop - Install exchange transmission:
Job number	00 54 897
Labour	52 FRUs 325iA/330iA US 74 FRUs 325iXA/330iXA 69 FRUs X5 3.0iA 56 FRUs X3 3.0iA In case of order without additional repair operations - Install exchange transmission:
Job number	00 54 230
Labour	53 FRUs 325iA/330iA 75 FRUs 325iXA/330iXA 71 FRUs X5 3.0iA 57 FRUs X3 3.0iA
Warranty type	1
Warranty stage	1 (within vehicle warranty) 2 (outside vehicle warranty)

Only one of the above job numbers may be submitted for reimbursement.

Reimbursement is limited to **36 months/100 000 km** and only possible until **November 2006**.